

TST 2022 VIRTUAL
19th ANNUAL BIG
EVENT

MOST WITH A TWIST

- DIAGNOSING GM MOST NETWORKS



WORLD PAC 
Wholesale Distributor of Original Equipment Automotive Parts

Course Objectives

- New Model Viewing
- Case Study
- Infotainment Technology Overview

Course Objectives

- Infotainment Technology Overview
- Center Stack Designs
- MOST Exercises

New Model Viewing



2017 Buick Cascada





Case Study#1

Chime is not Loud
Enough





Chime Malfunction

The screenshot displays a web browser window with the URL <https://gsi.ext.gm.com/gsi/showDoc.do?docSyskey=3818498&cellId=164174&pubObjSyskey=8853974&from=sm&pubCellSyskey=6211717&deliveryEffectiveDate=Sep+1%2C+2017>. The page is titled "Service Information" and "2014 Chevrolet Cruze | Cruze N America Service Manual 5565221 | Document ID: 3818498".

Chime Malfunction

Diagnostic Instructions

- Perform the [Diagnostic System Check - Vehicle](#) prior to using this diagnostic procedure.
- Review [Strategy Based Diagnosis](#) for an overview of the diagnostic approach.
- [Diagnostic Procedure Instructions](#) provides an overview of each diagnostic category.

Circuit/System Description

The radio generates the audible warnings. The instrument cluster, the body control module (BCM), the inflatable restraint sensing and diagnostic module (SDM) or the object alarm module request audible warnings via serial data.

Reference Information

Schematic Reference

[Audible Warnings Schematics](#)

Connector End View Reference

[Component Connector End Views](#)

Description and Operation

[Audible Warnings Description and Operation](#)


Electrical Information Reference

- [Circuit Testing](#)
- [Connector Repairs](#)

© 2017 General Motors. All rights reserved.

12:56 PM
9/18/2017

Amplifier



A photograph showing a person's hand holding a circular car speaker. The speaker is black with a silver-colored center cap. It is being held next to the internal wiring of a car door, which is partially disassembled. The wiring includes a blue cable and a black cable with a multi-colored connector. The background shows the interior of the car door and a battery unit.

There is no Chime Module

A bad speaker
was found

Infotainment System Modules

Human Machine Interface

- The Human Machine Interface (HMI) module is responsible for the following: **Video for the Infotainment display, Bluetooth ®, USB, memory card reader, and speech recognition functions.** The HMI module communicates with the Info Display Module via the LIN bus for control information, touch communications and dimming level.



Amplifier

- The purpose of the amplifier is to increase the power of a voltage or current signal. The output signal of an amplifier may consist of the same frequencies as the input signal or it may consist of only a portion of the frequencies as in the case of a subwoofer or midrange speaker. The audio amplifier amplifies the signal and sends it to the appropriate speakers.



Instrument Cluster

- The instrument cluster is a multifunction module that provides the vehicle operator with information such as vehicle speed and engine RPM using analog gauges. Oil pressure, battery voltage, fuel level, and coolant temperature can also be displayed using an interactive LCD display.



Radio

-



Radio/HVAC Controls


- The Radio and HVAC controls are communicated on Low Speed GMLAN. The **information display** communicates via a LIN Buss to the Radio and HVAC controls. The HVAC controls will communicate via LIN Buss to the HVAC control module.



Infotainment Technology Overview

GM Infotainment

Infotainment: An information and entertainment infrastructure




Connected Radios

- Connected Radios
 - Beamed In
 - Built In
 - Brought In
- Beamed In Features (Signals Received Over the Air)
 - Sirius
 - Satellite Navigation
 - Onstar Services

Connected Radios

- Built In(Uses Components inside the vehicle)
 - Speech Recognition
 - Noise Cancellation
 - Touch Screen
- Brought In(Interface with personal electronic devices)
 - Cellular Phones
 - MP3 Players
 - Tablet PC's

Center Stack Designs



2010 Buick
LaCrosse

Monochrome Display



2016 Chev Silverado



2016 Chev Silverado



2016 Chev Equinox



2016 Chev Equinox



2016 Chev Equinox



2017 Chev Camaro



2017 Chev Camaro



2017 Chev Spark



2017 Chev Spark



2017 Chev Spark



2017 Chev Spark



2017 Chev Volt



2017 Chev Volt



2017 Chev Volt



2017 Chev Volt



2016 Chev Cruze



2017 Chev Cruze



2017 GMC Truck



2017 GMC Truck




2015 Buick Lacrosse




2015 Buick Lacrosse




RPO Codes and SPI Labels



2010 Buick
LaCrosse



High Speed GMLAN (without F46)





The SPI Label is located in the trunk area of the vehicle

SERVICE PARTS IDENTIFICATION

DO NOT REMOVE

1G4GB5EG7AF124014

NKFR02

4GB69

AEF	AEQ	AE2	AFB	AG1	AJC	AL0	AP9	AQQ	AXG	AXJ
AY0	A23	A51	A6C	A69	A70	A90	BAH	BTT		
B7Y	B85	C1U	C59	C68	DA5	DBU	DCP	DH6		
D31	D70	EAK	EA1	EA2	EF7	E3E	FA1	FBM		
FX3	GAR	GNA	GNC	JJ2	J61	J71	KB7	KD4		
KRH	K34	LF1	LHD	MDE	MH2	NCG	NR0	NT7		
PYX	P77	QFV	R6F	R9N	TSP	TT4	TU2	T61		
T83	UAG	UDC	UE1	UH1	UJM	UMN	UTJ	UYE	U2K	U65
U77	U80	VQ2	VRG	VRH	VRK	VRL	VRM	VRN	VRR	VX7
VY7	V33	V8D	WDP	W1Y	W2X	XL7	01C	1AD	1SZ	4AH
6AB	7AB	8AD	9AD							

BC/CC

U 501Q

01C

There is not a rear differential clutch module on this vehicle.


There is not an RPO code F46 that is noted on the SPI Label

Networks

LIN

Monochrome Display


- This 2010 Buick Lacrosse uses what is called a "monochrome Display"
- The word "monochrome" literally means "one color." Therefore, a monochrome image only includes one color.



How it all works

- The radio/HVAC controls is a separate component from the radio. The radio/HVAC controls contain the radio control knobs and buttons for all audio functions.
- The radio/HVAC controls operate radio functions through serial data messages. The radio/HVAC controls communicate to the info display module through LIN serial data. The info display module communicates to radio through CGI serial data.

Local Interconnect Network (LIN)



- Infotainment systems with a monochrome display use a LIN Bus to connect the faceplate to the display
- In most infotainment systems, the radio sets DTCs in the event of a fault with the LIN Bus or a fault with the device that is connected

2017 Buick Lacrosse



2017 Buick Lacrosse




How it all works

- When the operator rotates a radio control knob to change radio stations or increase the volume a message is sent to the radio over serial data. After receiving the message the radio will make the adjustment. Messages communicated between the radio and the radio/HVAC controls and info display include the following:
 - Button presses/knob rotations
 - Info display module dimming
 - Radio/HVAC controls back-lighting
 - Graphics and text information

How it all works


- HVAC data for controls and status indicators is communicated between the radio/HVAC controls and the HVAC control module with a separate LIN serial data circuit. HVAC status screen information from the HVAC control module is transmitted to the radio on the GMLAN serial data circuit. The radio then displays the desired screen information on the info display using the video data circuits.

Local Interconnect Network (LIN)



- Infotainment systems with a monochrome display use a LIN Bus to connect the faceplate to the display
- In most infotainment systems, the radio sets DTCs in the event of a fault with the LIN Bus or a fault with the device that is connected

Expanded View






Local Interconnect Network Bus 1,2,3,4



K9 Body Control Module X2

Pin 21 of the X2
Connector (Gray Wire)




K9 Body Control Module X2


18	—	—	Not Used
19	0.35 PK/BK	780	Driver Door Lock Switch Lock Signal
20	—	—	Not Used
21	0.35 GY	6135	Linear Interconnect Network Bus 4
22	0.35 D-GN	5060	Low Speed GMLAN Serial Data



**Pin 21 LIN Bus 4
(without UYS)**







LIN

Case Study

Case Study

Vehicle: 2015 Cadillac Escalade 6.2L L86
4WD

vin: 1GYS4HKJ8FR215500

104,140 miles

Concern: The Info Display Module (P17) is blank. There is audio.

Performed diagnostics on Thursday, October 7, 2021.

Courtesy of John Thornton





Case Study

Background Info:

- the radio audio works with the steering wheel controls
- there is a Media Disc Player (A33) in the bottom of the stack
- the shop has replaced the Touch Screen with one from Amazon



REPLACEMENT CUE® TOUCH SCREEN DISPLAY

Fits Cadillac CUE® Equipped Vehicles



FITS

2013-2017 Cadillac ATS®
2014-2017 Cadillac CTS®
2014-2016 Cadillac ELR®
2015-2017 Cadillac Escalade®
2015-2017 Cadillac Escalade ESV®
2013-2016 Cadillac SRX®
2013-2017 Cadillac XTS®

AA Ignition is a registered trademark of GWA Auto Parts Inc. Other trademarks are registered trademarks of auto manufacturers

**shop installed replacement Touch Screen from
Amazon in the Info Display Module (P17)**



REPLACEMENT CUE® TOUCH SCREEN DISPLAY

® Fits Cadillac CUE® Equipped Vehicles

Premium gel-free
screen display
for maximum heat
resistance

OEM chip design requires
no programming

Factory mounting points



AA Ignition is a registered trademark of GWA Auto Parts Inc. Other trademarks are registered trademarks of auto manufacturers

**shop installed replacement Touch Screen from
Amazon in the Info Display Module (P17)**





1GYS4HKJ8FR215500



MDI 2 SN#: 88729380

Click to disconnect



DASHBOARD

GDS2

GDS2

Vehicle Selection

Device:

MDI 2: 88729380

☐ Navigate Without Device

Press Enter To Continue.

Make

Cadillac

Model

Escalade ESV

Model Year

2015

VIN:

1GYS4HKJ8FR215500

Clear Vehicle Selection

Copy VIN

1G1PC5SHXC7130670	2012	Chevrolet	Cruze	Oct 5, 2021 11:08:05 AM
NOVIN211005104425	2012	Chevrolet	Cruze	Oct 5, 2021 10:58:35 AM
2GNALDEK3C6232964	2012	Chevrolet	Equinox	Oct 2, 2021 12:44:21 PM
1G1ZB5ST2GF176103	2016	Chevrolet	Malibu	Aug 20, 2021 1:44:30 PM
1G1JA5SH9E4127176	2014	Chevrolet	Sonic	Aug 9, 2021 11:28:18 AM

Back



Home



Vehicle Menu



Enter

Techline Connect

GM Techline Connect- Standalone mode
Version: 1.12.0.4 Production

1GYS4HKJ8FR215500

MDI 2 SN#: 88729380
Click to disconnect

DASHBOARD GDS2

GDS2

Vehicle DTC Information

☐ Continuously Update Diagnostic Trouble Codes

Create Report

Add Bookmark

DTC Summary

Status	Control Module Name	Control Module Status	DTC Count	DLC Pin
✓	Instrument Cluster	No DTCs Stored	0	1
+	Radio/HVAC Controls	Read DTCs only supported under Module Diagno...	1	1
✗	Active Safety Control Module	No Communication		6,14
✗	Video Processing Control Module	No Communication		1
⚠	Radio	DTCs Stored	1	1
✓	Amplifier	No DTCs Stored	0	1
✗	Media Disc Player	No Communication		1
⚠	Human Machine Interface Control Module	DTCs Stored	2	6,14
✓	Telematics Communication Interface Control Module	No DTCs Stored	0	1
⚠	HVAC Control Module	DTCs Stored	1	1

Clear DTCs

Refresh

Details

Reset Ethernet

Back

Home

Vehicle Menu

Enter

GDS 2 v.22.2.03302 GM Global v2021.8.1 VIN: 1GYS4HKJ8FR215500 2015,Cadillac,Escalade ESV,Vehicle Diagnostics MDI 2: 88729380 14.6 V

module scan

Case Study

Module Scan:

- the Media Disc Player (A33) shows no communication
- this is normal
- the Media Disc Player is only on the MOST Bus

Media Disc Player (A33)

A33 Media Disc Player X1 (TG5)

Pin	Size	Color	Circuit	Function	Terminal Type ID	Option
1	0.35	WH/VT	3999	MOST Control	I	—
2	—	—	—	Not Occupied	—	—
3	0.5	WH/L-GN	3997	MOST Serial Data (-)	I	—
4	0.5	GY/VT	3998	MOST Serial Data (+)	I	—
5	0.5	WH/L-GN	3997	MOST Serial Data (-)	I	—
6	0.5	GY/VT	3998	MOST Serial Data (+)	I	—
7	—	—	—	Not Occupied	—	—
8	0.75	BK	2550	Ground	I	—
9	0.35	GY	4016	Remote Media Eject Signal	II	Z75
10	0.75	RD/VT	340	Battery Positive Voltage	I	—

A33 (rpo T65) does not communicate on any bus except MOST

Techline Connect

Techline Connect- Standalone mode
Version: 1.12.0.4 Production

1GYS4HKJ8FR215500

MDI 2 SN#: 88729380
Click to disconnect

DASHBOARD GDS2

GDS2

Vehicle DTC Information [Create Report](#) [Add Bookmark](#)

DTC Display

Control Module	Type	DTC	Sym...	Description	Symptom Description	Status
Radio		U15E1	00	Lost Communication with Device on LIN Bus	- - -	Current
Human Machine Interface Control Module		B124B	04	Universal Serial Bus (USB) Circuit 1	Open	Current
Human Machine Interface Control Module		U15F0	00	Lost Communication with Device on LIN Bus	- - -	Current
HVAC Control Module		U1510	00	Lost Communication with Device on LIN Bus	- - -	Current

Category	Decoded Value
DTC Current Status	Current
DTC History Status	History

[Clear DTCs](#) [Refresh](#) [Summary](#)

[Back](#) [Home](#) [Vehicle Menu](#) [Enter](#)

GDS 2 v.22.2.03302 GM Global v2021.8.1 VIN: 1GYS4HKJ8FR215500 2015,Cadillac,Escalade ESV,Vehicle Diagnostics MDI 2: 88729380 14.6 V

3 of the 4 codes relate to the LIN Bus

Techline Connect

Techline Connect- Standalone mode
Version: 1.12.0.4 Production

1GYS4HKJ8FR215500

MDI 2 SN#: 88729380
Click to disconnect

DASHBOARD GDS2

GDS2

DTC Display Create Report Add Bookmark

Status	Control Module Name	Control Module Status	DTC Co...	DLC Pin
	Radio	Requesting DTCs	1	1

Control Module	Type	DTC	Symptom Byte	Description	Sympt...	Status
Radio		U15E1	00	Lost Communication with Device on LIN Bus	---	Current

Category	Decoded Value
DTC Current Status	Current
DTC History Status	History

Clear DTCs Refresh

Back Home Vehicle Menu Enter

GDS 2 v.22.2.03302 GM Global v2021.8.1 VIN: 1GYS4HKJ8FR215500 2015,Cadillac,Escalade ESV,Module Diagnostics,Radio,Dagnostic Trouble Codes (DTC) MDI 2: 88729380 14.7 V

the Radio (A11) sets a U15E1

Techline Connect

Techline Connect- Standalone mode
Version: 1.12.0.4 Production

1GYS4HKJ8FR215500

MDI 2 SN#: 88729380
Click to disconnect

DASHBOARD GDS2

GDS2

DTC Display Create Report Add Bookmark

Status	Control Module Name	Control Module Status	DTC Co...	DLC Pin
	Human Machine Interface Control Module	DTCs Stored	2	6,14

Control Module	Type	DTC	Symptom Byte	Description	Sympt...	Status
Human Machine Interface Con...		B124B	04	Universal Serial Bus (USB) Circuit 1	Open	Current
Human Machine Interface Con...		U15F0	00	Lost Communication with Device on LIN Bus	- - -	Current

Category	Decoded Value
DTC Current Status	Current
DTC History Status	History

Clear DTCs Refresh

Back Home Vehicle Menu Enter

GDS 2 v.22.2.03302 GM Global v2021.8.1 VIN: 1GYS4HKJ8FR215500 2015,Cadillac,Escalade ESV,Module Diagnostics,Human Machine Interface Control Module,Dagnostic Trouble ... MDI 2: 88729380 14.7 V

the HMI (K74) sets a U15F0

Techline Connect

GM Techline Connect- Standalone mode
Version: 1.12.0.4 Production

1GYS4HKJ8FR215500

MDI 2 SN#: 88729380
Click to disconnect

DASHBOARD GDS2

GDS2

DTC Display

Create Report Add Bookmark

Status	Control Module Name	Control Module Status	DTC Co...	DLC Pin
	HVAC Control Module	DTCs Stored	1	1

Control Module	Type	DTC	Symptom Byte	Description	Sympt...	Status
HVAC Control Module		U1510	00	Lost Communication with Device on LIN Bus	- - -	Current

Category	Decoded Value
DTC Current Status	Current
DTC History Status	History

Clear DTCs Refresh

Back Home Vehicle Menu Enter

GDS 2 v.22.2.03302 GM Global v2021.8.1 VIN: 1GYS4HKJ8FR215500 2015,Cadillac,Escalade ESV,Module Diagnostics,HVAC Control Module,Dagnostic Trouble Codes (DTC) MDI 2: 88729380 14.7 V

the HVAC (K33) sets a U1510

Techline Connect

GM Techline Connect- Standalone mode
Version: 1.12.0.4 Production

1GYS4HKJ8FR215500

MDI 2 SN#: 88729380
Click to disconnect

DASHBOARD GDS2

GDS2

DTC Display

Create Report Add Bookmark

Status	Control Module Name	Control Module Status	DTC Co...	DLC Pin
	Media Disc Player	No Communication		1

Control Module	Type	DTC	Symptom Byte	Description	Sympt...	Status
----------------	------	-----	--------------	-------------	----------	--------

Category	Decoded Value
----------	---------------

Clear DTCs Refresh

Back Home Vehicle Menu Enter

GDS 2 v.22.2.03302 GM Global v2021.8.1 VIN: 1GYS4HKJ8FR215500 2015,Cadillac,Escalade ESV,Module Diagnostics,Media Disc Player,Dagnostic Trouble Codes (DTC) MDI 2: 88729380 14.7 V

this is normal



1GYS4HKJ8FR215500

MDI 2 SN#: 88729380
Click to disconnect

DASHBOARD

GDS2

GDS2

- [P16] Instrument Cluster
- [A20] Radio/HVAC Controls
- [K124] Active Safety Control Module
- [K157] Video Processing Control Module
- [A11] Radio
- [T3] Amplifier
- [A33] Media Disc Player
- [K74] Human Machine Interface Control Module
- [K73] Telematics Communication Interface Control Module
- [K33] HVAC Control Module
- [K391] Liftgate Control Module

Selected Vehicle

Property	Value	Value Source
Model Year	2015	VIN
Make	Cadillac	VIN
Model	Escalade ...	VIN

Selected Vehicle Configuration

Property	Value	Value Source
Chassis ...	Active Gril...	Contro...
Engine I...	6.2L (L86)	User

Navigation Path

Module Diagnostics

Back

Home

Vehicle Menu

Enter

Techline Connect

GM Techline Connect- Standalone mode
Version: 1.12.0.4 Production

1GYS4HKJ8FR215500

MDI 2 SN#: 88729380
Click to disconnect

DASHBOARD GDS2

GDS2

DTC Display

Create Report Add Bookmark

Status	Control Module Name	Control Module Status	DTC Co...	DLC Pin
	Radio/HVAC Controls	No Communication		1

Control Module	Type	DTC	Symptom Byte	Description	Sympt...	Status
----------------	------	-----	--------------	-------------	----------	--------

Category	Decoded Value
----------	---------------

Clear DTCs Refresh

Back Home Vehicle Menu Enter

GDS 2 v.22.2.03302 GM Global v2021.8.1 VIN: 1GYS4HKJ8FR215500 2015,Cadillac,Escalade ESV,Module Diagnostics,Radio/HVAC Controls,Diagnostic Trouble Codes (DTC) MDI 2: 88729380 14.7 V

this is not normal

Case Study

MOST Bus:

- there does not seem to be an issue with the **MOST Bus**
- there are no **MOST Bus** related codes

Techline Connect

Techline Connect- Standalone mode
Version: 1.12.0.4 Production

1GYS4HKJ8FR215500

MDI 2 SN#: 88729380
Click to disconnect

DASHBOARD GDS2

GDS2

Data Display Create Report Add Bookmark

Diagnostic Data Display Graphical Data Display Line Graph DTC Display


Radio Data

Parameter Name	Value	Unit	Control Module
Surrogate MOST Master Node Upstream Position	None		Radio
Number of MOST Communication Breaks	3		Radio
Last Working MOST ID of Node 1	Radio		Radio
Last Working MOST ID of Node 2	CD		Radio
Last Working MOST ID of Node 3	Human Machine In...		Radio
Last Working MOST ID of Node 4	Amplifier		Radio
Last Working MOST ID of Node 5	Instrument Cluster		Radio
Last Working MOST ID of Node 6	UNRECOGNIZED S...		Radio
Last Working MOST ID of Node 7	UNRECOGNIZED S...		Radio

Back Home Vehicle Menu Enter

GDS 2 v.22.2.03302 GM Global v2021.8.1 VIN: 1GYS4HKJ8FR215500 2015,Cadillac,Escalade ESV,Module Diagnostics,Radio MDI 2: 88729380 14.7 V

there are 5 modules on the MOST Bus





DASHBOARD

GDS2

GDS2

MOST Bus Diagnostic Starting Point

Add Bookmark

Incomplete or Missing Data for Test

Either the vehicle configuration does not match the data provided by the Radio, or the Radio is not providing a Surrogate MOST Master Node. This procedure will not provide any valuable diagnostic information. Refer to Service Information and the scan tool Data Display for additional diagnostic information.

Continue

Back

Home

Vehicle Menu

Enter

Case Study

The Issues:

- no display
- no com to Radio/HVAC Controls A20
- Radio A11 sets a LIN bus code
- HMI K74 sets a LIN bus code
- HVAC K33 sets a LIN bus code

SERVICE PARTS IDENTIFICATION

DO NOT REMOVE

1GYS4HKJ8FR215500

RSRXXRH

6K15906



AG2	AKJ	AKK	AKO	AKX	AL0	AN3	ARL	AS8	ATH	ATN
AU3	AXP	AYQ	A31	A45	BTM	BTV	BVE	B30	B58	B85
CE1	CF5	CJ4	C25	C49	C6H	DCP	DD8	DL3	D07	EF7
FE9	FH0	GBA	GU6	G80	H2X	I06	I15	JD9	JF4	KA6
KB6	KC4	KI4	KNP	KW7	K34	K47	L86	MAH	MYC	NKC
NP0	NT7	N30	N38	QST	Q7L	RC4	R00	RUF	R9N	SAF
SFE	SLM	TC2	TG5	TQ5	UDV	UD5	UEU	UE1	UFG	UFI
UG1	UJM	UKC	UK3	UMN	UQH	UTJ	UTR	UTT	UTU	UTV
UVC	UVD	UV6	U2M	U77	VH9	VK3	VRK	VRS	VT7	V54
V8D	WMF	XL7	YM8	Y65	ZY1	Z75	Z82	Z95	1SB	1SZ
4AA	6XF	7XF	8X2	9X2						

BC/CC

U 8555

H2X

SERVICE PARTS IDENTIFICATION

DO NOT REMOVE

1GYS4HKJ8FR215500

RSRXRH

6K15906

AG2	AKJ	AKK	AKO	AKX	AL0	AN3	ARL	A38	ATH
AU3	AXP	AYQ	A31	A45	BTM	BTV	BVE	B30	B58
CE1	CF5	CJ4	C25	C49	C6H	DCP	DD8	DL3	D07
FE9	FH0	GBA	GU6	G80	H2X	I06	I15	JD9	JF
KB6	KC4	KI4	KNP	KW7	K34	K47	L86	MAH	MY
NP0	NT7	N30	N38	QST	Q7L	RC4	R00	RUF	R
SFE	SLM	TC2	TG5	TQ5	UDV	UD5	UEU	UE1	U
UG1	UJM	UKC	UK3	UMN	UQH	UTJ	UTR	UTT	
UVC	UVD	UV6	U2M	U77	VH9	VK3	VRK	VRS	
V8D	WMF	XL7	YM8	Y65	ZY1	Z75	Z82	Z95	
4AA	6XF	7XF	8X2	9X2					

BC/CC

U 8555

H2X


Case Study


Critical RPO's:

➤ IO6

➤ TG5

➤ Z75





Case Study


Info Display Module P17:


- P17 contains the Display P7
- P17 contains the Radio/HVAC Controls A20
- there is no communication to A20
- Low Speed LAN is circuit 5060 found at X1, pin #12


Case Study

Info Display Module P17:

- P17 is a slave module to 3 separate LIN Buses







P17 Info Display Module X1 (Z75)

Pin	Size	Color	Circuit	Function
1 - 5	—	—	—	Not Occupied
6	0.5	L-GN/WH	7527	Local Interconnect Network Serial Data Bus 5
7	0.5	L-GN/D-BU	7532	Local Interconnect Network Serial Data Bus 10
8	0.35	L-GN/YE	7531	Local Interconnect Network Serial Data Bus 9
9	0.5	RD/GY	2840	Battery Positive Voltage
10 - 11	—	—	—	Not Occupied
12	0.5	L-GN	5060	Low Speed GMLAN Serial Data
13 - 15	—	—	—	Not Occupied
16	0.35	BK	2550	Ground

Case Study

Info Display Module P17 Testing:


- **check feed and ground**
- **check Low Speed LAN**
- **check all 3 LIN Buses**

P17 Info Display Module X1 (Z75)


Pin	Size	Color	Circuit	Function
1 - 5	—	—	—	Not Occupied
6	0.5	L-GN/WH	7527	Local Interconnect Network Serial Data Bus 5
7	0.5	L-GN/D-BU	7532	Local Interconnect Network Serial Data Bus 10
8	0.35	L-GN/YE	7531	Local Interconnect Network Serial Data Bus 9
9	0.5	RD/GY	2840	Battery Positive Voltage
10 - 11	—	—	—	Not Occupied
12	0.5	L-GN	5060	Low Speed GMLAN Serial Data
13 - 15	—	—	—	Not Occupied
16	0.35	BK	2550	Ground









P17 Info Display Module X1 (Z75)






blue channel across battery feed and ground



Low Speed LAN




Low Speed LAN with P17 X1 connector disconnected


Case Study

Info Display Module P17 Testing:

- **P17 has good feed and ground**
- **P17 has a good Low Speed LAN**



X1 pin #6 LIN Bus from HMI




X1 pin #6 LIN Bus to HMI: X1 connector disconnected


Case Study

Info Display Module P17 Testing:

- **X1 pin #6 LIN Bus from HMI is good**
- **P17 is a slave on this LIN Bus**
- **P17 is also a slave module on the other 2 LIN Buses**



X1 pin #7 LIN Bus from Radio



X1 pin #8 LIN Bus from HVAC


Case Study

Diagnosis:

- the Info Display Module P17 has failed
- it has good feed and ground, but can't communicate on Low Speed LAN or any of its 3 LIN Buses

Low Speed GMLAN


Radio and HVAC Module




The radio and the HVAC Module can be communicated on low speed GMLAN

Information Display Module

Note: Wake Up Signal is located on Pin 4 of the P17 Connector (Light Green Wire)





Frontal View of Center Stack






P17 Information Display Module X1






Wake-Up Circuit -2010 Buick Lacrosse

- A “wake-up” circuit is used to turn on a monochrome display or radio faceplate depending on the vehicle’s infotainment system




Integrated Center Stack Wake Up Signal (without UYS)






Reset Circuit – 2010 Buick Lacrosse



- If the radio recognizes that a device is not responding to the signal on the wake-up circuit, the radio briefly pulls the reset circuit low to try to “reboot” the controls.
- Only works if communication is established, then lost.

Integrated Center Stack Reset Signal (without UYS)





Bare Wire


Bare Wire






CAN Graphical Interface

CAN Graphical Interface




- High speed serial data interface with a two-wire design
 - Connects the information display or the faceplate

CAN Graphical Interface



- Used to connect the radio to a display (monochrome display) or radio controls (full color display)



MOST

MOST

Normal Operation

MOST

- Infotainment: an information and entertainment infrastructure.
- MOST is used to connect infotainment system components in many vehicles.
- GM first used MOST in the MY2013
- 2013 Cadillac XTS, ATS, and SRX

MOST

- 100 times faster than GMLAN
- Streams audio and video
- 16 turns of wire per foot
- Radio is the gateway of the bus
- Communication occurs in one direction around a ring configuration

Point of Discussion


- Splice Packs
- Infotainment Component Codes
- MOST Diagnostic Tool

Splice Packs????









Splice Packs

Infotainment Component Codes

Control Module References

Service Information
2017 Chevrolet Impala | Impala Service Manual 9410864 | Driver Information and Entertainment | Cellular, Entertainment, and Navigation | Diagnostic Information and Procedures | Document ID: 4451483

Control Module References

Reference Information

- [Data Link References](#)
- [Diagnostic System Check - Vehicle](#)
- [Diagnostic Trouble Code \(DTC\) List - Vehicle](#)
- [Symptoms - Vehicle](#)

Control Module References

Code	Control Module/Scan Tool Information	Schematic	Repair Instruction	Programming and Setup
A11	Radio Scan Tool Information	Radio/Navigation System Schematics	Radio Replacement	Radio Programming and Setup
A20	Radio/HVAC Controls	Radio/Navigation System Schematics	Radio Control Assembly Replacement	Radio Control Programming and Setup
A33	Media Disc Player	Radio/Navigation System Schematics	Disc Player Replacement	Media Disc Player Programming and Setup
B94L/R	Side Object Sensing Alert Module Scan Tool Information	Object Detection Schematics	Side Object Sensing Alert Module Replacement	Side Object Sensor Programming and Setup
K9	Body Control Module Scan Tool Information	Body Control System Schematics	Body Control Module Replacement	Body Control Module Programming and Setup

© 2017 General Motors. All rights reserved.

Data Link References

Service Information
2017 Chevrolet Impala | Impala Service Manual 9410864 | Driver Information and Entertainment | Cellular, Entertainment, and Navigation | Diagnostic Information and Procedures | Document ID: 4542981

Data Link References

This table identifies which serial data link that a particular device uses for in-vehicle data transmission. Some devices may use more than one data link to communicate. Some devices may have multiple communication circuits passing through them without actively communicating on that data link. This table is used to assist in correcting a communication malfunction. Not all devices listed will be applicable to all vehicles. Refer to the schematics to determine which devices apply. For the description and operation of these serial data communication circuits, refer to [Data Link Communications Description and Operation](#).

Reference Information
Schematic Reference: [Data Communication Schematics](#)

Code	Device	Data Link Type	Diagnostic Procedure
A11	Radio	- Gateway Isolated Low Speed GMLAN - MOST Bus - Local Interconnect Network (LIN)	DTC U007D DTC U0028 DTC U1500-U15FF
A13	Rear Audio Control Module	Gateway Isolated Low Speed GMLAN	DTC U007D
A26	HVAC Controls	- Low Speed GMLAN - Local Interconnect Network (LIN)	Scan Tool Does Not Communicate with Low Speed GMLAN Device DTC U1500-U15FF
A22	Media Disc Player	MOST Bus	DTC U0028

© 2017 General Motors. All rights reserved.

MOST Diagnostic Tool




2017 Chev
Malibu

EL-51578 MOST Bus Diagnostic Tool Kit



- The EL-51578 MOST Bus Diagnostic Test Kit will assist in the diagnosis of a MOST ring break, DTC U0028

EL-51578 MOST Bus Diagnostic Tool Kit





- The MOST Bus Diagnostic Tool Kit consists of several test connectors
- Each connector matches a connector on a MOST device
- Connectors jump the MOST bus wires to bypass MOST devices




2017 Chev Malibu

Human
Interface
Module






Amplifier



MOST
Normal Operation
(3 Steps)

Media Oriented Systems Transport – **Step 1** Normal Operation

- MOST is 100 times Faster than GMLAN
- Modules are connected together with a two-wire twisted pair in a ring format.
- The radio is the MOST master
 - Data will travel in one direction through the MOST protocol.
 - Data direction is indicated by the arrow placed in the pictorial.



Normal Operation

2018 Chev Malibu


2018 Chev Malibu



2018 Chev Malibu




2018 Chev Malibu



2018 Chev Malibu

HMI and Radio Locations



2018 Chev Malibu

GDS 2

Vehicle Selection

Device: MDI 2: 88746860 ☐ Navigate Without Device

Press Enter To Continue.

Make	Chevrolet
Model	Malibu
Model Year	2018

VIN: 1G1ZD5T6JF122692

VIN	Model Year	Make	Model	Timestamp
1G1105S38HU195416	2017	Chevrolet	Impala	Sep 3, 2017 2:35:44 PM

GDS 2 v.17.1.15100 GM Global v2017.8.0 MDI 2: 88746860 12.3 V

3:45 PM 9/18/2017

2018 Chev Malibu

The screenshot displays the GDS 2 software interface. On the left, a list of vehicle modules is shown, with 'Radio' selected. On the right, the 'Selected Vehicle' and 'Selected Vehicle Configuration' tables are visible. The status bar at the bottom shows the VIN 1G1ZD5ST6JF122692 and the vehicle name 2018,Chevrolet,Malibu.

Selected Vehicle

Property	Value	Value Source
Model Year	2018	VIN
Make	Chevrolet	VIN
Model	Malibu	VIN

Selected Vehicle Configuration

Property	Value	
Engine Identifier	1.5L (LFV)	..
Transmission Ty...	Automatic	..
Stop/Start Syste...	Stop/Start System (KL9)	..
Seat Memory Co...	Not Equipped	..
Telematics Com...	10	..
Marketing Region	Other	..

Navigation Path

Module Diagnostics

Status Bar: GDS 2 v.17.1.15100 GM Global v2017.8.0 VIN: 1G1ZD5ST6JF122692 2018,Chevrolet,Malibu MDI 2: 88746860 12.3 V 3:54 PM 9/18/2017

2018 Chev Malibu

GDS 2

Data Display

Diagnostic Data Display Graphical Data Display Line Graph DTC Display

Radio Data

Parameter Name Value Unit Control Module


Alternative Frequency Status	Inactive		Radio
m Position	None		Radio
ts	169		Radio
	Radio		Radio
	Radio		Radio
	Radio		Radio
Human Machine Interface Control Module	Radio		Radio
Instrument Cluster	Radio		Radio
UNRECOGNIZED STATE	UNRECOGNIZED STATE		Radio

Back Contact Us Home Vehicle Menu Enter

GDS 2 v.17.1.15100 GM Global v2017.8.0 VIN: 1G1ZD5ST6JF122692 2018,Chevrolet,Malibu MDI 2: 88746860 12.4 V

3:57 PM 9/18/2017

2018 Chev Malibu



GDS 2

Active AM/FM Antenna

Satellite Antenna

MOST Communication Enable Circuit

MOST Bus Diagnostic Starting Point

Selected Vehicle

Property	Value	Value Source
Model Year	2018	VIN
Make	Chevrolet	VIN
Model	Malibu	VIN

Selected Vehicle Configuration

Property	Value
Engine Iden...	1.5L (LFV)
Transmissio...	Automatic
Stop/Start S...	Stop/Start System (KL9)
Seat Memor...	Not Equipped
Telematics ...	10
Headlamp T...	Halogen (T4A TT4)
Marketing R...	Other

Navigation Path


Module Diagnostics

Radio

Back Contact Us Home Vehicle Menu Enter

GDS 2 v.17.1.15100 GM Global v2017.8.0 VIN: 1G1ZD5T6JF122692 2018,Chevrolet,Malibu MDI 2: 88746860 12.4 V 4:25 PM 9/18/2017

2018 Chev Malibu



MOST

Normal Operation-Cont'd

2017 Chev Impala




Center Stack



Info Display Face is
Blank (Failure)


MOST Schematics



MOST Questions


- Does each module generate its own 12 volt signal?
- Answer: It appears the radio alone provides the rest voltage (12 volts) and also pulls it low to promote communication.
- The schematics imply that there are pull up circuits in each module.
- Further investigation is needed to confirm this.

MOST Schematics – A11 Radio




Rest state of 12 volts is provided by Radio/Radio also pulls the rest state of 12 volts low to awaken modules

J206




MOST Schematics – K74 HMI and A33 Media Disc Player



A instrument panel harness will provide a path for the 12 volts to be routed to each module. (J206)

Instrument Cluster and T3 Amplifier




The 12 volt rest state is called “MOST Control” on GM schematics. (This is the “Wake Up Call”)


Media Oriented Systems Transport – **Step 2**

Normal Operation

- The rest state for these modules is 12 volts, the MOST Master will pull this value low for **100ms to activate these modules**.
- Once **activated**, the modules will initiate communication over the MOST Protocol in a CCW direction. (Downstream)
- An **IPC harness** is used to distribute the 12 volts to each module




Instrument Cluster and T3 Amplifier



The 12 volt rest state is called “MOST Control” on GM schematics. (This is the “Wake Up Call”)

Amplifier Connector X4




Brown Colored Connector

Amplifier Location



Amplifier Location






Amplifier Location




Media Oriented Systems Transport – **Step 3** Normal Operation


- Once activated, each module sends segments of data in a CCW motion, this is a continuous loop
- Data will flow from one module to the next.
- Data flow will always begin at the radio, each module is considered downstream (CCW) from the previous one before it.





MOST Question


- Do the modules respond in some way to the wake up call to verify its receipt of this message?
- Answer: Yes, they send out segments of data that verify communication is taking place.



















MOST Abnormal Operation


Media Oriented Systems Transport – **Step 1**

Abnormal Operation

- If any of the modules do not respond to the 100ms wake-up call, the radio will resend the signal up to 3 times with a 2 second delay between each one of the attempts.
- If an abnormal response is received after three attempts, the radio sets a DTC for the MOST Bus








Media Oriented Systems Transport – **Step 2** Abnormal Operation

- Once a DTC is set, diagnostics upstream (CW) begins and a 300ms low signal is sent over the MOST protocol.
- All modules will try to respond by transmitting data over the MOST protocol.
- The responding module prior to the break upstream of the radio becomes the Surrogate MOST master
- The entire process takes up to 10 seconds to complete.




Case Study #1

2017 Chev Impala




Center Stack



Info Display Face is
Blank (Failure)

What caused this
failure to occur?

MOST Schematics



MOST Scan Data

Scan Data

The screenshot displays the GDS software interface. At the top, the browser address bar shows the file path: C:\Users\User\AppData\Local\Temp\GDS 2\Data Displ. The main window features the GDS logo and the title "Global Diagnostic System 2". Below this, the section "Read Vehicle Wide DTC and ID Information" is active. Under the "Overview" tab, a table provides key information: Vehicle Identification Number (VIN) 1G1105S38HU195416 and Report Creation Date 2017-09-03 13:42:21 CDT. The "Vehicle Configuration Property" section follows, listing various vehicle attributes and their values. At the bottom, the "System Information Property" section is partially visible. The Windows taskbar at the bottom shows the time as 1:54 PM on 9/3/2017.

GDS
Global Diagnostic System 2

Read Vehicle Wide DTC and ID Information

Overview

Vehicle Identification Number (VIN)	1G1105S38HU195416
Report Creation Date	2017-09-03 13:42:21 CDT

Vehicle Configuration Property

Make	Chevrolet
Model	Impala
Model Year	2017
Headlamp Type	Halogen (T4A TT4)
Steering Column Lock Control (ULS/N06)	Not Equipped
Chassis Control Module Version	0301
Marketing Region	Other
Power Steering Type	Belt Driven Electric Power Steering (NJ2)
Telematics Communication Interface Control Module Version	10
Power Steering Control Module Version	0A09
Seat Memory Control Module Version	Not Equipped
HVAC Control Module Type	Auto Control Dual Zone (CJ2)
Engine Identifier	3.6L (LFX)

System Information Property

Scan Data

System Information Property

VCI Serial Number	MDI 2: 88746860
Vehicle Session Creation Date	2017-09-01 14:22:41
Test Start Time	2017-09-03 13:42:21 CDT

Engine Control Module

Identification Information	Value
Vehicle Identification Number (VIN)	1G1105S38HU195416
End Model Part Number	12666070
Base Model Part Number	12631787
Software Module 1 Identifier	12666071
Software Module 2 Identifier	12670413
Software Module 3 Identifier	12670410
Software Module 4 Identifier	12670419
Software Module 5 Identifier	12670407
Software Module 6 Identifier	12678627

No DTCs Stored

Chassis Control Module

Identification Information	Value
Vehicle Identification Number (VIN)	1G1105S38HU195416
Subscriber ID	PCDHSTN#50
Date Programmed	20170222
Diagnostic Data Identifier	0301
Base Model Part Number	84097001
End Model Part Number	84082495
Software Module 1 Identifier	84082492

Scan Data

Read Vehicle Wide DTC and...

Identification Information	Value
Vehicle Identification Number (VIN)	1G1105S38HU195416
Subscriber ID	PCDHSTN#50
Date Programmed	20170222
Diagnostic Data Identifier	0301
Base Model Part Number	84097001
End Model Part Number	84082495
Software Module 1 Identifier	84082492
Software Module 2 Identifier	22974906
Software Module 3 Identifier	84018128
Software Module 4 Identifier	
Software Module 5 Identifier	
System Code	03

No DTCs Stored

Transmission Control Module

Identification Information	Value
Vehicle Identification Number (VIN)	1G1105S38HU195416
Date Programmed	20170222
Diagnostic Data Identifier	0
End Model Part Number	24276632
Base Model Part Number	24239358
Software Module 1 Identifier	24276633
Software Module 1 Identifier Alpha Code	BA
Software Module 2 Identifier	24280488
Software Module 2 Identifier Alpha Code	AB
Software Module 3 Identifier	24280493
Software Module 3 Identifier Alpha Code	AB
Software Module 4 Identifier	24280495

1:55 PM 9/3/2017

Scan Data U0028 stored in Radio

Radio

Identification Information	Value
End Model Part Number	84102334
Boot Software Part Number	287454020
Software Module 1 Identifier	84022441
Software Module 2 Identifier	23407028
Software Module 3 Identifier	23272759
Software Module 4 Identifier	23367700
Software Module 5 Identifier	22970004
Software Module 6 Identifier	23132160
Software Module 7 Identifier	23229005
Software Module 8 Identifier	23387888
Software Module 9 Identifier	23428027
Software Module 10 Identifier	22969969
Software Module 11 Identifier	22969968
Digital Radio Receiver ID	1Y0XR34U
DVD Region Code	
DVD Region Code Changes Remaining	
Manufacturer Enable Counter	0
VIN Digits 2-17	G1105S38HU195416
Diagnostic Data Identifier	B02
Manufacturer's Traceability Number	N216335NNB288741

DTC Display	Symptom Byte	DTC Description	Symptom Description	Status	
U0028	00	MOST Bus	---	Current	
				DTC Current Status	Current
				DTC History Status	History

Amplifier

1:56 PM 9/3/2017

Scan Data

Media Disc Player

No Communication

Human Machine Interface Control Module

Identification Information	Value
End Model Part Number	84131941
Boot Software Part Number	84131951
Calibration Part Number 1	84131951
Calibration Part Number 2	84234141
Calibration Part Number 3	23458625
Calibration Part Number 4	84080584
Calibration Part Number 5	23458590
Calibration Part Number 6	23458627
Calibration Part Number 7	84144186
Calibration Part Number 8	84225887
Calibration Part Number 9	23458601
Calibration Part Number 10	23463834
Calibration Part Number 11	23463841
Calibration Part Number 12	0
Calibration Part Number 13	23199293
Calibration Part Number 14	23199237
Calibration Part Number 15	23199236
Calibration Part Number 16	0
Calibration Part Number 17	10000002
Calibration Part Number 18	84029222
Calibration Part Number 19	84029214
Control Module Production Date	14.02.2017
Software Freeze Date	19.09.2016
VIN Digits 2-17	G1105S38HU195416

Scan Data-U0029 stored in HMI Module

The screenshot displays a diagnostic tool window with the following data:

Calibration Part Number	Value
Calibration Part Number 9	23450001
Calibration Part Number 10	23463834
Calibration Part Number 11	23463841
Calibration Part Number 12	0
Calibration Part Number 13	23199293
Calibration Part Number 14	23199237
Calibration Part Number 15	23199236
Calibration Part Number 16	0
Calibration Part Number 17	10000002
Calibration Part Number 18	84029222
Calibration Part Number 19	84029214
Control Module Production Date	14.02.2017
Software Freeze Date	19.09.2016
VIN Digits 2-17	G1105S38HU195416
Diagnostic Data Identifier	708
Manufacturer Enable Counter	0
Hardware Version	PP 2.00

DTC Display	Symptom Byte	DTC Description	Symptom Description	Status
U0029	00	MOST Bus Performance	---	Current DTC Current Status: Current DTC History Status: History

Telematics Communication Interface Control Module

Identification Information	Value
Bluetooth	Disabled
End Model Part Number	84136296
Firmware Over-the-Air Version	0851
GSM Network Code	28672
Manufacturer	LG
Manufacturer's Traceability Number	4447005000005953

Scan Data

GDS 2

Vehicle DTC Information

Create Report Add Bookmark

DTC Summary

Status	Control Module Name	Control Module Status	DTC Count	DLC Pin
✓	Engine Control Module	No DTCs Stored	0	6,14
✓	Chassis Control Module	No DTCs Stored	0	6,14
✓	Transmission Control Module	No DTCs Stored	0	6,14
✓	Electronic Brake Control Module	No DTCs Stored	0	6,14
✗	Distance Sensing Cruise Control Module	No Communication		6,14
✓	Parking Brake Control Module	No DTCs Stored	0	6,14
✓	Power Steering Control Module	No DTCs Stored	0	6,14
✓	Steering Wheel Angle Sensor Module	No DTCs Stored	0	12,13
✓	Body Control Module	No DTCs Stored	0	6,14
✓	Serial Data Gateway Module	No DTCs Stored	0	6,14
✓	Inflatable Restraint Sensing and Diagnostic Module	No DTCs Stored	0	1
✓	Passenger Presence Module	No DTCs Stored	0	1

Clear DTCs Refresh Details

Back Contact Us Home Vehicle Menu Enter

GDS 2 v.17.1.15100 GM Global v2017.8.0 VIN: 1G1105S38HU195416 2017,Chevrolet,Impala MDI 2: 88746860 13.9 V

1:58 PM 9/3/2017

Scan Data

GDS 2

Vehicle DTC Information

Create Report Add Bookmark

DTC Summary

Status	Control Module Name	Control Module Status	DTC Count	DLC Pin
✓	Passenger Presence Module	No DTCs Stored	0	1
✓	Instrument Cluster	No DTCs Stored	0	1
✓	Radio Controls	No DTCs Stored	0	1
✓	HVAC Controls	No DTCs Stored	0	1
⚠	Radio	DTCs Stored	1	1
✓	Amplifier	No DTCs Stored	0	1
✗	Media Disc Player	No Communication		1
⚠	Human Machine Interface Control Module	DTCs Stored	1	6,14
✓	Telematics Communication Interface Control Mod...	No DTCs Stored	0	6,14
✓	HVAC Control Module	No DTCs Stored	0	1
✗	Seat Memory Control Module - Driver	No Communication		1
✗	Keyless Entry Control Module	No Communication		1

Clear DTCs Refresh Details

Back Contact Us Home Vehicle Menu Enter

GDS 2 v.17.1.15100 GM Global v2017.8.0 VIN: 1G1105S38HU195416 2017,Chevrolet,Impala MDI 2: 88746860 13.9 V

1:59 PM 9/3/2017

Scan Data

GDS 2

Vehicle DTC Information

Create Report Add Bookmark

DTC Summary

Status	Control Module Name	Control Module Status	DTC Count	DLC Pin
⚠	Radio	DTCs Stored	1	1
✓	Amplifier	No DTCs Stored	0	1
✗	Media Disc Player	No Communication		1
⚠	Human Machine Interface Control Module	DTCs Stored	1	6,14
✓	Telematics Communication Interface Control Mod...	No DTCs Stored	0	6,14
✓	HVAC Control Module	No DTCs Stored	0	1
✗	Seat Memory Control Module - Driver	No Communication		1
✗	Keyless Entry Control Module	No Communication		1
✗	Right Side Object Detection Control Module	No Communication		1
✗	Left Side Object Detection Control Module	No Communication		1
✗	Parking Assist Control Module	No Communication		1
✗	Frontview Camera Module	No Communication		1

Clear DTCs Refresh Details

Back Contact Us Home Vehicle Menu Enter

GDS 2 v.17.1.15100 GM Global v2017.8.0 VIN: 1G1105S38HU195416 2017,Chevrolet,Impala MDI 2: 88746860 13.9 V

1:59 PM 9/3/2017

Scan Data

The screenshot displays the GDS 2 software interface. On the left, a sidebar contains four menu items: 'Module Diagnostics' (highlighted), 'Vehicle Diagnostics', 'System Diagnostics', and 'Session Manager'. The main area on the right is divided into three sections. The top section, 'Selected Vehicle', contains a table with vehicle information. The middle section, 'Selected Vehicle Configuration', contains a table with various vehicle specifications. The bottom section, 'Navigation Path', is currently empty. At the bottom of the window, a status bar provides system information, and a taskbar is visible at the very bottom.

Property	Value	Value Source
Model Year	2017	VIN
Make	Chevrolet	VIN
Model	Impala	VIN

Property	Value	
Steering Column...	Not Equipped	..
Headlamp Type	Halogen (T4A TT4)	..
Chassis Control ...	0301	..
Power Steering Ty...	Belt Driven Electric Power Steering ...	..
Marketing Region	Other	..
Telematics Com...	10	..
Power Steering Co...	0A09	..
Seat Memory Cont...	Not Equipped	..
HVAC Control Mod...	Auto Control Dual Zone (CJ2)	..
Engine Identifier	3.6L (LFX)	..

Navigation Path

Back Contact Us Home Vehicle Menu Enter

GDS 2 v:17.1.15100 GM Global v2017.8.0 VIN: 1G1105S38HU195416 2017,Chevrolet,Impala MDI 2: 88746860 12.3 V

2:06 PM 9/3/2017

Scan Data

Data Bus Diagnostic Tool


Detected State: OK 01:50:800

Responded	Longest Response Time	Data Circuit	Control Module
✓		6, 14	K20 Engine Control Module
✓		6, 14	K71 Transmission Control Module T12 Automatic Transmission Assembly Q8 Control Solenoid Valve Assembly
✓		6, 14	K38 Chassis Control Module K27 Fuel Pump Control Module K103 Fuel Injector Control Module
	00:07:416	1	K9 Body Control Module
✓		1	A11 Radio
✓		1	K85 Passenger Presence Module
✓		1	P17 Info Display Module K48 Infotainment Faceplate Control Module
✓		1	K36 Inflatable Restraint Sensing and Diagnostic Module
✓		1	A26 HVAC Controls
✓		1	P16 Instrument Cluster
✓		1	K73 Telematics Communication Interface Control Module
✓		1	K33 HVAC Control Module
✓		1	K56 Serial Data Gateway Module
✓		1	T3 Audio Amplifier

12.52 V MDI 2:88746860

2:13 PM 9/3/2017

MOST – BUS Diagnostic Starting Point



GDS 2

Info Display Test

Active AM/FM Antenna

Satellite Antenna

MOST Communication Enable Circuit

MOST Bus Diagnostic Starting Point

Selected Vehicle

Property	Value	Value Source
Model Year	2017	VIN
Make	Chevrolet	VIN

Selected Vehicle Configuration

Property	Value	Value Source
Steering...	Not Equi...	Control ...
Headlamp...	Halogen (...)	RPO
Chassis ...	0301	Control ...
Power Ste...	Belt Drive...	RPO
Marketing ...	Other	User
Telemati...	10	Control ...
Power Ste...	0A09	Control M...

Navigation Path

Module Diagnostics


Radio

Back Contact Us Home Vehicle Menu Enter

GDS 2 v.17.1.15100 GM Global v2017.8.0 VIN: 1G1105S38HU195416 2017,Chevrolet,Impala MDI 2: 88746860 13.7 V

2:00 PM 9/3/2017

MOST – BUS Diagnostic Starting Point



GDS 2

MOST Bus Diagnostic Starting Point

Complete

Add Bookmark

Parameter Name	Control Module	Value	Unit
Battery Voltage	Radio	11.6	V
Number of MOST Communication Breaks	Radio	0	
Number of MOST Bus Nodes	Radio	4	
Surrogate MOST Master Node Upstream Position	Radio	0	
Node Locations of MOST Bus Communication Break	Radio	4 - 1	

Continue

Back Contact Us Home Vehicle Menu Enter

GDS 2 v.17.1.15100 GM Global v2017.8.0 VIN: 1G1105S38HU195416 2017,Chevrolet,Impala MDI 2: 88746860 12.4 V

2:01 PM 9/3/2017

MOST – BUS Diagnostic Starting Point

GDS 2

MOST Bus Diagnostic Starting Point

Complete

Add Bookmark

Parameter Name	Control Module	Value	Unit
Node Locations of MOST Bus Communication Break	Radio	4 - 1	
Last Working MOST ID of Node 1	Radio	Radio	
Last Working MOST ID of Node 2	Radio	Human Machine Interface ...	
Last Working MOST ID of Node 3	Radio	Amplifier	
Last Working MOST ID of Node 4	Radio	Instrument Cluster	


Continue

Back Contact Us Home Vehicle Menu Enter

GDS 2 v.17.1.15100 GM Global v2017.8.0 VIN: 1G1105S38HU195416 2017,Chevrolet,Impala MDI 2: 88746860 12.5 V

2:03 PM 9/3/2017

MOST – BUS Diagnostic Starting Point



GDS 2

MOST Bus Diagnostic Starting Point

Complete

Add Bookmark

Parameter Name	Control Module	Value	Unit
Last Working MOST ID of Node 1	Radio	Radio	
Last Working MOST ID of Node 2	Radio	Human Machine Interface ...	
Last Working MOST ID of Node 3	Radio	Amplifier	
Last Working MOST ID of Node 4	Radio	Instrument Cluster	
Last Working MOST ID of Node 5	Radio	UNRECOGNIZED STATE	


Continue

Back Contact Us Home Vehicle Menu Enter

GDS 2 v.17.1.15100 GM Global v2017.8.0 VIN: 1G1105S38HU195416 2017,Chevrolet,Impala MDI 2: 88746860 12.5 V

2:03 PM 9/3/2017

MOST Schematics




MOST – Numbers Assigned for normal operation CCW

- Radio – 1
- HMI - 2
- Amp – 3
- IC- 4

Media Oriented Systems Transport – Normal Operation

- Here is an example of how the normal operation may be viewed per this example.

**There is no
Media Disc
Player on this
vehicle**




MOST – Numbers Assigned for diagnostics CW


- Radio – 0
- IC – 1
- Amp- 2
- HMI – 3

- Here is an example of how the diagnostics may be viewed per this example.


- There is no
Media Disc
Player on this
vehicle**




Data Bus Tool – Pins 6 and 14



Data Bus Tool – Pin 1



Radio Failure - Example



Bad Radio



MOST Data Parameters

Surrogate MOST Master

Scan Data

Surrogate MOST master node upstream position	Radio	1
Number of MOST communication breaks	Radio	24
Last working MOST ID of Node 1	Radio	Human Machine Interface Control Module
Last working MOST ID of Node 2	Radio	Instrument Cluster
Last working MOST ID of Node 3	Radio	Amplifier
Last working MOST ID of Node 4	Radio	CD



DownStream



Upstream

1

“Surrogate MOST master node upstream position” Parameter on Scan Tool

- When the radio assigns a node as the **“Surrogate MOST Master”**
- The radio is identifying the **last module** in the ring to **communicate with the radio**. Buss management functions are NOT transferred to the surrogate.

“Surrogate MOST master node upstream position” Parameter on Scan Tool

- The “Surrogate MOST Master Node Upstream Position” parameter is used to denote which module is the **Surrogate MOST Master**.
- The Radio will denote the “Surrogate MOST Master Node Upstream” Position value when codes such as **DTC U0028** are stored in the radio history

“Surrogate MOST master node upstream position” Parameter on Scan Tool


- The **Last Working MOST ID** of Node parameters tell you how modules are connected to the network and should match the same order outlined in the **Service Information MOST communications schematic**

“Surrogate MOST master node upstream position” Parameter on Scan Tool

- Use the Surrogate MOST Master Node Upstream Position parameter number to **count the nodes upstream of the radio**
 - For example: If the **Surrogate MOST Master Node Upstream Position parameter is 1**, you would count the last node on the list as the number 1. It will be shown as the last one on the list for **MOST ID of Node parameters list**.

Media Oriented Systems Transport – Example

- Once a DTC is set, diagnostics (CW) begins and a 300ms low signal is sent over the MOST protocol.
- All modules will try to respond by transmitting data over the MOST protocol.
- The responding module prior to the break upstream of the radio becomes the Surrogate MOST master
- The entire process takes up to 10 seconds to complete.



Scan Data

Surrogate MOST master node upstream position	Radio	1
Number of MOST communication breaks	Radio	24
Last working MOST ID of Node 1	Radio	Human Machine Interface Control Module
Last working MOST ID of Node 2	Radio	Instrument Cluster
Last working MOST ID of Node 3	Radio	Amplifier
Last working MOST ID of Node 4	Radio	CD



DownStream



Upstream

1

Number of MOST Communication Breaks

“Number of MOST Communication Breaks” Parameter on Scan Tool

- The “Number of MOST Communication Breaks” parameter displays the number of times MOST communication is interrupted
- A MOST Communication Break counter will increment each time the MOST communication ring successfully initializes and then goes down. In other words, when the U0028 sets current, this will be 1 count. When the U0028 goes to history and back to current again, this will equal 2 counts

“Number of MOST Communication Breaks” Parameter on Scan Tool

- The Number of MOST Communication Breaks parameter and the Surrogate MOST Master Upstream Position parameter can be used to identify possible causes of intermittent MOST network faults
- The Number of MOST Communication Breaks parameter begins at **0** and can count up to **65,535 breaks**

“Number of MOST Communication Breaks” Parameter on Scan Tool

- The Number of MOST Communication Breaks parameter and the Surrogate MOST Master Upstream Position parameter can be used to identify possible causes of intermittent MOST network faults
- The Number of MOST Communication Breaks parameter begins at **0** and can count up to **65,535 breaks**

Scan Data

Surrogate MOST master node upstream position	Radio	1
Number of MOST communication breaks	Radio	24
Last working MOST ID of Node 1	Radio	Human Machine Interface Control Module
Last working MOST ID of Node 2	Radio	Instrument Cluster
Last working MOST ID of Node 3	Radio	Amplifier
Last working MOST ID of Node 4	Radio	CD

MOST Diagnosis: MOST Parameters

- The Surrogate MOST Master Node Upstream Position parameter is used to find the Surrogate MOST Master module
- With the latest software, the radio will report the Surrogate MOST Master Node Upstream Position value when DTC U0028 is stored in history
- The Last Working MOST ID of Node parameters tell you how modules are connected to the network and should match the same order outlined in the Service Information MOST communications schematic
- Use the Surrogate MOST Master Node Upstream Position parameter number to count the nodes upstream of the radio
 - For example: if the Surrogate MOST Master Node Upstream Position parameter is 3, you will count three modules up from the last node / module on the Last Working MOST ID of Node parameters list.

Surrogate MOST Master Exercises


Finding the Surrogate MOST Master

Data Display			
Radio Data			
Parameter Name	Control Module	Value	Unit
Surrogate MOST Master Node Upstream Position	Radio	4	
Last Working MOST ID of Node 1	Radio	Radio	
Last Working MOST ID of Node 2	Radio	HMI Module	4
Last Working MOST ID of Node 3	Radio	Instrument Cluster	3
Last Working MOST ID of Node 4	Radio	Amplifier	2
Last Working MOST ID of Node 5	Radio	CD-Player	1

- If the Surrogate MOST Master Node Upstream Position parameter is 4, the HMI module will be the Surrogate MOST Master

Media Oriented Systems Transport – Abnormal Operation

- If the HMI Module is the Surrogate MOST Master, the cause of the MOST fault will be between the HMI module and the radio or the radio may be at fault




Finding the Surrogate MOST Master

Data Display			
Radio Data			
Parameter Name	Control Module	Value	Unit
Surrogate MOST Master Node Upstream Position	Radio	3	
Last Working MOST ID of Node 1	Radio	Radio	
Last Working MOST ID of Node 2	Radio	HMI Module	
Last Working MOST ID of Node 3	Radio	Instrument Cluster	3
Last Working MOST ID of Node 4	Radio	Amplifier	2
Last Working MOST ID of Node 5	Radio	CD-Player	1

- If the Surrogate MOST Master Node Upstream Position parameter is 3, the instrument cluster will be the Surrogate MOST Master

Media Oriented Systems Transport – Abnormal Operation

- If the instrument cluster is the Surrogate MOST Master, the cause of the MOST fault will be between the instrument cluster and the HMI module, or the HMI module may be at fault




Finding the Surrogate MOST Master

Data Display			
Radio Data			
Parameter Name	Control Module	Value	Unit
Surrogate MOST Master Node Upstream Position	Radio	2	
Last Working MOST ID of Node 1	Radio	Radio	
Last Working MOST ID of Node 2	Radio	HMI Module	
Last Working MOST ID of Node 3	Radio	Instrument Cluster	
Last Working MOST ID of Node 4	Radio	Amplifier	2
Last Working MOST ID of Node 5	Radio	CD-Player	1

- If the Surrogate MOST Master Node Upstream Position parameter is 2, the amplifier will be the Surrogate MOST Master

Media Oriented Systems Transport – Abnormal Operation

- If the instrument cluster is the Surrogate MOST Master, the cause of the MOST fault will be between the Amplifier and the Instrument Cluster, or the Instrument Cluster may be at fault




Finding the Surrogate MOST Master

Data Display			
Radio Data			
Parameter Name	Control Module	Value	Unit
Surrogate MOST Master Node Upstream Position	Radio	1	
Last Working MOST ID of Node 1	Radio	Radio	
Last Working MOST ID of Node 2	Radio	HMI Module	
Last Working MOST ID of Node 3	Radio	Instrument Cluster	
Last Working MOST ID of Node 4	Radio	Amplifier	
Last Working MOST ID of Node 5	Radio	CD-Player	

- If the Surrogate MOST Master Node Upstream Position parameter is 1, the CD Player will be the Surrogate MOST Master

Media Oriented Systems Transport – Abnormal Operation

- If the instrument cluster is the Surrogate MOST Master, the cause of the MOST fault will be between the CD and the Amplifier, or the Amplifier may be at fault




Finding the Surrogate MOST Master

Data Display			
Radio Data			
Parameter Name	Control Module	Value	Unit
Surrogate MOST Master Node Upstream Position	Radio	0	
Last Working MOST ID of Node 1	Radio	Radio	
Last Working MOST ID of Node 2	Radio	HMI Module	
Last Working MOST ID of Node 3	Radio	Instrument Cluster	
Last Working MOST ID of Node 4	Radio	Amplifier	
Last Working MOST ID of Node 5	Radio	CD-Player	

- If the Surrogate MOST Master Node Upstream Position parameter is 0, the Radio will be the Surrogate MOST Master


Media Oriented Systems Transport – Abnormal Operation

- If the radio is the Surrogate MOST Master, the cause of the MOST fault will be between radio and the CD player, or the CD player may be at fault



MOST Diagnosis

- The cause of the MOST ring break may be:
 - A MOST network circuit fault upstream of the Surrogate
 - An open in the MOST control circuit
 - Loss of power or ground to a module upstream of the Surrogate
 - Fault internal to a module upstream of the Surrogate
 - A fault internal to the Surrogate MOST Master module itself that prevents the module from receiving data



Which module is Surrogate MOST Master if:

- Surrogate MOST Master Node Upstream Position = 2
- Vehicle RPOs:
 - IO3
 - WCN

Correct Answer:
Instrument Cluster

MOST Wire Repair

- Replacement wire should be the same size as the wire being repaired
 - Refer to connector end views in SI for wire size
 - MOST wire size must be larger than 0.22mm (31 AWG)
- MOST communication wires should maintain a certain number of twists per length of wire when possible
 - One twist for every 45mm (1 45/64in) of wire
- Any untwisted sections of MOST wire (i.e., a wire leading up to a connector) must not exceed 10cm (3 15/16in) in length

After Repairing a MOST Fault

- After correcting a MOST fault:
 - Carry out the Diagnostic Repair Verification procedure
 - Remove power from the radio for one minute either by removing the radio fuse(s) or disconnecting the negative battery terminal. By doing this the following two items will be accomplished:
 - The Surrogate MOST Master Node Upstream Position value is reset to "None"
 - The Number of MOST Communication Breaks counter is reset to "0"

Diagnostic Tool to Assist with MOST Communication Breaks

EL-51578 MOST Bus Diagnostic Tool Kit




- The EL-51578 MOST Bus Diagnostic Test Kit will assist in the diagnosis of a MOST ring break, DTC U0028

EL-51578 MOST Bus Diagnostic Tool Kit



- The MOST Bus Diagnostic Tool Kit consists of several test connectors
- Each connector matches a connector on a MOST device
- Connectors jump the MOST bus wires to bypass MOST devices

EL-51578 MOST Bus Diagnostic Tool Kit



EL-51578-5 CD Player Test Connector		
Pin#	Circuit#	Function
1	3999	MOST ECL
3	3997	MOST (-) Transmit
4	3998	MOST (+) Transmit
5	3997	MOST (-) Receive
6	3998	MOST (+) Receive

- Two jumper wires on each test connector connect the MOST receive (RX) and MOST transmit (TX) circuits.
- A third wire is used to test the MOST Electronic Control Line (ECL). A standard banana socket allows for a DMM lead or Lab Scope to be connected to test the circuit.

EL-51578 MOST Bus Diagnostic Tool Kit

DTC Display					
Control Module	DTC	Symptom Byte	Description	Symptom Description	Status
Radio	U0028	00	MOST Bus	———	Current

DTC Display					
Control Module	DTC	Symptom Byte	Description	Symptom Description	Status
Radio	U0028	00	MOST Bus	———	History


- The scan tool is used along with the MOST Bus Diagnostic Tool Kit
- When a test connector from the kit is used to bypass a MOST device, the status of DTC U0028 will be used to determine if there is still a break in the MOST ring
- If DTC U0028 status is "Current", there is still a break in the MOST ring. If DTC U0028 status switches to "History", the ring is complete.



MOST Question

- If one of the 2 MOST communication lines are grounded(example), will it code and broadcast on the other MOST bus line that are not grounded?
- Answer: It would be recorded as a break in the system and a code would set indicating that there is an issue with the MOST bus.
- A surrogate would be assigned to assist with the diagnostics of the system.

EL-51578 MOST Bus Diagnostic Tool Kit



Ring Break Review:

Possible causes of a MOST ring break include:


- A. A fault with the MOST device upstream of the Surrogate MOST Master
 1. internal fault
 2. power / ground
 3. ECL circuit fault
- B. A fault internal to the RX circuit inside the Surrogate MOST Master
- C. A fault in the MOST network wiring upstream of the Surrogate MOST Master

The MOST Bus Diagnostic Kit and the scan tool help to isolate the cause of a MOST ring break by connecting the MOST network around a device rather than through it.

Amplifier Fault


Media Oriented Systems Transport – Abnormal Operation

- In this example, an amplifier fault keeps the amplifier from communicating over the MOST bus
- DTC U0028 is set in the radio as a “current” DTC
- The CD Player is reported as the Surrogate MOST Master




Media Oriented Systems Transport – Abnormal Operation

- The wiring harness is disconnected from the amplifier
- The appropriate test connector is connected to the harness in place of the amplifier



Media Oriented Systems Transport – Abnormal Operation


- The scan tool is used to view radio DTCs
- If the status of DTC U0028 changes from Current to History, the amplifier was the cause of the ring break
- If amp GMLAN communications is now present, replace the amplifier



MOST Wiring Fault


Media Oriented Systems Transport – Abnormal Operation

- In this example, an amplifier fault keeps the amplifier from communicating over the MOST bus
- DTC U0028 is set in the radio as a “current” DTC
- The CD Player is reported as the Surrogate MOST Master




Media Oriented Systems Transport – Abnormal Operation

- The wiring harness is disconnected from the amplifier
- The appropriate test connector is connected to the harness in place of the amplifier




Media Oriented Systems Transport – Abnormal Operation

- The scan tool is used to view radio DTCs
- In this instance, the status of DTC U0028 remains Current
- The next step is to bypass the Surrogate (CD player) using the appropriate test connector




Media Oriented Systems Transport – Abnormal Operation

- The amplifier wiring harness is reconnected
- The wiring harness is disconnected from the CD player
- The appropriate test connector is connected to the harness in place of the CD player



Media Oriented Systems Transport – Abnormal Operation

- The scan tool is used to view radio DTCs
- In this instance the status of DTC U0028 remains “Current”
- The MOST serial data circuits are tested for short to voltage, short to ground, short together, and high resistance



Normal Operation

2018 Chev Impala

2018 Chev Impala



2018 Chev Impala



2018 Chev Impala



2018 Chev Impala

GDS 2

Vehicle Selection

Device: MDI 2: 88746860 ☐ Navigate Without Device

Press Enter To Continue.

Make	Chevrolet
Model	Impala
Model Year	2018

VIN: 2G1105S33J9110940

VIN	Model Year	Make	Model	Timestamp
1G1ZD5ST6JF122692	2018	Chevrolet	Malibu	Sep 18, 2017 4:26:38 PM
1G1105S38HU195416	2017	Chevrolet	Impala	Sep 3, 2017 2:35:44 PM

GDS 2 v.17.1.15100 GM Global v2017.8.0 MDI 2: 88746860 12.3 V

4:29 PM 9/20/2017

2018 Chev Impala

GDS 2

Data Display

Diagnostic Data Display Graphical Data Display Line Graph DTC Display

Radio Data


Parameter Name	Value	Unit	Control Module
XM Subscription Status	Invalid		Radio
High Definition Signal	Not Present		Radio
Digital Audio Signal	Not Present		Radio
Alternative Frequency Status	Inactive		Radio
Surrogate MOST Master Node Upstream Position	None		Radio
Number of MOST Communication Breaks	95		Radio
Last Working MOST ID of Node 1	Radio		Radio
Last Working MOST ID of Node 2	Human Machine Interface Control Module		Radio
Last Working MOST ID of Node 3	Amplifier		Radio
Last Working MOST ID of Node 4	Instrument Cluster		Radio
Last Working MOST ID of Node 5	UNRECOGNIZED STATE		Radio

Back Contact Us Home Vehicle Menu Enter

GDS 2 v.17.1.15100 GM Global v2017.8.0 VIN: 2G1105S33J9110940 2018,Chevrolet,Impala MDI 2: 88746860 12.4 V

4:33 PM 9/20/2017

2018 Chev Impala



Abnormal Operation

2018 Chev Impala

2018 Chev Impala



2018 Chev Impala – No Fault

GDS 2

Data Display

Diagnostic Data Display Graphical Data Display Line Graph DTC Display

Radio Data

Parameter Name Value Unit Control Module

XM Subscription Status	Invalid		Radio
High Definition Signal	Not Present		Radio
Digital Audio Signal	None		Radio
Alternative Frequency Status	98	Radio	Radio
Surrogate MOST Master	Radio	Radio	Radio
Number of MOST Co			
Last Working MOST	Human Machine Interface Control Module	Radio	
Last Working MOST	Amplifier	Radio	
Last Working MOST ID	Instrument Cluster	Radio	
Last Working MOST ID of		Radio	Radio
Last Working MOST ID of Node	UNRECOGNIZED STATE	Radio	Radio

Back Contact Us Enter

GDS 2 v.17.1.15100 GM Global v2017.8.0 VIN: 2G1105S33J9110940 2018,Chevrolet,Impala MDI 2: 88746860 13.6 V 2:03 PM 9/21/2017

2018 Chev Impala – Fault

GDS 2

Data Display

Diagnostic Data Display Graphical Data Display Line Graph DTC Display

Radio Data

Parameter Name Unit Control Module


XM Subscription Status	1	Radio	Radio
High Definition Signal	98	Radio	Radio
Digital Audio Signal	Radio	Radio	Radio
Alternative Frequency Stat	Radio	Radio	Radio
Surrogate MOST Master	Human Machine Interface Control Module	Radio	Radio
Number of MOST Commu	Amplifier	Radio	Radio
Last Working MOST ID of N	Instrument Cluster	Radio	Radio
Last Working MOST ID of Node	UNRECOGNIZED STATE	Radio	Radio
Last Working MOST ID of Node 3			Radio
Last Working MOST ID of Node 4			Radio
Last Working MOST ID of Node 5	UNRECOGNIZED STATE		Radio

Back Contact Us Home Vehicle Menu Enter

GDS 2 v.17.1.15100 GM Global v2017.8.0 VIN: 2G1105S33J9110940 2018,Chevrolet,Impala MDI 2: 88746860 13.9 V

2:09 PM 9/21/2017

MOST Schematic – 2018 Impala



2018 Chev Impala

GDS 2

MOST Bus Diagnostic Starting Point

Complete

Add Bookmark

Parameter Name	Control Module	Value	Unit
Battery Voltage	Radio	13.0	V
Number of MOST Communication Breaks	Radio	98	
Number of MOST Bus Nodes	Radio	4	
Surrogate MOST Master Node Upstream Position	Radio	1	
Node Locations of MOST Bus Communication Break	Radio	3 - 4	


Continue

Back Contact Us Home Vehicle Menu Enter

GDS 2 v.17.1.15100 GM Global v2017.8.0 VIN: 2G1105S33J9110940 2018,Chevrolet,Impala MDI 2: 88746860 13.7 V


2:10 PM 9/21/2017

2018 Chev Impala



MOST Schematic - 2010

Impala



2018 Chev Impala

GDS 2

MOST Bus Diagnostic Starting Point

Complete

Add Bookmark

Parameter Name	Control Module	Value	Unit
Last Working MOST ID of Node 1	Radio	Radio	
Last Working MOST ID of Node 2	Radio	Human Machine Interface ...	
Last Working MOST ID of Node 3	Radio	Amplifier	
Last Working MOST ID of Node 4	Radio	Instrument Cluster	
Last Working MOST ID of Node 5	Radio	UNRECOGNIZED STATE	

Continue

Back Contact Us Home Vehicle Menu Enter


GDS 2 v.17.1.15100 GM Global v2017.8.0 VIN: 2G1105S33J9110940 2018,Chevrolet,Impala MDI 2: 88746860 13.7 V

2:11 PM 9/21/2017

2018 Chev Impala



2018 Chev Impala



2018 Chev Impala



2018 Chev Impala - Current

GDS 2

DTC Display

Create Report Add Bookmark

DTC Display

Control Module	DTC	Symptom Byte	Description	Symptom Description	Status
Radio	U0028	00	MOST Bus	- - -	Current

Category	Decoded Value
DTC Current Status	Current
DTC History Status	History

Clear DTCs Refresh Summary

Back Contact Us Home Vehicle Menu Enter

GDS 2 v.17.1.15100 GM Global v2017.8.0 VIN: 2G1105S33J9110940 2018,Chevrolet,Impala MDI 2: 88746860 13.6 V 2:11 PM 9/21/2017

Bypass Tool



2018 Chev Impala



GDS 2

Vehicle DTC Information

Create Report Add Bookmark

DTC Summary

Status	Control Module Name	Control Module Status	DTC Count	DLC Pin
✓	Inflatable Restraint Sensing and Diagnostic Module	No DTCs Stored	0	1
✓	Passenger Presence Module	No DTCs Stored	0	1
✓	Instrument Cluster	No DTCs Stored	0	1
⚠	Radio Controls	DTCs Stored	1	1
✓	HVAC Controls	No DTCs Stored	0	1
⚠	Radio	DTCs Stored	1	1
✓	Amplifier	No DTCs Stored	0	1
✗	Rear Audio Control Module	No Communication		1
✗	Media Disc Player	No Communication		1
⚠	Human Machine Interface Control Module	DTCs Stored	1	6,14
✓	Telematics Communication Interface Control Mod...	No DTCs Stored	0	6,14
✓	HVAC Control Module	No DTCs Stored	0	1

Clear DTCs Refresh Details

Back Contact Us Home Vehicle Menu Enter

GDS 2 v.17.1.15100 GM Global v2017.8.0 VIN: 2G1105S33J9110940 2018,Chevrolet,Impala MDI 2: 88746860 13.7 V 9/21/2017

2018 Chev Impala - History

GDS 2

DTC Display

Create Report Add Bookmark

Control Module	DTC	Symptom Byte	Description	Symptom Description	Status
Human Machine Interf...	U0029	00	MOST Bus Performance	- - -	History


Category	Decoded Value
DTC Current Status	Not Current
DTC History Status	History

Clear DTCs Refresh Summary

Back Contact Us Home Vehicle Menu Enter

GDS 2 v.17.1.15100 GM Global v2017.8.0 VIN: 2G1105S33J9110940 2018,Chevrolet,Impala MDI 2: 88746860 13.7 V 2:13 PM 9/21/2017

Radio and HVAC Communications



- **A20** needs to talk to **P17**, if communication is questionable a code will be set indicating that there is a possible issue with the LIN Bus

2018 Chev Impala

GDS 2

Vehicle DTC Information

Create Report Add Bookmark

DTC Display

Control Module	DTC	Symptom Byte	Description	Symptom Description	Status
Instrument Cluster	U2098	00	MOST Communication Enable Ci...	- - -	Passed and Failed
Radio Controls	U150F	00	LIN Bus	- - -	History
Radio	U0028	00	MOST Bus	- - -	History
Human Machine Interf...	U0029	00	MOST Bus Performance	- - -	History
Human Machine Interf...	U0029	02	MOST Bus Performance	Short to Ground	History

Category	Decoded Value
This Ignition Cycle	Passed
Since DTC Clear	Passed and Failed
DTC Current Status	Not Current
DTC History Status	History


Clear DTCs Refresh Summary

Back Contact Us Home Vehicle Menu Enter


GDS 2 v.17.1.15100 GM Global v2017.8.0 VIN: NOVIN170921142747 2018,Chevrolet,Impala MDI 2: 88746860 13.7 V

2:37 PM 9/21/2017

2018 Chev Impala – Code Clear



2018 Chev Impala



2018 Chev Impala

GDS 2

Vehicle DTC Information

Create Report Add Bookmark

DTC Summary

Status	Control Module Name	Control Module Status	DTC Count	DLC Pin
✓	Serial Data Gateway Module	No DTCs Stored	0	6,14
✓	Inflatable Restraint Sensing and Diagnostic Module	No DTCs Stored	0	1
✓	Passenger Presence Module	No DTCs Stored	0	1
✓	Instrument Cluster	No DTCs Stored	0	1
✓	Radio Controls	No DTCs Stored	0	1
✓	HVAC Controls	No DTCs Stored	0	1
✓	Radio	No DTCs Stored	0	1
✓	Amplifier	No DTCs Stored	0	1
✗	Rear Audio Control Module	No Communication		1
✗	Media Disc Player	No Communication		1
✓	Human Machine Interface Control Module	No DTCs Stored	0	6,14
✓	Telematics Communication Interface Control Mod...	No DTCs Stored	0	6,14

Clear DTCs Refresh Details

Back Contact Us Home Vehicle Menu Enter

GDS 2 v.17.1.15100 GM Global v2017.8.0 VIN: NOVIN170921142747 2018,Chevrolet,Impala MDI 2: 88746860 13.8 V 2:42 PM 9/21/2017

2018 Chev Impala – Code Clear

GDS 2

Data Display

Diagnostic Data Display | Graphical Data Display | Line Graph | DTC Display

Radio Data

|| | | | | |

Parameter Name	Value	Unit	Control Module
Digital Audio Signal	Not Present		Radio
Alternative Frequency Status	Inactive		Radio
Surrogate MOST Master Node Upstream Position	None		Radio
Number of MOST Communication Breaks	0		Radio
Last Working MOST ID of Node 1	Radio		Radio
Last Working MOST ID of Node 2	Human Machine Interface Control Module		Radio
Last Working MOST ID of Node 3	Amplifier		Radio
Last Working MOST ID of Node 4	Instrument Cluster		Radio
Last Working MOST ID of Node 5	UNRECOGNIZED STATE		Radio
Last Working MOST ID of Node 6	UNRECOGNIZED STATE		Radio
Last Working MOST ID of Node 7	UNRECOGNIZED STATE		Radio

Back | Contact Us | Home | Vehicle Menu | Enter

GDS 2 v.17.1.15100 | GM Global v2017.8.0 | VIN: NOV1N170921142747 | 2018,Chevrolet,Impala | MDI 2: 88746860 | 13.8 V | 2:50 PM 9/21/2017

2018 Chev Impala No Fault

GDS 2

Data Display

Diagnostic Data Display Graphical Data Display Line Graph DTC Display

Radio Data

|| | | | | |

Parameter Name	Value	Unit	Control Module
Battery Voltage	3.0	V	Radio
Power Mode	Off		Radio
Date	September 21, 2017		Radio
Time	00:53:42		Radio
Radio Band	UNRECOGNIZED STATE		Radio
Current FM Frequency	0	MHz	Radio
Current AM Frequency	0	kHz	Radio
Radio Power Button	Off		Radio
Remote CD	Not Present		Radio
Rear Seat Entertainment	Not Present		Radio
Front 3.5 mm AUX Input	Not Present		Radio

Back Contact Us Home Vehicle Menu Enter

GDS 2 v.17.1.15100 GM Global v2017.8.0 VIN: NOV1N170921142747 2018,Chevrolet,Impala MDI 2: 88746860 12.9 V

2:53 PM 9/21/2017

2018 Chev Impala - Fault

GDS 2

Data Display

Diagnostic Data Display Graphical Data Display Line Graph DTC Display

Radio Data

Pause Lock Upload Download Refresh

Parameter Name	Value	Unit	Control Module
High Definition Signal	Not Present		Radio
Digital Audio Signal	Not Present		Radio
Alternative Frequency Status	Inactive		Radio
Surrogate MOST Master Node Upstream Position	1		Radio
Number of MOST Communication Breaks	0		Radio
Last Working MOST ID of Node 1	Radio		Radio
Last Working MOST ID of Node 2	Human Machine Interface Control Module		Radio
Last Working MOST ID of Node 3	Amplifier		Radio
Last Working MOST ID of Node 4	Instrument Cluster		Radio
Last Working MOST ID of Node 5	UNRECOGNIZED STATE		Radio
Last Working MOST ID of Node 6	UNRECOGNIZED STATE		Radio

Back Contact Us Home Vehicle Menu Enter

GDS 2 v.17.1.15100 GM Global v2017.8.0 VIN: NOV1N170921142747 2018,Chevrolet,Impala MDI 2: 88746860 13.8 V

2:55 PM 9/21/2017

2018 Chev Impala

GDS 2

Vehicle DTC Information

Create Report Add Bookmark

DTC Summary

Status	Control Module Name	Control Module Status	DTC Count	DLC Pin
✓	Passenger Presence Module	No DTCs Stored	0	1
✓	Instrument Cluster	No DTCs Stored	0	1
✓	Radio Controls	No DTCs Stored	0	1
✓	HVAC Controls	No DTCs Stored	0	1
⚠	Radio	DTCs Stored	1	1
✓	Amplifier	No DTCs Stored	0	1
✗	Rear Audio Control Module	No Communication		1
✗	Media Disc Player	No Communication		1
⚠	Human Machine Interface Control Module	DTCs Stored	1	6,14
✓	Telematics Communication Interface Control Mod...	No DTCs Stored	0	6,14
✓	HVAC Control Module	No DTCs Stored	0	1
✗	Seat Memory Control Module - Driver	No Communication		1

Clear DTCs Refresh Details

Back Contact Us Home Vehicle Menu Enter

GDS 2 v.17.1.15100 GM Global v2017.8.0 VIN: 2G1105S33J9110940 2018,Chevrolet,Impala MDI 2: 88746860 13.6 V

2:57 PM 9/21/2017

2018 Chev Impala - Fault

GDS 2

Vehicle DTC Information

Create Report Add Bookmark

DTC Display

Control Module	DTC	Symptom Byte	Description	Symptom Description	Status
Radio	U0028	00	MOST Bus	---	Current
Human Machine Interf...	U0029	00	MOST Bus Performance	---	History

Category	Decoded Value
DTC Current Status	Current
DTC History Status	History

Clear DTCs Refresh Summary

Back Contact Us Home Vehicle Menu Enter

GDS 2 v.17.1.15100 GM Global v2017.8.0 VIN: 2G1105S33J9110940 2018,Chevrolet,Impala MDI 2: 88746860 13.7 V 2:58 PM 9/21/2017

2018 Chev Impala - Fault



2018 Chev Impala

GDS 2

Vehicle DTC Information

Create Report Add Bookmark

DTC Display

Control Module	DTC	Symptom Byte	Description	Symptom Description	Status
Radio	U0028	00	MOST Bus	- - -	Current
Human Machine Interf...	U0029	00	MOST Bus Performance	- - -	Current

Category	Decoded Value
DTC Current Status	Current
DTC History Status	History

Clear DTCs Refresh Summary

Back Contact Us Home Vehicle Menu Enter

GDS 2 v.17.1.15100 GM Global v2017.8.0 VIN: 2G1105S33J9110940 2018,Chevrolet,Impala MDI 2: 88746860 13.7 V 3:08 PM 9/21/2017

2018 Chev Impala

GDS 2

Vehicle DTC Information

Create Report Add Bookmark

DTC Summary

Status	Control Module Name	Control Module Status	DTC Count	DLC Pin
✓	Radio Controls	No DTCs Stored	0	1
✓	HVAC Controls	No DTCs Stored	0	1
⚠	Radio	DTCs Stored	1	1
✓	Amplifier	No DTCs Stored	0	1
✗	Rear Audio Control Module	No Communication		1
✗	Media Disc Player	No Communication		1
⚠	Human Machine Interface Control Module	DTCs Stored	1	6,14
✓	Telematics Communication Interface Control Mod...	No DTCs Stored	0	6,14
✓	HVAC Control Module	No DTCs Stored	0	1
✗	Seat Memory Control Module - Driver	No Communication		1
✓	Keyless Entry Control Module	No DTCs Stored	0	1
✗	Right Side Object Detection Control Module	No Communication		1

Clear DTCs Refresh Details

Back Contact Us Home Vehicle Menu Enter

GDS 2 v.17.1.15100 GM Global v2017.8.0 VIN: 2G1105S33J9110940 2018,Chevrolet,Impala MDI 2: 88746860 13.6 V 3:17 PM 9/21/2017

2018 Chev Impala – No Fault

Vehicle DTC Information

Create Report Add Bookmark

DTC Display

Control Module	DTC	Symptom Byte	Description	Symptom Description	Status
Radio	U0028	00	MOST Bus	---	History
Human Machine Interf...	U0029	00	MOST Bus Performance	---	History

Category	Decoded Value
DTC Current Status	Not Current
DTC History Status	History

Clear DTCs Refresh Summary

Back Contact Us Home Vehicle Menu Enter

GDS 2 v.17.1.15100 GM Global v2017.8.0 VIN: 2G1105S33J9110940 2018,Chevrolet,Impala MDI 2: 88746860 13.8 V

3:18 PM 9/21/2017

2018 Chev Impala – No Fault



Case Study #2

2015 Cadillac ATS

U2098 Code



**Radio Face is Blank
(Failure)**

Browser window showing the GM Service Information website. The address bar displays the URL: <https://gsi.ext.gm.com/gsi/showDoc.do?docSys>. The page title is "Service Information". The document ID is 2893843.

DTC U2098

Diagnostic Instructions

- Perform the [Diagnostic System Check - Vehicle](#) prior to using this diagnostic procedure.
- Review [Strategy Based Diagnosis](#) for an overview of the diagnostic approach.
- [Diagnostic Procedure Instructions](#) provides an overview of each diagnostic category.

DTC Descriptor

DTC U2098 00
MOST Communication Enable Circuit Malfunction

DTC U2098 02
MOST Communication Enable Circuit Short to Ground

Diagnostic Fault Information


Circuit	Short to Ground	Open/High Resistance	Short to Voltage	Signal Performance
MOST Control	U2098 00, U2098 02, U0029 02	U0028 00	—	—

Circuit/System Description

When the ignition is ON, the A11 Radio initializes the Media Oriented Systems Transport (MOST) bus by sending a short 100 ms low voltage pulse on the electronic control line (or MOST control line) connected to all devices contained on the MOST ring. When MOST receive, transmit, or control line faults are detected, transmit/receive messages will not be received as expected from the wakeup request. The A11 Radio and the K74 Human Machine Interface Control Module will then perform diagnostics to isolate these MOST faults. If the MOST control line is shorted low to 0V for an excessive amount of time, the A11 Radio will set a U2098 DTC and K74 Human Machine Interface Control Module will set a U0029 02 DTC. At this point the MOST bus will be unable to

© 2015 General Motors. All rights reserved.

8:51 PM
3/20/2015



C:\Users\TechUser01\AppData\Local\Temp\GDS 2\DTC Display_1G6
GM GlobalConnect
Document ID: 3703018
DTC Display
DTC Display
DTC Display


File Edit View Favorites Tools Help
Find: amp Previous Next Options

Overview

MDI Serial Number	22116892
Vehicle Identification Number (VIN)	
Diagnostic End Date	2015-03-02 13:13:22
Diagnostic Start Date	2015-03-02 13:13:22
Number of Times Diagnostic Session Resumed	0
Make	Cadillac
Model	ATS
Model Year	2015
Vehicle Variation	A1XX

Control Module	DTC Display	Symptom Byte	DTC Description	Symptom Description	Status
Radio	U2098	02	MOST Communication Enable Circuit	Short to Ground	Current DTC Current Status Current DTC History Status History

1:49 PM
3/2/2015



GDS 2

Data Display

Diagnostic Data Display | Graphical Data Display | Line Graph

Radio Data

Parameter Name	Control Module	Value	Unit
Radio Power Button	Radio	Off	
Remote CD	Radio	Not Present	
Rear Seat Entertainment	Radio	Not Present	
Front 3.5 mm AUX Input	Radio	Not Present	
Rear 3.5 mm AUX Input	Radio	Not Present	
Front USB Receptacle	Radio	Not Present	
Rear USB Receptacle	Radio	Not Present	
Front SD Card Receptacle	Radio	Not Present	
Rear SD Card Receptacle	Radio	Not Present	
Radio Theft Lock Armed	Radio	Armed	
Radio Theft Lock Status	Radio	Inactive	
Test Bench Mode	Radio	Inactive	
Valet Mode Status	Radio	Inactive	
XM Subscription Status	Radio	Invalid	
High Definition Signal	Radio	Not Present	
Digital Audio Signal	Radio	Not Present	
Alternative Frequency Status	Radio	Inactive	
Surrogate MOST Master Node Upstream Position	Radio	0	
Number of MOST Communication Breaks	Radio	24	
Last Working MOST ID of Node 1	Radio	Radio	
Last Working MOST ID of Node 2	Radio	Amplifier	
Last Working MOST ID of Node 3	Radio	Instrument Cluster	
Last Working MOST ID of Node 4	Radio	Human Machine Interface Control Module	
Last Working MOST ID of Node 5	Radio	UNRECOGNIZED STATE	
Last Working MOST ID of Node 6	Radio	UNRECOGNIZED STATE	
Last Working MOST ID of Node 7	Radio	UNRECOGNIZED STATE	

Back Home Vehicle Menu Enter

GDS 2 v.13.0.01800 GM Global v2015.2.0 VIN: 1G6AF65X7F0120142 13.4 V 1:24 PM 3/2/2015

Scan Data


Surrogate MOST master node upstream position	Radio	0
Number of MOST communication breaks	Radio	24
Last working MOST ID of Node 1	Radio	Radio
Last working MOST ID of Node 2	Radio	Amplifier
Last working MOST ID of Node 3	Radio	Instrument Cluster
Last working MOST ID of Node 4	Radio	Human Machine Interface Control Module



Downstream



Upstream




MOST

- No Wakeup call being received with HMI Module in place.
- The wakeup call was being received with the HMI module isolated. The code also went to History as well. (Used MOST Bus Tool EL-51578)
- A bad HMI module was the cause of the issue concerning the graphics for the radio

EL-51578 Connectors





TST 2022 VIRTUAL
19th ANNUAL BIG
EVENT

Thank You for Attending