

## Diagnostic Process

- Description and Operation
  - How does it all Work?
- Verify the Concern
  - Confirm that the Complaint is Valid
- Verify the VIN Information
  - Confirm that there is not a VIN mismatch

## Diagnostic Process

- Check for Codes/Freeze Frame/TSB Search
  - Review Code Descriptors carefully
- Perform Visual Checks/Test Procedures
- Movement No 1
  - Technician Seeks Path
- Movement No 2
  - Technician Walks Path



## Diagnostic Process

- Perform Visual Checks/Test Procedures-Cont'd
- Movement No 3
  - Technician Completes Path
- Movement No 4
  - Technician whips its Tail





# Description and Operation



## 2011 Hyundai Sonata L4-2.4 Liter (GDI)



## Observations Noted

- The vehicle has an issue in terms of communication. The immobilizer system is down.
- It is clear that an understanding of how the Hyundai immobilizer system works is evident
- We must carefully review Description and Operation.

**TST Seminars**  
Professional Training for Automotive Experts







Immobilizer System (Antitheft and Alarm Systems) - ALLDATA Repair

https://my.alldata.com/repair/#/repair/article/48554/component/612/itype/392/nonstandard/927444/selfRefLink/false

Center of Learning... ProDemand Autom... Direct-Hit -- Create... Amazon.com Shop... Thank12w - Free D... AESWAVE ACE Misfire Detecti... Other favorites

**ALLDATA Repair** Diagnostic Hotline MARSHALL Help & Feedback

Change Vehicle Bookmarks Library Request Conversion Calculator Technician's Reference - Repair

immobilizer 114 x

2011 Hyundai Sonata L4-2.4L Community 96

## Immobilizer System

Vehicle > Accessories and Optional Equipment > Antitheft and Alarm Systems > Description and Operation > Components > Immobilizer System

**IMMOBILIZER SYSTEM**

**Description**

The immobilizer system will disable the vehicle unless the proper ignition key is used. In addition to the currently available anti-theft systems such as car alarms, the immobilizer system aims to drastically reduce the rate of auto theft.

1. Encrypted SMARTRA type immobilizer
  - A. The SMARTRA system consists of a passive challenge - response (mutual authentication) transponder located in the ignition key, an antenna coil, an encoded SMARTRA unit, an indicator light and the PCM(ECM).
  - B. The SMARTRA communicates to the PCM(ECM) (Engine Control Module) via a dedicated communications line. Since the vehicle engine management system is able to control engine mobilization, it is the most suitable unit to control the SMARTRA.
  - C. When the key is inserted in the ignition and turned to the ON position, the antenna coil sends power to the transponder in the ignition key. The transponder then sends a coded signal back through the SMARTRA unit to the PCM(ECM).
  - D. If the proper key has been used, the PCM(ECM) will energize the fuel supply system. The immobilizer indicator light in the cluster will simultaneously come on for more than five seconds, indicating that the SMARTRA unit has recognized the code sent by the transponder.
  - E. If the wrong key has been used and the code was not received or recognized by the PCM(ECM) the indicator light will continue blinking for about five seconds until the ignition switch is turned OFF.

**RELATED INFORMATION**

- Description and Operation Components
- Diagrams Electrical (OE) Electrical - Interactive Color (Non OE)
- Parts and Labor Antitheft and Alarm Systems
- Service and Repair Removal and Replacement
- Specifications Electrical
- Technical Service Bulletins

Type here to search

11:32 AM 3/29/2023

Immobilizer System (Antitheft and Alarm Systems) - ALLDATA Repair

https://my.alldata.com/repair/#/repair/article/48554/component/612/itype/392/nonstandard/927444/selfRefLink/fa...

Center of Learning... ProDemand Autom... Direct-Hit -- Create... Amazon.com Shop... Thank12w - Free D... AESWAVE ACE Misfire Detecti... Other favorites

**2011 Hyundai Sonata L4-2.4L** Community 96

F. If it is necessary to rewrite the PCM(ECM) to learn a new key, the dealer needs the customer's vehicle, all its keys and the GDS equipped with an immobilizer program card. Any key that is not learned during rewriting will no longer start the engine.

G. The immobilizer system can store up to eight key codes.


H. If the customer has lost his key, and cannot start the engine, contact Hyundai motor service station.

**Components Operations**

**PCM (Power Train Control Module)**

1. The PCM(ECM) (A) carries out a check of the ignition key using a special encryption algorithm, which is programmed into the transponder as well as the PCM(ECM) simultaneously. Only if the results are equal, the engine can be started. The data of all transponders, which are valid for the vehicle, are stored in the PCM(ECM).

ERN (Encrypted Random Number) value between EMS and encrypted smartra unit is checked and the validity of coded key is decided by EMS.



**Technical Service Bulletins**

- All New Technical Service Bulletins
- All Technical Service Bulletins
- Customer Interest Bulletins
- General Information Bulletins
- Repair Tips

**Testing and Inspection**

- Component Tests and General Diagnostics

Type here to search

11:37 AM 3/29/2023

Immobilizer System (Antitheft and Alarm Systems) - ALLDATA Repair

https://my.alldata.com/repair/#/repair/article/48554/component/612/itype/392/nonstandard/927444/selfRefLink/fa...

Center of Learning... ProDemand Autom... Direct-Hit -- Create... Amazon.com Shop... Thank12w - Free D... AESWAVE ACE Misfire Detecti... Other favorites


2011 Hyundai Sonata L4-2.4L Community 96

**ENCRYPTED SMARTRA unit (A)**

The SMARTRA carries out communication with the built-in transponder in the ignition key. This wireless communication runs on RF (Radio frequency of 125 kHz). The SMARTRA is mounted behind of the crash pad close to center cross bar.

The RF signal from the transponder, received by the antenna coil, is converted into messages for serial communication by the SMARTRA device. And, the received messages from the PCM(ECM) are converted into an RF signal, which is transmitted to the transponder by the antenna.

The SMARTRA does not carry out the validity check of the transponder or the calculation of encryption algorithm. This device is only an advanced interface, which converts the RF data flow of the transponder into serial communication to the PCM(ECM) and vice versa.



Open In New Tab Zoom/Print

Type here to search

11:39 AM 3/29/2023

Immobilizer System (Antitheft and Alarm Systems) - ALLDATA Repair

https://my.alldata.com/repair/#/repair/article/48554/component/612/itype/392/nonstandard/927444/selfRefLink/fa...


Center of Learning... ProDemand Autom... Direct-Hit -- Create... Amazon.com Shop... Thank12w - Free D... AESWAVE ACE Misfire Detecti... Other favorites

2011 Hyundai Sonata L4-2.4L Community 96

Open In New Tab Zoom/Print

**TRANSPONDER (Built-in keys)**

The transponder (A) has an advanced encryption algorithm. During the key teaching procedure, the transponder will be programmed with vehicle specific data. The vehicle specific data are written into the transponder memory. The write procedure is once only; therefore, the contents of the transponder can never be modified or changed.



Open In New Tab Zoom/Print

Antenna coil

Type here to search

11:40 AM 3/29/2023

Immobilizer System (Antitheft and Alarm Systems) - ALLDATA Repair

https://my.alldata.com/repair/#/repair/article/48554/component/612/itype/392/nonstandard/927444/selfRefLink/fa...

Center of Learning... ProDemand Autom... Direct-Hit -- Create... Amazon.com Shop... Thank12w - Free D... AESWAVE ACE Misfire Detecti... Other favorites

### 2011 Hyundai Sonata L4-2.4L


Community 96

#### Antenna coil

The antenna coil (A) has the following functions:

- The antenna coil supplies energy to the transponder.
- The antenna coil receives signal from the transponder.
- The antenna coil sends transponder signal to the SMARTRA.

It is located directly in front of the steering handle lock.



Open In New Tab Zoom/Print

Type here to search

11:42 AM 3/29/2023

# Verify the Concern

## A Case Study

## 2012 Ford Explorer – 2.0 Liter Ecoboost





**TST Seminars**  
Professional Training for Automotive Experts


### Observations Noted

- The vehicle owner complains that there is a ‘ “Check Engine Light” On. The vehicle appears to have intermittent misfire activity.
- The shop has replaced the coil no. 4. But, the engine continues to misfire intermittently on that cylinder.
- An attempt must be made to confirm the customers concern.

**TST Seminars**  
Professional Training for Automotive Experts







### 2012 MY(Model Year) Ford Vehicle Diagnostic Report

Tel: (773) 865-4414  
 Address: 1818 W 87th St  
 Creation Date: 2022-12-30

Scan type: Pre-scan  
 Scanner: Autel MaxiSys  
 Version Number: V4.60  
 License Plate: CZ54850  
 Manufacturer: Ford  
 Year: 2012 MY(Model Year)  
 Model: Explorer  
 Sub Model: 2.0L/EcoBoost - Gas Turbocharged Direct Injection  
 Engine:  
 Path: Ford>Automatic selection>Pre-Scan


Repair order: CZ54820  
 Serial Number: V1DGL8V01716  
 Technician: kenneth zanders  
 Client: Ernesto Customer  
 Phone Number:  
 VIN: 1FMHK7D9XCGA08645  
 Mileage: 110591.30 km  
 Color:  
 Status: 0


---

#### Insurance Information

Insured name:  
 Contact Information:  
 Insurance company:  
 Address:  
 Primary impact:


Claim number:  
 City state zip:





### CZ54820\_Ford\_Explorer\_2012 MY(Model Year).pdf

System	Status
1. PCM (Powertrain Control Module)	Fault   4
2. TCM (Transmission Control Module)	Pass   No fault
3. ABS (Anti-lock Brake System)	Fault   1
4. RCM (Restraint Control Module)	Fault   2
5. OCSM (Occupant Classification System Module)	Pass   No fault
6. IPC (Instrument Panel Control Module)	Pass   No fault
7. ACM (Audio Control Module)	Pass   No fault
8. APIM (Accessory Protocol Interface Module)	Fault   1
9. BdyCM(Body control module)	Fault   3
10. FCIM (Front Controls Interface Module)	Pass   No fault



CZ54820\_Ford\_Explorer\_2012 MY(Model Year).pdf

DTC


1. PCM (Powertrain Control Module)( 4 DTCs )



Codes	Description	Status
P0304:00-E8	Cylinder 4 Misfire Detected	CMDTCs
P0316:00-68	Misfire Detected On Startup (First 1000 Revolutions)	CMDTCs
P0420:00-EC	Catalyst System Efficiency Below Threshold (Bank 1)	CMDTCs
P128A:00-68	Cylinder Head Temperature Sensor Circuit Intermittent/Erratic	CMDTCs

2. ABS (Anti-lock Brake System)( 1 DTC )

Codes	Description	Status
U3003:16-60	Battery Voltage	CMDTCs

3. RCM (Restraint Control Module)( 2 DTCs )





Home - Autel x ALLDATA | OEM Repair x Technical Training x 2012 Explorer x

fordtechservice.dealerconnection.com

2012 Explorer  
1FMHK7D9XCGA08645

FORD FLEET

Help  
Logout

Home Vehicle ID Diagnostics TSB/GSB/SSM Workshop Wiring PC/ED Service Tips Owner Info PDI SLTS

Back

Report a Problem

## GENERAL SERVICE BULLETIN

### Various Vehicles - Catalytic Converter Concern Analysis

22-7  
18 January


**Summary**

This article is to alert dealers to investigate and understand contributors of catalyst efficiency diagnostic trouble codes (DTCs) P0420 and/or P043 that may be caused by base engine or other powertrain system concerns. Installation of a new catalyst without addressing root cause of the failure result in a repeat repair. Ford has observed the honeycomb substrate within the catalyst is melted or damaged on some returned parts due to excess heat exposure.


**Service Information**



Catalysts with heat damage or a melted condition are shown in Figures 1-3. Figure 4 shows a non-damaged honeycomb condition.



Figure 1 – Melted honeycomb (cannot be causal part)





© Copyright 2000, 2001-2022, Ford Motor Company. All rights reserved. Privacy Contact Us US- USA- FLEET-EN-US













## Conclusion

- The **sparkplugs** have become a forgotten part of the ignition system.
- The suggested maintenance schedule still **applies to all modern day vehicles**
- The **quick fix** is not the way to go on modern day automotive products.



# Verify the VIN Information

## A Case Study



### Observations Noted

- This vehicle has been **involved in a fire**. The vehicle was declared a total loss by the owners insurance company.
- A **local shop** decides that they may be able to bring this vehicle back to life.
- The shop performs a **harness and PCM replacement**. The vehicle cranks, but will not start.



Vehicle Information - 2018 Chevrolet Malibu L4-1.5L Turbo - ALLDATA Repair

https://my.alldata.com/repair/#/repair/vehicle/57732

Center of Learning... Thank12w - Free D... ProDemand Autom... Direct-Hit -- Create... Amazon.com Shop... AESWAVE ACE Misfire Detecti... Other favorites

**ALLDATA Repair** Diagnostic Hotline MARSHALL Help & Feedback

Change Vehicle Bookmarks Library Request Conversion Calculator Technician's Reference - Repair Search vehicle information

**2018 Chevrolet Malibu L4-1.5L Turbo** 1G1ZB5ST4JF104066 Community 17

POPULAR INFORMATION	SYSTEMS & COMPONENTS	INFORMATION
<ul style="list-style-type: none"> <li>Diagnostic Trouble Codes</li> <li>Service Tables</li> <li>TSBs</li> <li>Diagrams</li> <li>Specifications</li> <li>Parts and Labor</li> <li>Maintenance</li> </ul>	<ul style="list-style-type: none"> <li>Accessories and Optional Equipment</li> <li>ALL Diagnostic Trouble Codes (DTC)</li> <li>Body and Frame</li> <li>Brakes and Traction Control</li> <li>Cruise Control</li> <li>Electric Drive Systems</li> <li>Engine, Cooling and Exhaust               <ul style="list-style-type: none"> <li>Cooling System</li> <li>Engine</li> <li>Exhaust System</li> </ul> </li> <li>Heating and Air Conditioning</li> <li>Hybrid Drive Systems</li> <li>Instrument Panel, Gauges and Warning Indicators</li> <li>Lighting and Horns</li> <li>Maintenance</li> <li>Power and Ground Distribution</li> <li>Powertrain Management</li> <li>Relays and Modules</li> <li>Restraints and Safety Systems</li> <li>Sensors and Switches</li> <li>Starting and Charging</li> <li>Steering and Suspension</li> </ul>	<ul style="list-style-type: none"> <li>ALLDATA Reference</li> <li>ADAS Quick Reference</li> <li>Application and ID Components</li> <li>Description and Operation Components</li> <li>Locations Components               <ul style="list-style-type: none"> <li>Fuse and Fusible Links</li> <li>Grounds</li> <li>Harness</li> </ul> </li> <li>Service and Repair Procedures</li> <li>Service Precautions</li> <li>Technician Safety Information</li> <li>Testing and Inspection               <ul style="list-style-type: none"> <li>Initial Inspection and Diagnostic Overview</li> <li>Programming and Defining</li> </ul> </li> </ul>

Type here to search 10:16 AM 3/25/2023

gm-powertrain-lfv-engine-features-specifications.pdf

C:\Users\User\OneDrive\Desktop\gm-powertrain-lfv-engine-features-specifications.pdf

Center of Learning... Thank12w - Free D... ProDemand Autom... Direct-Hit -- Create... Amazon.com Shop... AESWAVE ACE Misfire Detecti... Other favorites


Draw Read aloud 1 of 2

**gm POWERED SOLUTIONS**

**1.5L I-4 TURBO, LFB**

**TURBO POWER QUIETLY REFINED**

The Ecotec 1.5L Turbocharged LFB engine is based on GM's small-engine modular architecture encompassing performance and efficiency. It offers 163 horsepower (122kW) with an impressive 184 lb-ft (250 Nm) of torque. In addition to performance, GM Engineers targeted every aspect of the architecture, reciprocating components, fuel system and engine management functions in the quest for smoothness and quietness.



1.5L Turbo LFB automotive engine shown

**STATE-OF-THE-ART TECHNOLOGIES**

**Lightweight, High-Pressure Casted Aluminum Cylinder Block**

- High-pressure casting produces a more dimensionally accurate block requiring fewer machining operations than conventional sand cast blocks

**ADDITIONAL FEATURES**

- Variable valve timing
- Low friction, PVD coated piston rings

Type here to search 1:38 PM 3/25/2023

## 1.5-liter Ecotec four-cylinder (LFV)

- Steve Kiefer, GM's vice president of global powertrain, explained that the company currently sees **11 variants** of this engine hitting the market by 2017, in 27 models, spread throughout five brands. Fully deployed, GM expects to build about 2.5 million of the engines in five GM plants around the world.



**TST Seminars**  
Professional Training for Automotive Experts



























# 2017 Chev Malibu

## Actual Vehicle Scan

**TST Seminars**  
Professional Training for Automotive Experts

The screenshot displays the ALLDATA Repair website interface. The browser address bar shows the URL: <https://my.alldata.com/repair/#/repair/vehicle/56869>. The page title is "Vehicle Information - 2017 Chevrolet Malibu L4-1.5L Turbo - ALLDATA Repair".

The main navigation bar includes the ALLDATA Repair logo, a Diagnostic Hotline icon, a user profile for MARSHALL, and links for Help & Feedback. Below this is a secondary navigation bar with links: Change Vehicle, Bookmarks, Library Request, Conversion Calculator, and Technician's Reference - Repair. A search bar for "Search vehicle information" is also present.

The vehicle information section displays "2017 Chevrolet Malibu L4-1.5L Turbo" with the VIN "1G1ZB5ST1HF120378". A "Community" link with a count of 28 is visible.

The content is organized into three columns:

- POPULAR INFORMATION:**
  - D diagnostic Trouble Codes
  - Service Tables
  - TSBs
  - Diagrams
  - Specifications
  - Parts and Labor
  - Maintenance
- SYSTEMS & COMPONENTS:**
  - Accessories and Optional Equipment
  - ALL Diagnostic Trouble Codes ( DTC )
  - Body and Frame
  - Brakes and Traction Control
  - Cruise Control
  - Electric Drive Systems
  - Engine, Cooling and Exhaust
    - Cooling System
    - Engine
    - Exhaust System
  - Heating and Air Conditioning
  - High Voltage System Disable / Enable, Hybrid
  - Hybrid Drive Systems
  - Instrument Panel, Gauges and Warning Indicators
  - Lighting and Horns
  - Maintenance
  - Power and Ground Distribution
  - Powertrain Management
  - Relays and Modules
  - Restraints and Safety Systems
  - Sensors and Switches
  - Starting and Charging
- INFORMATION:**
  - ALLDATA Reference
  - ADAS Quick Reference
  - Application and ID Components
  - Description and Operation Components
  - Locations Components
  - Fuse and Fusible Links
  - Grounds
  - Harness
  - Service and Repair Procedures
  - Removal and Replacement
  - Service Precautions
  - Technician Safety Information
  - Testing and Inspection
  - Initial Inspection and Diagnostic Overview

The Windows taskbar at the bottom shows the time as 10:12 AM on 3/25/2023, with various application icons including Edge, File Explorer, and several utility programs.

Techline Connect S(pom.version) Production

**gm**

**CHEVROLET**

**2017 MALIBU LS**  
 Color: NIGHTFALL GRAY METALLIC  
 Build Date: 2016-09-10  
 Delivery Date: 2017-01-03

**Vehicle Information**

Branded Title: No Warranty Block: No

**Open Field Actions**

Number	Status	Description	Type	SPS2
N192210570	O Open - Incomplete	Center High Mount Stop Lamp Water Leak	ZSPP	NA
N182188250	O Open - Incomplete	Loss of Continuity within Accelerator Pedal Position Sensor Circuit	ZSPP	NA

**Service Information**

Date	Number	Description	Type
Vehicle has no service information record			

**Warranty** **Service History**

Description	Start Date	End Date	Start Odometer	End Odometer
Special Coverage N192210570	2017-01-03	2023-01-03	34 M	72034 M
Special Coverage N182188250	2017-01-03	2027-01-03	34 M	150034 M
Emission Select Component Ltd Wty	2017-01-03	2025-01-03	34 M	80034 M

Type here to search

12:45 PM 3/14/2023

Techline Connect S(pom.version) Production

**gm**

**DTC**

**GDS2 DTC Check**

DTC run ended time: Mar 14, 2023 12:46:58 PM

Run DTCs Clear DTCs

K20	K71	K17	K177	K43	K9	K56	K36	K85	P16	A22	A26
K157	K26	A11	T3	K74	K82	K73	K33	K40D	K84	B218L	B218R
K182	K60	B233B									

**DTC Information**

Type	DTC	DTC Desc	Module Code	Module Desc	Status	Symptom Byte
	P06D2	5V Reference 5 Circuit	K20	Engine Control Mod...	Passed...	00
	P2230	Barometric Pressure (BARO) Sensor Circuit Erratic	K20	Engine Control Mod...	Passed...	00
	C056E	Electronic Control Unit Software	K43	Power Steering Cont...	Current	47
	P0449	Evaporative Emission (EVAP) Vent Solenoid Valve Control Circuit	K20	Engine Control Mod...	Current	00
	P0498	Evaporative Emission (EVAP) Vent Solenoid Valve Control Circuit Low Volt...	K20	Engine Control Mod...	Current	00
	P0463	Fuel Level Sensor Circuit High Voltage	K20	Engine Control Mod...	Current	00
	P018C	Fuel Pressure Sensor Circuit Low Voltage	K20	Engine Control Mod...	Current	00
	P0232	Fuel Pump Control Circuit High Voltage	K20	Engine Control Mod...	Current	00

**Vehicle Configuration**

Property	Value	Value Source	Select
Automatic Transmission Tune	Automatic Transmission 5-Speed (4MNU) - BPO		

Type here to search

12:47 PM 3/14/2023

Technline Connect S(pom.version) Production

Service Information

Document ID: 5622590

### #N182188250-02: Special Coverage Adjustment - Loss of Continuity within Accelerator Pedal Position Sensor Circuit - (Jun 19, 2020)

Subject: N182188250 — Loss of Continuity within Accelerator Pedal Position Sensor Circuit

Models: 2017–2018 Buick LaCrosse  
2018 Buick Regal  
2016–2018 Chevrolet Malibu

Release Date: August 2019      Revision: 02

Revision Description: The Parts Table was updated. Please discard all previous copies of bulletin N182188250.

Attention: This Special Coverage can be seen in the Applicable Warranties section in Investigate Vehicle History (IVH).

Make	Model	Model Year		RPO	Description
		From	To		
Buick	LaCrosse	2017	2018		
Buick	Regal	2018	2018		
Chevrolet	Malibu	2016	2018		

Involved vehicles are identified on the Applicable Warranties section in GM Global Warranty Management system. This site should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs.

© 2023 General Motors. All rights reserved.

Technline Connect S(pom.version) Production

Service Information

Document ID: 5622590

### #N182188250-02: Special Coverage Adjustment - Loss of Continuity within Accelerator Pedal Position Sensor Circuit - (Jun 19, 2020)

Involved vehicles are identified on the Applicable Warranties section in GM Global Warranty Management system. This site should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs.

<b>Condition:</b>	Certain 2016–2018 model year Chevrolet Malibu, 2017–2018 model year Buick LaCrosse, and 2018 model year Buick Regal vehicles may have a condition which affects the electrical connection to one of the vehicle's accelerator pedal position sensors. If this electrical connection is interrupted, the accelerator pedal will still function, but the vehicle will enter a reduced engine power mode in which the vehicle's maximum acceleration and torque are reduced. Additionally, the Malfunction Indicator Light (Check Engine Light) will illuminate, the 'Engine Power is Reduced' message will display, and a diagnostic trouble code for Accelerator Pedal Position Sensor Correlation (P2138) will be set when this condition occurs.
<b>Special Coverage Adjustment</b>	<p>This special coverage covers the condition described above for a period of 10 years or 150,000 miles (240,000 km), whichever occurs first, from the date the vehicle was originally placed in service, regardless of ownership.</p> <p>For vehicles covered by Vehicle Service Contracts, all eligible claims with repair orders on or after August 15, 2019, are covered by this special coverage and must be submitted using the labor operation codes provided with this bulletin. Claims with repair orders prior to August 15, 2019, must be submitted to the Service Contract provider.</p> <p>Vehicle owners or lessees who paid for repairs referenced in this Special Coverage ("Customers") are eligible for reimbursement of their reasonable and customary expenses in accordance with the procedures specified below. The conditional right to reimbursement is provided by GM solely in the interest of customer satisfaction and is personal to Customers. <i>Customers may not assign and GM does not consent to any assignment of any Customer's right to submit reimbursement claims, or to receive reimbursement, or any other rights granted by this Special Coverage to any third party, including but not limited to service contract providers, and this Special Coverage is not intended to and does not confer any third party beneficiary, subrogation or contribution rights, or any other rights to reimbursement, against GM, whether in law, equity or otherwise, on any third parties.</i></p>
<b>Correction</b>	Dealers are to replace the accelerator pedal and position sensor assembly as necessary and repair the engine wire harness (Malibu LFV only). The repairs will be made at no charge to the customer.

[Parts Information](#)

Quantity	Part Name	Part No.
© 2023 General Motors. All rights reserved.		

Technline Connect S(pom.version) Production

**2017 MALIBU LS**  
Color: NIGHTFALL GRAY METALLIC

**Vehicle Selection: Select Vehicle**

**Disconnect Vehicle**

**Manual Vehicle Selection**

Input VIN:

Year:

Make:

Model:

Current SI Region: North America

**Recent Vehicles**

- 1G1ZB5ST1HF120378**  
2017 • Chevrolet • Malibu  
3/14/23 12:47 PM
- 2GNAXSEV4L6158098**  
2020 • Chevrolet • Equinox  
3/4/23 11:07 AM
- 2GNALBEC8B1151144**  
2011 • Chevrolet • Equinox  
2/16/23 3:18 PM
- 3GSCL33P98S649738**  
2008 • Saturn • VUE - FWD  
12/11/22 1:12 PM

**Select**

**Run DTCs** **Clear DTCs**

**Vehicle Information**

Branded Title: No

**Open Field Action**

Number	Status
N192210...	O Op
N182188...	O Op

**Service Information**

Date	Num
2017-01-03	72034 M
2027-01-03	150034 M

**Warranty Service**

**Close Vehicle Session**

**Vehicle Configuration**

Property	Value	Value Source	Select
Automatic Transmission Type	Automatic Transmission	PPG	

12:49 PM 3/14/2023

Technline Connect S(pom.version) Production

**Service Information**

**2017 Chevrolet Malibu (1G1ZB5ST1HF120378)** Malibu Service Manual Israel, N America 9460077

Basic Search [Search By Phrase]

Search documents matching all of these keywords:  Search Reset

[Fastener Specifications](#) [RPO Code List](#) [Maintenance Items](#) [Master Electrical Component List](#) [Diagnostic Starting Point](#) [Diagnostic Trouble Code List](#) [Symptom List](#) [Control Module References](#)



Select a Service Category Type:

- Bulletins By Category
- View All Bulletins
- Campaigns
- Preliminary Information
- Preface
- General Information
- Body Hardware and Trim
- Body Repair
- Body Systems
- Brakes
- Diagnostic Overview, Starting Point, and Programming
- Driveline/Axle
- Driver Information and Entertainment
- Engine/Propulsion
- HVAC
- Power and Signal Distribution
- Roof
- Safety and Security
- Seats
- Steering
- Suspension
- Transmission

© 2023 General Motors. All rights reserved.

1:25 PM 3/14/2023





## Conclusion

- The VIN mismatch is a **serious flaw**. There were 11 different variants of this engine family introduced by 2017.
- There was a **considerate amount** of work completed by the repairing shop.
- The **quick fix** is not the way to go on modern day automotive products.



## Check for Codes/TSB's Search

A Case Study



## Observations Noted

- This vehicle was received from another repairing shop, the shop has replaced the following items: Fuel Injector and MAF sensor.
- The shop owner is requesting a diagnosis be performed.
- Once code information was obtained, a code review and TSB search was performed.



## 2017 Pathfinder

Code P219F stored in memory –Air Fuel Ratio Imbalance  
(Cylinder No 4)



## Possible Causes

- Fuel injector
- Exhaust gas leaks
- Incorrect fuel pressure
- Mass air flow sensor
- Intake air leaks
- Lack of fuel



## Possible Causes

- Incorrect PCV hose connection
- Improper spark plug
- Insufficient compression
- The fuel injector circuit is open or shorted
- ignition coil
- The ignition signal circuit is open or shorted

**TST Seminars**  
Professional Training for Automotive Experts

The screenshot shows a web browser window with the address bar displaying a URL from my.alldata.com. The page title is "2017-2018 PATHFINDER; MIL ON WITH DTC P219F". The page content includes the following text:

**APPLIED VEHICLES:** 2017-2018 Pathfinder (R52)  
**APPLIED ENGINE:** VQ35DD (direct injection)


**IF YOU CONFIRM**

The MIL is ON with DTC P219F (AIR-FUEL RATIO IMBALANCE [CYLINDER 4]) stored,

And

There are no drivability issues.

The browser's taskbar at the bottom shows the time as 9:48 AM on 3/25/2023.



# Perform Visual Checks

## 2017 Hyundai Santa Fe – 3.3 Liter Engine




**TST Seminars**  
Professional Training for Automotive Experts

### Customer Concern

- Customer was driving his vehicle and the engine stalled
- The vehicle was towed in and it was determined that the Intake Cam Phaser on Bank 2 came apart
- The engine was reassembled and a code P0019 was stored in memory. (Crank-Cam Correlation)
- The first plan of attack was to locate the PCM



**TST Seminars**  
Professional Training for Automotive Experts



Engine Control System (G6DH : LAMBDA II 3.3L GDI) (1)

SD313-1

## PCM Terminal Information




## E100-A

PIN	COLOR	DESCRIPTION	PIN	COLOR	DESCRIPTION	PIN	COLOR	DESCRIPTION
1	-	-	35	O	C-CAN (Low)	68	-	-
2	-	-	36	-	-	70	B	RPM Signal
3	-	-	37	P	Rail Pressure Sensor (Ground)	71	Gr	C/Fan Relay Control
4	-	-	38	Gr	APS 1 Signal	72	O	Alternator (COM)
5	B	Ground	39	-	-	73	-	-
6	B	Ground	40	-	-	74	R	MMIO Data Line
7	-	-	41	-	-	75	P	Engine Control Relay ON Input
8	-	-	42	-	-	76	-	-
9	W	CCP-CAN (High)	43	G/B	Brake Light Switch	77	L	Memory Power
10	G	C-CAN (High)	44	G/B	[A/T]PositionSwitch (S1)	78	-	-
11	G	FTPS Signal	45	Br	[A/T]PositionSwitch (S2)	79	W	[A/T] Select Switch
12	-	-	46	G	[A/T]PositionSwitch (S3)	80	B	Ground
13	-	-	47	Gr	[A/T]PositionSwitch (S4)	81	-	-
14	Br	APS 1 Power	48	-	-	82	-	-
15	P	APT/RPS Power	49	-	-	83	-	-
16	O	Fuel Level Sensor	50	-	-	84	-	-
17	-	-	51	-	-	85	-	-
18	-	-	52	R	Memory Power	86	-	-
19	-	-	53	-	-	87	W	Lift Diagnostic Data Line
20	-	-	54	-	[A/T] Down Shift	88	-	-
21	Br	Brake TEST Switch	55	B	Ground	89	-	-
22	-	-	56	-	-	90	R	APS 2 Power
23	W	Alternator (FB)	57	G/B	F/Pump Relay Control (IVO/MMO)	91	-	-
24	-	-	58	-	-	92	-	-
25	-	-	59	B/O	APS 2 Ground	93	B	Start Relay
26	-	-	60	B	APS 1 Ground	94	Gr	Engine Control Relay Control
27	P	ON/START Input	61	Br	FTPS Ground	95	G/B	F/Pump Relay Control (IVB/MMO)
28	W	Rail Pressure Sensor (Signal)	62	-	-	96	Gr	COV
29	Gr	[A/T] Up Shift	63	B	APT Ground	97	-	-
30	B	Ground	64	-	-	98	-	-
31	-	-	65	L	FTPS Power	99	O	Engine Control Relay ON Input
32	-	-	66	-	-	100	P	Engine Control Relay ON Input
33	-	-	67	G	APT Signal	-	-	-
34	Br	CCP-CAN (Low)	68	P	APS 2 Signal	-	-	-

\* [A/T] : See Automatic Transaxle Control System (SD450)

## C100-B

PIN	COLOR	DESCRIPTION	PIN	COLOR	DESCRIPTION	PIN	COLOR	DESCRIPTION
1	Y	[A/T]O2_VFS	35	Gr	ECTS Signal	68	O	VIV 2 Control
2	-	-	36	-	-	70	R	CMP5 Bank #1(EX) Signal
3	Gr	[A/T]Input Speed Signal	37	-	-	71	G	CMP5 Bank #1(IN) Signal
4	G	[A/T]Output Speed Signal	38	Gr	Oxygen Sensor #1 (Hi)	72	-	-
5	P	CMP5 Bank #1(IN/EX) Power	39	G	Oxygen Sensor #1 (LO)	73	P	CMP5 Bank #2(IN/EX) Power
6	Gr	TPS Power	40	B	Shield Ground	74	Y	Ignition Coil #5 Control
7	-	-	41	Y	Knock Sensor #1 (LO)	75	-	-
8	P	Start Switch	42	P	Knock Sensor #1 (LO)	76	G	[A/T]Solenoid Power 1
9	O	BPS Signal	43	G	CXPS LO	77	O	[A/T]Solenoid Power 2
10	W	Oil Temp. Sensor Signal	44	Br	CMP5 Bank #2(IN/EX) Ground	78	Gr	[A/T]O2_VFS
11	-	-	45	-	-	79	-	-
12	G	TPS 1 Signal	46	G	CMP5 Bank #2(EX) Signal	80	W/B	ETC Motor (Hi)
13	Y	MAP Sensor Signal	47	-	-	81	L	ETC Motor (LO)
14	W	Intake Air Temp. Sensor	48	P	MAP/BPS Power	82	P	Oxygen Sensor #3 Heater
15	W/B	Vehicle Speed Input	49	B	Ignition Coil #3 Control	83	P/B	Oxygen Sensor #4 Heater
16	Gr	Knock Sensor #2 (Hi)	50	-	-	84	Gr	PPRV Control
17	O	Knock Sensor #1 (Hi)	51	Y/B	[A/T]LINE_VFS	85	G/B	Injector #2 Control
18	W	CXPS Hi	52	P	[A/T]UD_VFS	86	O	Injector #5 Control
19	B	Oil Temp. Sensor Ground	53	R	[A/T]SS_B	87	Y	Injector #3 Control
20	-	-	54	W/B	[A/T]Output Speed Power	88	O	Injector #4 Control
21	Gr	CMP5 Bank #2(IN) Signal	55	W	[A/T]Oil Temp. Sensor (+)	89	R	Injector #4 Control
22	L	Wiper Motor Input	56	B	MAP/ECTS-BPS Ground	90	B	Injector #1 Control
23	-	-	57	L/B	[A/T]Oil Temp. Sensor (-)	91	P	Oxygen Sensor #1 Heater
24	W	Ignition Coil #1 Control	58	Gr	Oxygen Sensor #4 (Hi)	92	P/B	Oxygen Sensor #2 Heater
25	-	-	59	W	Oxygen Sensor #3 (Hi)	93	G	CVT (EX) - Bank 2
26	Br	[A/T]ICCN_VFS	60	Br	Oxygen Sensor #3 (LO)	94	L/B	CVT (EX) - Bank 1
27	G	[A/T]SSR_VFS	61	-	-	95	W	CVT (IN) - Bank 2
28	O	[A/T]SS_A	62	-	-	96	L	CVT (IN) - Bank 1
29	L	[A/T]Input Speed Power	63	G/B	Oxygen Sensor #2 (Hi)	97	G	Ignition Coil #2 Control
30	-	-	64	W	Oxygen Sensor #2 (LO)	98	L	Ignition Coil #5 Control
31	Br	TPS Ground	65	O	VIV 1 Control	99	R	Ignition Coil #4 Control
32	B	CMP5 Bank #1(IN/EX) Ground	66	G	PCSV Control	100	-	-
33	Br	Oxygen Sensor #4 (LO)	67	-	-	-	-	-
34	W	TPS 2 Signal	68	-	-	-	-	-



PIN	COLOR	DESCRIPTION	PIN	COLOR	DESCRIPTION	PIN	COLOR	DESCRIPTION
1	Y	[A/T]OD_VFS	35	Gr	ECTS Signal	69	O	VIV. 2 Control
2	-	-	36	-	-	70	R	CMPS Bank #1(EX) Signal
3	Gr	[A/T]Input Speed Signal	37	-	-	71	G	CMPS Bank #1(IN) Signal
4	G	[A/T]Output Speed Signal	38	Gr	Oxygen Sensor #1 (HI)	72	-	-
5	P	CMPS Bank #1/2(IN EX) Power	39	G	Oxygen Sensor #1 (LO)	73	P	CMPS Bank #2/1(IN EX) Power
6	Gr	TPS Power	40	B	Shield Ground	74	Y	Ignition Coil #5 Control
7	-	-	41	Y	Knock Sensor #2 (LO)	75	-	-
8	P	Start Switch	42	P	Knock Sensor #1 (LO)	76	G	[A/T]Solenoid Power 1
9	O	BPS Signal	43	G	CKPS LO	77	O	[A/T]Solenoid Power 2
10	W	Oil Temp. Sensor Signal	44	Br	CMPS Bank #2/1(IN EX) Ground	78	Gr	[A/T]26B_VFS
11	-	-	45	-	-	79	-	-
12	G	TPS.1 Signal	46	G	CMPS Bank #2(EX) Signal	80	W/B	ETC Motor (HI)
13	Y	MAP Sensor Signal	47	-	-	81	L	ETC Motor (LO)
14	W	Intake Air Temp. Sensor	48	P	MAP/BPS Power	82	P	Oxygen Sensor #3 Heater
15	W/B	Vehicle Speed Input	49	B	Ignition Coil #3 Control	83	P/B	Oxygen Sensor #4 Heater
16	Gr	Knock Sensor #2 (HI)	50	-	-	84	Gr	FPRV Control
17	O	Knock Sensor #1 (HI)	51	Y/B	[A/T]LINE_VFS	85	Gr/B	Injector #2 Control
18	W	CKPS HI	52	P	[A/T]UD_VFS	86	O	Injector #5 Control
19	B	Oil Temp. Sensor Ground	53	R	[A/T]SS_B	87	Y	Injector #3 Control
20	-	-	54	W/B	[A/T]Output Speed Power	88	G	Injector #6 Control
21	Gr	CMPS Bank #2(IN) Signal	55	W	[A/T]Oil Temp. Sensor (+)	89	R	Injector #4 Control
22	L	Wiper Motor Input	56	B	MAP/ECTS/BPS Ground	90	B	Injector #1 Control
23	-	-	57	L/B	[A/T]Oil Temp. Sensor (-)	91	P	Oxygen Sensor #1 Heater
24	W	Ignition Coil #1 Control	58	Gr	Oxygen Sensor #4 (HI)	92	P/B	Oxygen Sensor #2 Heater
25	-	-	59	W	Oxygen Sensor #3 (HI)	93	G	CVVT (EX) - Bank 2
26	Br	[A/T]T/CON_VFS	60	Br	Oxygen Sensor #3 (LO)	94	L/B	CVVT (EX) - Bank 1
27	G	[A/T]3SR_VFS	61	-	-	95	W	CVVT (IN) - Bank 2
28	O	[A/T]SS_A	62	-	-	96	L	CVVT (IN) - Bank 1
29	L	[A/T]Input Speed Power	63	G/B	Oxygen Sensor #2 (HI)	97	G	Ignition Coil #2 Control
30	-	-	64	W	Oxygen Sensor #2 (LO)	98	L	Ignition Coil #6 Control
31	Br	TPS Ground	65	O	VIV. 1 Control	99	R	Ignition Coil #4 Control
32	B	CMPS Bank #1/2(IN EX) Ground	66	G	PCSV Control	100	-	-
33	Br	Oxygen Sensor #4 (LO)	67	-	-			
34	W	TPS. 2 Signal	68	-	-			

Oil Control Valves



## VVT Testing

### 1. Scan Tool:

- Read codes
  - P0019 stored in memory
- Determine how cam position is displayed
  - Cam Position cannot be determined based on scantool information
- Solenoid/actuator duty cycle commands
  - Brake torque performed; duty cycle was noted to always be at zero degrees

## VVT Testing

### 1. Scan Tool:

- Error pids
  - No error pid information is shown
- Desired position pids
  - Desired position pids always show zero degrees (maybe due to the P0019 code that has set)
- Check for bi-directional capability
  - There appears to be no bi-directional capability due to the P0019 code that has set

Hyundai  
V4.00

Hyundai > Automatic selection > Control unit > ENG (Engine) > Trouble codes

VCMS 14.4V

ECU information

**Trouble codes**

Live data

Active test

Special function

DTC	Status	Description	Intelligent diagnostics
<u>P0019</u>	Pending	Crankshaft position (CKP) - Camshaft position (CMP) correlation (Bank 2 sensor B (exhaust))	

Hyundai  
V4.00

Hyundai > Automatic selection > Control unit > ENG (Engine) > Trouble codes

VCMS 14.5V

ECU information

**Trouble codes**

Live data

Active test

Special function


DTC	Status	Description	Intelligent diagnostics
<u>P0019</u>	Active	Crankshaft position (CKP) - Camshaft position (CMP) correlation (Bank 2 sensor B (exhaust))	

### DTC Description


PCM monitors timing misalignment while no active faults are present with fully warmed up engine oil at idle. If the timing is misaligned PCM determines that a fault exists and a P0019 DTC is stored.

### DTC Detecting Condition

Item		Detecting Condition	Possible Cause
DTC Strategy		<ul style="list-style-type: none"> <li>Determines if CAM target is aligned correctly to crankshaft</li> </ul>	<div style="border: 2px solid red; padding: 5px;">           1. loosened CKPS            2. Timing Misalignment         </div>
Enable Conditions		<ul style="list-style-type: none"> <li>No active faults</li> <li>Fully warmed up at idle</li> </ul>	
Threshold value	Case 1	1 tooth misalignment at greater than 80 °C(176 °F) and less than 90 °C(194°F) of engine oil temperature.	
	Case 2	2 tooth misalignment at lower than 80 °C(176 °F) or higher than 90 °C(194°F) of engine oil temperature.	
Diagnosis Time		<ul style="list-style-type: none"> <li>Continuous (Within 1min.)</li> </ul>	
MIL On Condition		<ul style="list-style-type: none"> <li>2 Drive Cycles</li> </ul>	



https://my.alldata.com/repair/#/repair/vehicle/56389/component/1/ftype/100/tsbs/20191008115736250/selfRefLink/true



## HYUNDAI

### Technical Service Bulletin

GROUP	ENGINE	NUMBER
DATE	October, 2019	MODEL(S)
		MULTIPLE MODELS

**SUBJECT:** LAMBDA ENGINE TIMING CHAIN AND CRANKSHAFT SPROCKET PARTS INFORMATION

**Description:** This bulletin provides information regarding the changes in the timing chain and the crankshaft sprockets on certain Azera (HG), Santa Fe/Santa Fe XL (NC), Genesis (BH/DH), Genesis Coupe (BK), and G90 (HI) vehicles equipped with Lambda 3.3L / 3.8L GDI engines.

**Applicable Vehicles:**

- 2012-17 MY Azera (HG)
- 2013-18 MY Santa Fe and 2019MY Santa Fe XL (NC)
- 2012-14 MY Genesis (BH) with 3.8L GDI engine
- 2015-16 MY Genesis (DH) with 3.8L GDI engine
- 2013-16 MY Genesis Coupe (BK) with 3.8L GDI engine


**Parts Information:**

https://my.alldata.com/repair/#/repair/vehicle/56389/component/1/ftype/100/tsbs/20191008115736250/selfRefLink/true

**Applicable Vehicles:**

- 2012-17 MY Azera (HG)
- 2013-18 MY Santa Fe and 2019MY Santa Fe XL (NC)
- 2012-14 MY Genesis (BH) with 3.8L GDI engine
- 2015-16 MY Genesis (DH) with 3.8L GDI engine
- 2013-16 MY Genesis Coupe (BK) with 3.8L GDI engine


**Parts Information:**



Crankshaft sprocket has a total of 19 teeth

Part Name	OLD	NEW	Remarks
Timing Chain	24312-3CGA2	<b>24312-3L100</b>	(Timing Chain: QTY 2 required)
Crankshaft	23121-3CGA3 (LH)	<b>23121-3L100 (LH)</b>	(Crankshaft Sprocket: Both LH and RH required) NEW and OLD part numbers cannot be

https://my.alldata.com/repair/#/repair/vehicle/56389/component/1/type/100/tsbs/20191008115736250/selfRefLink/true




A: Timing Chain		B: Crankshaft Sprocket		C: Tooth root diameter of crankshaft sprocket
Part Name	OLD	NEW	Remarks	
Timing Chain	24312-3CGA2	24312-3L100	(Timing Chain: QTY 2 required)	
Crankshaft Sprocket	23121-3CGA3 (LH)	23121-3L100 (LH)	(Crankshaft Sprocket: Both LH and RH required) NEW and OLD part numbers cannot be interchanged.	
	23122-3CGA1 (RH)	23122-3L100 (RH)		

**NOTICE**


Whenever a replacement Short Engine Assembly is being installed or if any Timing Chains and/or Crankshaft Sprockets require replacement, install all NEW corresponding part numbers listed above as a set.



NEW and OLD parts should never be interchanged due to the different tooth root diameter of the LH/RH Crankshaft Sprockets and the corresponding Timing Chain.


Circulate To: General Manager, Service Manager, Parts Manager, Warranty Manager, Service











Scan Data

Hyundai V4.00

Hyundai > Automatic selection > Control unit > ENG (Engine) > Live data

VCMI 14.6V

ECU information

Trouble codes

Live data

Active test

Special function

Vehicle running at Idle

Name	Value	Unit
[002]Actual engine speed	1176	RPM
[003]Target idle rpm	1180	RPM
[064]Camshaft control condition	Off	
[125]Exhaust camshaft desired position (Bank 1)	0.02	°
[126]Exhaust camshaft actual position (Bank 1)	-0.1	°
[127]Exhaust camshaft desired position (Bank 2)	0.02	°
[128]Exhaust camshaft actual position (Bank 2)	0.02	°
[129]Exhaust camshaft phaser 1 duty cycle	0	%
[130]Exhaust camshaft phaser 2 duty cycle	0	%

Cancel All Show all Graph merge To top Setting Clear data Freeze Record Review Back

VCMI 95% 12:42

Hyundai V4.00

Hyundai > Automatic selection > Control unit > ENG (Engine) > Live data

VCMI 14.5V

ECU information

Trouble codes

Live data

Active test

Special function

Vehicle acceleration of 49.71 MPH

Name	Value	Unit
[002]Actual engine speed	1418	RPM
[019]Vehicle speed	49.71	mph
[064]Camshaft control condition	Off	
[125]Exhaust camshaft desired position (Bank 1)	0.02	°
[126]Exhaust camshaft actual position (Bank 1)	0.09	°
[127]Exhaust camshaft desired position (Bank 2)	0.02	°
[128]Exhaust camshaft actual position (Bank 2)	0.02	°

Cancel All Show all Graph merge To top Setting Clear data Freeze Record Review Back

VCMI 67% 15:21

Hyundai V4.00

Hyundai > Automatic selection > Control unit > ENG (Engine) > Live data

VCMI 14.5V

ECU information

Trouble codes

**Live data**

Active test

Special function

Vehicle acceleration of 51.26 MPH

Name	Value	Unit
[002]Actual engine speed	1462	RPM
[019]Vehicle speed	51.26	mph
[064]Camshaft control condition	Off	
[125]Exhaust camshaft desired position (Bank 1)	0.02	°
[126]Exhaust camshaft actual position (Bank 1)	0.33	°
[127]Exhaust camshaft desired position (Bank 2)	0.02	°
[128]Exhaust camshaft actual position (Bank 2)	0.02	°

Cancel All Show all Graph merge To top Setting Clear data Freeze Record Review Back

VCMI

67% 15:21

# Labscope



## VVT Testing


### 1. LabScope:

- Perform a Relative Compression Test
  - Test Results: Good
- Perform a Cranking Vacuum Test
  - Test Results: Slight deviation noted in pattern
- Perform an In Cylinder Test
  - Test Results: Slight deviation noted in pattern





## Relative Compression Test and Vacuum Waveform Analysis








Ignition Coil  
No. 6 was used  
as a Synch  
Pin No 98 at  
PCM















## VVT Testing

### 2. Scope In Cylinder:



- Perform cranking and running compression checks
  - Cam Timing appears to be Off
- Determine true TDC of crank sensor signal (Shown Later)
- Determine crank sensor reluctor "degrees per tooth" (Shown Later)















## VVT Testing

### 3. Scope Crank Cam Synch:

- #1 coil vs crank sensor vs cam sensor (s)
  - Cam and Crank sensor were evaluated
- check crank to cam for proper relationship, to determine belt or chain alignment and stretch
  - There appears to be a Cam Sensor Issue


**TST Seminars**  
Professional Training for Automotive Experts

## VVT Testing

### 3. Scope Crank Cam Synch:


- Determine crank sensor reluctor “degrees per tooth”
  - The crankshaft sensor signal has a 60-2 design. You would divide 360 degrees/60 teeth = 6 crank degrees per pulse.

**TST Seminars**  
Professional Training for Automotive Experts








Camshaft  
Position Sensor  
Intake 1 and 2  
Pins 21 and 71





## Notes from Hyundai

- Normal waveform of CKPS & CMPS at idle.
- Our example shows a typical Crankshaft Position Sensor (CKPS) and Camshaft Position Sensor (CMPS) waveform at idle. If the 17th signal of the CKPS after missing tooth of the target wheel is aligned with the high signal of the CMPS at idle, PCM recognizes that Synchronization between CKPS and CMPS is completed.






## Camshaft Position Sensor - Intake










## Camshaft Position Sensor - Exhaust


Notes: The valve cover was damaged as a result of the Intake cam phasor coming apart. The valve cover included a new exhaust cam sensor






## Calculations

- The crankshaft pulley has 19 teeth in total. You would divide 360 degrees/19 teeth = 19 degrees of crankshaft rotation per tooth.



## Calculations

- The crankshaft sensor signal has a 60-2 design. You would divide 360 degrees/60 teeth = 6 crank degrees per pulse.





**TST Seminars**  
Professional Training for Automotive Experts

## Calculations

- If the processor (PCM) thinks the we are 3 pulses off, this would equate to 18 crank degrees. The PCM will set a Code P0019

1 crank  
tooth =  
19 crank  
degrees



3 pulses =  
18 crank  
degrees


**TST Seminars**  
Professional Training for Automotive Experts



### ■ Timing Mark Inspection

1. IG "OFF". Check the timing mark is correctly aligned.

Reference :



2. Is the timing mark correctly aligned?

**YES**

► Fault is intermittent. Drive the vehicle to meet the enable condition for the DTC, and go to "Verification of Vehicle Repair" procedure.

**NO**

► Repair or replace as necessary and then, go to "Verification of Vehicle Repair" procedure.

Parts and Labor (Camshaft Position Sensor) - ALLDATA Repair

https://my.alldata.com/repair/#/repair/article/56389/component/226/itype/189/nonstandard//selfRefLink/false

Center of Learning... ProDemand Autom... Direct-Hit -- Create... Amazon.com Shop... Thank12w - Free D... AESWAVE ACE Misfire Detecti... Other favorites

**ALLDATA Repair** Diagnostic Hotline MARSHALL Help & Feedback

Change Vehicle Bookmarks Library Request Conversion Calculator Technician's Reference - Repair Search vehicle information

2017 Hyundai Truck Santa Fe FWD V6-3.3L Community 1

## Parts and Labor

Vehicle > Powertrain Management > Sensors and Switches - Powertrain Management > Sensors and Switches - Computers and Control Systems > Camshaft Position Sensor > Parts and Labor

PARTS AND LABOR			
Parts	OEM PART #	PRICE	
Powertrain Control			
Camshaft Position Sensor	393183C500	120.95	
Labor	SKILL	WARRANTY	STANDARD
Remove & Replace			
Powertrain Control			
Camshaft Position Sensor, R&R	B	0.3	0.4

**RELATED INFORMATION**


- Description and Operation Components
- Diagrams Electrical (OE)
- Parts and Labor Camshaft Position Sensor
- Service and Repair Procedures
- Specifications Electrical

Type here to search

3:45 PM 3/27/2023

## Camshaft Position Sensors

**Black Top with Grey Body**



This was the sensor that was sent per the dealer with the new valve cover assembly

**Grey Top with Black Body**



This is the sensor that should have been sent

## Part No. 393183C510 vs 393183C500



https://www.parts Hyundai.com/oem-parts/hyundai-engine-camshaft-position-sensor-393183c510

PARTS HYUNDAI.COM

Home Track Order Contact Us My Account

No Vehicle Selected

Part Number(s), Keywords, or VIN

Home > HYUNDAI 39318-3C510

**Engine Camshaft Position Sensor - Hyundai (39318-3C510)**  
2017-2019 Hyundai

MSRP: [Redacted]  
Discount: [Redacted]  
Sale Price: [Redacted]

Make sure this part fits your car >

ADD TO CART

Manufacturer Warranty  
Minimum of 12 Months

Guaranteed Fitment  
Always the correct parts

Shop with Confidence  
Your information is safe

In-House Experts  
We know our products

DETAILS VEHICLE FITMENT

Genuine: [Hyundai Logo]  
SKU: 39318-3C510  
Positions: Left

Feedback

Type here to search

48°F 5:24 AM 10/28/2021

- Black Top with Grey Body
- There is no direct reference to this sensor in Service Information??

https://www.parts Hyundai.com/oem-parts/hyundai-camshaft-position-sensor-393183c500

PARTS HYUNDAI.COM

Home Track Order Contact Us My Account

No Vehicle Selected

Part Number(s), Keywords, or VIN

Home > HYUNDAI 39318-3C500

**Camshaft Position Sensor - Hyundai (39318-3C500)**  
2012-2019 Hyundai

MSRP: [Redacted]  
Discount: [Redacted]  
Sale Price: [Redacted]

Make sure this part fits your car >

ADD TO CART

Manufacturer Warranty  
Minimum of 12 Months

Guaranteed Fitment  
Always the correct parts

Shop with Confidence  
Your information is safe

In-House Experts  
We know our products

DETAILS VEHICLE FITMENT


Genuine: [Hyundai Logo]  
SKU: 39318-3C500  
Positions: Right Left

Feedback

Type here to search

48°F 8:26 PM 10/27/2021


- Grey Top with Black Body
- A direct reference to this sensor is in Service Information







# Final Analysis




# Relative Compression Test and Vacuum Waveform Analysis











# Crank and Cam Signals









# Scan Data

Hyundai V4.00							
Hyundai > Automatic selection > Control unit > ENG (Engine) > Live data				VCN  14.3V			
ECU information Trouble codes <b>Live data</b> Active test Special function	Name  7 items selected			Value	Unit		
	<input checked="" type="checkbox"/>	[064]Camshaft control condition		Off			
	<input checked="" type="checkbox"/>	[125]Exhaust camshaft desired position (Bank 1)		0.02	°		
	<input checked="" type="checkbox"/>	[126]Exhaust camshaft actual position (Bank 1)		-0.16	°		
	<input checked="" type="checkbox"/>	[127]Exhaust camshaft desired position (Bank 2)		0.02	°		
	<input checked="" type="checkbox"/>	[128]Exhaust camshaft actual position (Bank 2)		0.02	°		
	<input checked="" type="checkbox"/>	[129]Exhaust camshaft phaser 1 duty cycle		0	%		
	<input checked="" type="checkbox"/>	[130]Exhaust camshaft phaser 2 duty cycle		0	%		

Hyundai  
V4.00

Hyundai > Automatic selection > Control unit > ENG (Engine) > Live data

VCMS 14.3V

ECU information

Trouble codes

**Live data**

Active test

Special function

Name	Value	Unit
<input checked="" type="checkbox"/> [064]Camshaft control condition	On	
<input checked="" type="checkbox"/> [125]Exhaust camshaft desired position (Bank 1)	-6.71	°
<input checked="" type="checkbox"/> [126]Exhaust camshaft actual position (Bank 1)	-6.21	°
<input checked="" type="checkbox"/> [127]Exhaust camshaft desired position (Bank 2)	-6.71	°
<input checked="" type="checkbox"/> [128]Exhaust camshaft actual position (Bank 2)	-7.21	°
<input checked="" type="checkbox"/> [129]Exhaust camshaft phaser 1 duty cycle	46.27	%
<input checked="" type="checkbox"/> [130]Exhaust camshaft phaser 2 duty cycle	47.84	%

Hyundai  
V4.00

Hyundai > Automatic selection > Control unit > ENG (Engine) > Live data

VCMS 14.3V

ECU information

Trouble codes

**Live data**

Active test

Special function

Name	Value	Unit
<input checked="" type="checkbox"/> [064]Camshaft control condition	Off	
<input checked="" type="checkbox"/> [117]Intake camshaft desired position (Bank 1)	0.02	°
<input checked="" type="checkbox"/> [118]Intake camshaft actual position (Bank 1)	0.01	°
<input checked="" type="checkbox"/> [119]Intake camshaft desired position (Bank 2)	0.02	°
<input checked="" type="checkbox"/> [120]Intake camshaft actual position (Bank 2)	-0.19	°
<input checked="" type="checkbox"/> [121]Intake camshaft phaser 1 duty cycle	0	%
<input checked="" type="checkbox"/> [122]Intake camshaft phaser 2 duty cycle	0	%





# Engine Mechanical Analysis

using the 4 stroke cycle

## 2016 Dodge Durango

Loud Tapping Noise  
(Obvious)

## Observations Noted

- The misfire monitor on the vehicle has been suspended.
- There are **no misfire codes** stored in the controllers memory (PCM).
- There is an audible tapping noise coming from the engine. It is not clear which **side of the engine** it is coming from.




## Description and Operation




## Description and Operation

- The 3.6 liter (219.7 CID) flexible fuel V-6 engine features Variable Valve Timing (VVT), Dual Overhead Camshafts (DOHC) and a high-pressure die-cast aluminum cylinder block with steel liners in a 60° configuration.



If the engine has experienced a catastrophic failure, THE INTAKE MANIFOLD MUST BE REPLACED!





## Description and Operation

- The 3.6 liter engine has a chain driven variable discharge [oil pump](#) with a two-stage pressure regulator for improved fuel economy. The [exhaust manifold](#)s are integrated into the [cylinder heads](#) for reduced weight.

## Description and Operation

- The cylinders are numbered from front to rear. The **right bank is numbered 1, 3, 5** and the **left bank is numbered 2, 4, 6**. The firing order is **1-2-3-4-5-6**. The engine serial number is located on the left side of the cylinder block at the transmission flange.

**TST Seminars**  
Professional Training for Automotive Experts

Service Library

https://library.fcaservices.com/web/secure/disciplines?config-level=YEAR\_MODEL\_ENGINE&config-id=0998d01a-b096-11...

Center of Learning... Thank12w - Free D... ProDemand Autom... Direct-Hit -- Create... Amazon.com Shop... AESWAVE ACE Misfire Detecti... Other favorites

SERVICE LIBRARY Enter VIN → Start Chat Support Hub Kenneth Zanders

2015 WD - DODGE DURAN... 3.6L V6 V.V.T. Search misfire

S1309000016 - Ticking/Tapping Noise From Upper Engine Ar... FEEDBACK

**STAR Case**

**Service & Parts**  
MOPAR. STICK WITH THE SPECIALISTS®  
RAM DODGE CHRYSLER Jeep

**Case Number:** S1309000016

**Release Date:** 03/18/2014

**Symptom/Vehicle Issue:** Ticking/Tapping Noise from Upper Engine Area with Possible Misfire DTCs

Type here to search 2:01 PM 3/24/2023

Service Library

https://library.fcaservices.com/web/secure/disciplines?config-level=YEAR\_MODEL\_ENGINE&config-id=0998d01a-b096-11...

Center of Learning... Thank12w - Free D... ProDemand Autom... Direct-Hit -- Create... Amazon.com Shop... AESWAVE ACE Misfire Detecti... Other favorites

SERVICE LIBRARY Enter VIN Start Chat Support Hub Kenneth Zanders

2015 WD - DODGE DURAN... 3.6L V6 V.V.T. Search misfire


S1309000016 - Ticking/Tapping Noise From Upper Engine Ar...

**Symptom/Vehicle Issue:** Ticking/Tapping Noise from Upper Engine Area with Possible Misfire DTCs

**Diagnosis:** Remove components required to gain access for proper inspection of each rocker arm roller bearing for missing or worn needle bearings and damage to the corresponding cam lobe (Fig.1 & Fig.2). Please note that this condition is typically found on vehicles with mileage accumulation of 15K miles or more.

**NOTE:** This failure may also set the following DTCs for various cylinder misfire.

- P0300 Multiple Cylinder Misfire
- P0301-P0306 - #1 - #6 Misfire



Type here to search 2:17 PM 3/24/2023

Service Library


https://library.fcaservices.com/web/secure/disciplines?config-level=YEAR\_MODEL\_ENGINE&config-id=0998d01a-b096-11...

Center of Learning... Thank12w - Free D... ProDemand Autom... Direct-Hit -- Create... Amazon.com Shop... AESWAVE ACE Misfire Detecti... Other favorites


SERVICE LIBRARY Enter VIN Start Chat Support Hub Kenneth Zanders

2015 WD - DODGE DURAN... 3.6L V6 V.V.T. Search misfire

S1309000016 - Ticking/Tapping Noise From Upper Engine Ar...



(Fig.1)



(Fig.2)

Type here to search 2:34 PM 3/24/2023

Service Library

https://library.fcaservices.com/web/secure/disciplines?config-level=YEAR\_MODEL\_ENGINE&config-id=0998d01a-b096-11...


Center of Learning... Thank12w - Free D... ProDemand Autom... Direct-Hit -- Create... Amazon.com Shop... AESWAVE ACE Misfire Detecti... Other favorites

SERVICE LIBRARY Enter VIN → Start Chat Support Hub Kenneth Zanders

2015 WD - DODGE DURAN... 3.6L V6 V.V.T. Search misfire

S1309000016 - Ticking/Tapping Noise From Upper Engine Ar... FEEDBACK

(Fig.1)



(Fig.2)

Inspect the Hydraulic Lash Adjusters (HLA) for a collapsed condition.

[Contact the STAR Center for assistance if no solution is found](#)

Chrysler Group LLC Version 3

Type here to search 2:40 PM 3/24/2023

Service Library


https://library.fcaservices.com/web/secure/disciplines?config-level=YEAR\_MODEL\_ENGINE&config-id=0998d01a-b096-11...

Center of Learning... Thank12w - Free D... ProDemand Autom... Direct-Hit -- Create... Amazon.com Shop... AESWAVE ACE Misfire Detecti... Other favorites

SERVICE LIBRARY Enter VIN → Start Chat Support Hub Kenneth Zanders

2015 WD - DODGE DURAN... 3.6L V6 V.V.T. Search misfire

S1309000016 - Ticking/Tapping Noise From Upper Engine Ar... FEEDBACK



(Fig.3)

Type here to search 2:41 PM 3/24/2023



Service Library


https://library.fcaservices.com/web/secure/disciplines?config-level=YEAR\_MODEL\_ENGINE&config-id=0998d01a-b096-11...

Center of Learning... Thank12w - Free D... ProDemand Autom... Direct-Hit -- Create... Amazon.com Shop... AESWAVE ACE Misfire Detecti... Other favorites

SERVICE LIBRARY Enter VIN Start Chat Support Hub Kenneth Zanders

2015 WD - DODGE DURAN... 3.6L V6 V.V.T. Search misfire

S1309000016 - Ticking/Tapping Noise From Upper Engine Ar... FEEDBACK



(Fig.3)

**NOTE:** If the HLA feels spongy it does not need to be replaced. Replace only collapsed HLA as shown in Fig.3

Type here to search 2:42 PM 3/24/2023

Engine - Specifications (Engine) - ALLDATA Repair

https://my.alldata.com/repair/#/repair/article/54483/component/8/type/28/nonstandard/11214/selfRefLink/false

Center of Learning... Thank12w - Free D... ProDemand Autom... Direct-Hit -- Create... Amazon.com Shop... AESWAVE ACE Misfire Detecti... Yahoo | Mail, Weath... Other favorites

2015 Dodge or Ram Truck Durango 4WD V6-3.6L 1C4RDJDG9FC781987 Community 9

## ENGINE SPECIFICATIONS

### GENERAL SPECIFICATIONS

Description	Specification
Type	60° DOHC V-6 24-Valve
Compression Ratio	10.2:1
Lead Cylinder	#1 Right Bank
Firing Order	1-2-3-4-5-6

Description	Metric	Standard
Displacement	3.6 Liters	220 Cubic Inches
Bore and Stroke	96.0 x 83.0 mm	3.779 in. x 3.268 in.

Type here to search 5:19 PM 2/21/2023

Engine - Specifications (Engine) - ALLDATA Repair

https://my.alldata.com/repair/#/repair/article/54483/component/8/itype/28/nonstandard/11214/selfRefLink/false

Center of Learning... Thank12w - Free D... ProDemand Autom... Direct-Hit -- Create... Amazon.com Shop... AESWAVE ACE Misfire Detecti... Yahoo | Mail, Weath... Other favorites

2015 Dodge or Ram Truck Durango 4WD V6-3.6L 1C4RD Community 9

### VALVE TIMING-INTAKE VALVES

Description	Specification
Opens	2° (ATDC)
Closes	82° (ABDC) or 262° (ATDC)
Centerline	128°

Note: Units are in crank degrees, using 0.1524 mm (0.006 in.) valve lift as the threshold.

### VALVE TIMING-EXHAUST VALVES

Description	Specification
Opens	59° (BBDC) or 239° (BTDC)
Closes	12° (ATDC)
Valve Overlap	10°

Note: Units are in crank degrees, using 0.1524 mm (0.006 in.) valve lift as the threshold.



### CYLINDER HEAD



Description	Specification
	Metric Standard

Type here to search

3:55 PM 2/3/2023

# Cranking Vacuum Waveforms Intake Stroke







## Questions: Intake Stroke

➤ What cylinder(s) appears to be affected?

➤ \_\_\_\_\_



➤ Do we appear to have a mechanical issue?


➤ \_\_\_\_\_



## Relative Compression Test Compression Stroke







## Questions: Compression Stroke

➤ What cylinder(s) appears to be affected?

➤ \_\_\_\_\_

➤ Do we appear to have a mechanical issue?


➤ \_\_\_\_\_

➤ What cylinder was affected on the Intake Stroke?



➤ \_\_\_\_\_

# Cranking Exhaust Waveforms

## Exhaust Stroke







## Questions: Exhaust Stroke

➤ What cylinder(s) appears to be affected?

➤ \_\_\_\_\_

➤ Do we appear to have a mechanical issue?



➤ \_\_\_\_\_

➤ What cylinder was affected on the Compression Stroke?



➤ \_\_\_\_\_



Running Exhaust Waveforms  
Exhaust Stroke









## Questions: Exhaust Stroke

➤ What cylinder(s) appears to be affected?

➤ \_\_\_\_\_

➤ Do we appear to have a mechanical issue?

➤ \_\_\_\_\_

➤ What cylinder was affected on the cranking Exhaust Stroke?

➤ \_\_\_\_\_



In Cylinder Analysis  
Cylinder No 2

Engine - Specifications (Engine) - ALLDATA Repair

https://my.alldata.com/repair/#/repair/article/54483/component/8/itype/28/nonstandard/11214/selfRefLink/false

Center of Learning... Thank12w - Free D... ProDemand Autom... Direct-Hit -- Create... Amazon.com Shop... AESWAVE ACE Misfire Detecti... Yahoo | Mail, Weath... Other favorites

2015 Dodge or Ram Truck Durango 4WD V6-3.6L 1C4RD Community 9

### VALVE TIMING-INTAKE VALVES

Description	Specification
Opens	2° (ATDC)
Closes	82° (ABDC) or 262° (ATDC)
Centerline	128°

Note: Units are in crank degrees, using 0.1524 mm (0.006 in.) valve lift as the threshold.


### VALVE TIMING-EXHAUST VALVES



Description	Specification
Opens	59° (BBDC) or 239° (BTDC)
Closes	12° (ATDC)
Valve Overlap	10°


Note: Units are in crank degrees, using 0.1524 mm (0.006 in.) valve lift as the threshold.

### CYLINDER HEAD



Description	Specification
	Metric Standard




















## Conclusion

- The vehicle was repaired successfully and the misfire monitor has been reinstated.
- There are no misfire codes stored in the controllers memory (PCM) per a test drive.
- The vehicle appears to be working as designed.

# Test Procedures

## Case Study No 2



# 2016 Dodge Caravan


## Appears to Run Extremely Quiet (Not So Obvious)




## Observations Noted

- The misfire monitor on this vehicle has recorded a **1 trip Failure**
- There is a **P0306** stored in the controllers memory(PCM).
- The vehicle appears to run quiet and it has been recorded that **minor cylinder misfire activity** has been noted.

Check VIN Information




# Verify Customers Concern




**Perform Visual Checks**







# Check for Codes/TSB's



Download free automotive diag... x My Apps Dashboard | fcawitech x wiTECH

app.am.fcawitech.com/wt2/index.html#/vehicle/action-items/dtcs

Capital One 360 - L... Arm Training: 5 Wa... The Ultimate Arm... Triceps Lying Tricep Extenti... Pump Up Your Bice... Arm Training: Build... Omertà - Wikipedia...

GLENPARKAUTO@GMAIL.COM

2C4RDGBG5GR122576

### Action Items

Topology All DTCs All Flashes Recalls RSUs Misc Functions System Tests

Status: All Clear All DTCs View Freeze Frame View Event Data DTC Data

ECU	CODE	DESCRIPTION	STATUS
ABS	C0021-02	Brake Booster-General Signal Failure	Stored
PCM	P0306	Cylinder 6 Misfire	Stored
PCM	P0222	Throttle Position Sensor 2 Circuit Low	Stored
PCM	P0123	Throttle Position Sensor 1 Circuit High	Stored
PCM	P0108	Manifold Absolute Pressure Sensor Circuit High	Stored

List updates as DTCs are set or cleared.

12:54 PM 3/6/2023

Download free automotive diag... x My Apps Dashboard | fcawitech x wiTECH

app.am.fcawitech.com/wt2/index.html#/vehicle/ecu/16/dataList

Capital One 360 - L... Arm Training: 5 Wa... The Ultimate Arm... Triceps Lying Tricep Extenti... Pump Up Your Bice... Arm Training: Build... Omertà - Wikipedia...

GLENPARKAUTO@GMAIL.COM

2016 DODGE CARAVAN 3.6L V6 V.V.T.  
2C4RDGBG5GR122576

14.10 Volts

### PCM

Powertrain Control Module

Flash DTCs Data Misc Functions System Tests Actuators Details Configuration


Type: All Record Units: Imperial Filter Graph Data Clear 0.75 s Search

Ungrouped Data 264 items

NAME	VALUE	UNIT	TYPE
------	-------	------	------

12:57 PM 3/6/2023

# Review Scan Data



The screenshot shows a web browser window with the URL `app.am.fcawitech.com/wt2/index.html#/vehicle/ecu/16/dataList`. The page displays a table of scan data. A red dashed box highlights the first three rows of the table, which are:

Parameter Name	Value	Units	Sensor Type
Injector Pulse Width Cylinder 1	1920	US	Sensors
Injector Pulse Width Cylinder 2	2000	US	Sensors
Injector Pulse Width Cylinder 3	1928	US	Sensors

The table continues with the following rows:

Injector Pulse Width Cylinder 4	1984	US	Sensors
Injector Pulse Width Cylinder 5	1888	US	Sensors
Injector Pulse Width Cylinder 6	1720	US	Sensors
Cranking Injector Pulse Width	8648	US	Sensors

The browser's taskbar at the bottom shows the time as 12:57 PM on 3/6/2023.



Download free automotive diag... My Apps Dashboard | fcawitech x wiTECH

app.am.fcawitech.com/wt2/index.html#/vehicle/ecu/16/dataList

GLENPARKAUTO@GMAIL.COM

Cooled EGR volts	0.0000	volts	Sensors	
Injector Pulse Width Cylinder 1	1920	US	Sensors	
Injector Pulse Width Cylinder 2	2000	US	Sensors	
Injector Pulse Width Cylinder 3	1928	US	Sensors	
Injector Pulse Width Cylinder 4	1984	US	Sensors	
Injector Pulse Width Cylinder 5	1888	US	Sensors	
Injector Pulse Width Cylinder 6	1720	US	Sensors	
Cranking Injector Pulse Width	8648	US	Sensors	
1/1 O2 Sensor Level: High			Sensors	

12:57 PM 3/6/2023

Download free automotive diag... My Apps Dashboard | fcawitech x wiTECH

app.am.fcawitech.com/wt2/index.html#/vehicle/ecu/16/dataList

GLENPARKAUTO@GMAIL.COM

























2/2 O2 Heater Temp	1248.80	°F	Sensors	
1/1 Short Term ADAP	-1.8	%	Sensors	
2/1 Short Term ADAP	-1.2	%	Sensors	
1/1 Long Term ADAP	0.8	%	Sensors	
2/1 Long Term ADAP	-2.0	%	Sensors	
Closed Loop Timer	0.0	seconds	Sensors	
Current ADAP Cell ID	24		Sensors	
Ethanol Percent	0.0	%	Sensors	
FFV ETHANOL	0	Counts	Sensors	

12:58 PM 3/6/2023

Download free automotive diag... x My Apps Dashboard | fcawitech x wiTECH

app.am.fcawitech.com/wt2/index.html#/vehicle/ecu/16/dataList

GLENPARKAUTO@GMAIL.COM

























Cam Sync State	In Sync	Sensors	  
Crank Signal Missing	False	Sensors	  
Crank Sync State	In Sync	Sensors	  
Crank System Fault and in Limp-Home mode.	False	Sensors	  
Exhaust Cam 1 / Crank Difference	-5.1	EngineDeg Sensors	  
Exhaust Cam 2 / Crank Difference	0.6	EngineDeg Sensors	  
Intake Cam 1 / Crank Difference	-4.1	EngineDeg Sensors	  
Intake Cam 2 / Crank Difference	-0.9	EngineDeg Sensors	  

1:00 PM 3/6/2023

Download free automotive diag... x My Apps Dashboard | fcawitech x wiTECH

app.am.fcawitech.com/wt2/index.html#/vehicle/ecu/16/dataList

GLENPARKAUTO@GMAIL.COM

Cam Sync State	In Sync	Sensors	  
Crank Signal Missing	False	Sensors	  
Crank Sync State	In Sync	Sensors	  
Crank System Fault and in Limp-Home mode.	False	Sensors	  
Exhaust Cam 1 / Crank Difference	-5.1	EngineDeg Sensors	  
Exhaust Cam 2 / Crank Difference	0.6	EngineDeg Sensors	  
Intake Cam 1 / Crank Difference	-4.1	EngineDeg Sensors	  
Intake Cam 2 / Crank Difference	-0.9	EngineDeg Sensors	  

























1:00 PM 3/6/2023

Download free automotive diag... x My Apps Dashboard | fcawitech x wiTECH

app.am.fcawitech.com/wt2/index.html#/vehicle/ecu/16/dataList

Capital One 360 - L... Arm Training: 5 Wa... The Ultimate Arm... Triceps Lying Tricep Extenti... Pump Up Your Bice... Arm Training: Build... Omertà - Wikipedia...

GLENPARKAUTO@GMAIL.COM

Exhaust Cam 1 Desired Position	115.0	EngineDeg	Sensors	  
Exhaust Cam 1 Actual Position	115.2	EngineDeg	Sensors	  
Exhaust Cam 2 Duty Cycle	0.0000	%DC	Sensors	  
Exhaust Cam 2 Desired Position	115.8	EngineDeg	Sensors	  
Exhaust Cam 2 Actual Position	115.7	EngineDeg	Sensors	  
Intake Cam 1 Duty Cycle	0.0000	%DC	Sensors	  
Intake Cam 1 Desired Position	129.3	EngineDeg	Sensors	  
Intake Cam 1 Actual	128.8	EngineDeg	Sensors	  

1:01 PM 3/6/2023

Service Library

https://library.fcaservices.com/web/secure/disciplines?config-level=YEAR\_MODEL\_ENGINE&config-id=8c3477e5-450e-11e... A...

Center of Learning... Thank12w - Free D... ProDemand Autom... Direct-Hit -- Create... Amazon.com Shop... AESWAVE ACE Misfire Detecti... Other favorites

SERVICE LIBRARY Enter VIN → Start Chat Support Hub Kenneth Zanders

2016 RT - CHRYSLER TOW... 3.6L V6 V.V.T. Search misfire

S1609000004 - Customer complaint is that the vehicle has a ... FEEDBACK

**FCA** | **CHRYSLER** | **DODGE** | **FIAT** | **Jeep** | **RAM** | **MOPAR**

**STAR Case**

**Case Number: S1609000004**

**Release Date: 02/05/2016**

**Symptom/Vehicle Issue:** Customer complaint is that the vehicle has a misfire, may or may not have a DTC set for misfire. P0301, P0302, P0303, P0304, P0305, P0306.

**Discussion:** Once the vehicle has been inspected and it has been confirmed that there is a misfire condition. Perform the normal misfire diagnostics, compression test, leak down test, and swap the plug, coil and injectors. If all the tests are within specifications, and the plug, coil and injector swap did not change anything replace the lash adjuster and roller finger follower before removing the head.

Type here to search 1:14 PM 3/24/2023

## Diagnostic Process

- The STAR Case supports the replacement of the lash adjuster and roller finger follower.
- This vehicle is under a **used car warranty**, the shop has suggested an Engine Replacement.
- I have advised the shop that a **mechanical analysis** should be performed.


## Tests Performed



- **Cranking Vacuum Test**
- **Running Vacuum Test**
- **Relative Compression Test**
- **Running Exhaust Waveform Test**




# Cranking Vacuum Waveforms



## Intake Stroke









## Running Vacuum Waveforms Intake Stroke










# Relative Compression Test



## Compression Stroke

**TST Seminars**  
Professional Training for Automotive Experts



















## Running Exhaust Waveforms Exhaust Stroke








## Cylinder No 4

(Known Good)










# Cylinder No 6


(Suspect Cylinder)











# Test Procedures

## Case Study No 3

# A Tale of Two Batteries



Thank You for Attending

But Wait, There is More!

## Customer Concern

- The Check Engine Light is on.
- The technician does a code clear and takes the vehicle for a test drive. It is then noted that during a Start/Stop event that the check engine light illuminates again
- A code **P305F** is stored in the controllers (PCM) memory.



## Code P305F

Dual Battery Control Module Performance





## Diagnostic Process

- Step 1: Obtain **Trouble Code** Information
- Step 2: Determine the **RPO code** for the start/stop system you are working on (GM)
- Step 3: Review **Description and Operation**
- Step 4: Review **any and all TSB's** that may apply
- Step 5: Review **Wiring Diagrams** and **Trouble Code Chart**



## Obtain Trouble Code Information



Technline Connect 5(pom.version) Production

GDS2

DTC Display

Create Report Add Bookmark

Status	Control Module Name	Control Module Status	DTC Count	DLC Pin
⚠	Engine Control Module	DTCs Stored	1	6,14

Control Module	Type	DTC	Symptom...	Description	Symptom Description	Status
Engine Control Module		P305F	00	Dual Battery Control Module Performance	...	Current

**DBCM = Dual Battery Control Module**

Category	Decoded Value
This Ignition Cycle	Not Run
Last Test	Failed Current DTC
Since DTC Clear	Failed


Clear DTCs Refresh

Back Home Vehicle Menu Enter

GDS 2 v.22.3.02900 GM Global v.2022.12.0 VIN: 2G11Z55L3F9168124 2015,Chevrolet,Impala,1,Module Diagnostics,Engine Control Module,Dagnostic Trouble Codes ... MDI: 22009314 12.3 V

Type here to search S&P 500 +1.67% 10:29 AM 1/6/2023

# Determine the RPO Code(s)



## Description and Operartion

The screenshot shows a web browser window with the URL <https://my.alldata.com/repair/#/repair/article/54597/component/1240/itype/392/nonstandard/11203/selfRefLink/false>. The page is titled "2015 Chevrolet Impala L4-2.5L" and "Stop/Start System (w/ KL9) Description and Operation". The document ID is 3469162. The text describes the Stop/Start System's function to improve fuel efficiency by shutting off the engine at traffic lights and restarting it when the driver is ready to move. It also mentions the starter motor upgrade and the battery sensor module connected to the battery control module (BCM).

**Document ID: 3469162**

The Stop/Start System is used to improve fuel efficiency in stop/start driving. The vehicle automatically shuts off the engine in appropriate conditions, at a traffic light for example, resulting in zero tail pipe emissions and saving fuel which otherwise is used idling the engine when stationary. The engine restarts when the driver is ready to move away.

When the driver prepares to move away (by releasing the brake pedal and/or depressing the accelerator pedal), the engine will start; it takes approximately 400 ms for the engine to restart from the time the brake pedal transition initiates this activity.

To support the increased number of engine starts, the **starter motor** is upgraded with a high performance electric motor and a stronger pinion engagement mechanism with reduced noise levels.

There is a **battery sensor** module connected to the **battery** which continually monitors the battery charging current, and voltage. This module communicates to the body control module (BCM) via LIN serial data. The engine control module (ECM) receives the voltage and current information from the BCM via high speed serial data and this is used to determine if the battery state of charge (SOC) as calculated in the ECM by the Battery State Estimation (BSE) system, is sufficient to support a Stop/Start condition. The ECM has access to independent sensor systems to verify the information received from the battery sensor module via the BCM is

**RELATED INFORMATION**

- Description and Operation Components
- Exploded Parts Diagram Starting System
- Parts and Labor Starting System
- Technical Service Bulletins
  - All New Technical Service Bulletins
  - All Technical Service Bulletins By Symptom
  - General Information Bulletins
  - Recalls and Campaigns
- Testing and Inspection

# Dual Battery Control Module

## Dual Battery Control Module (DBCM)

The DBCM is used to isolate 12V primary battery from vehicle loads during cranking events. It switches primary and auxiliary batteries in and out at appropriate times to support vehicle loads and battery charging. It does not utilize vehicle bus communication. The following table defines the utilization of the primary and auxiliary batteries based on specified events.




# Dual Battery Control Module



Vehicle Load Supported by


Event	Primary Battery	Auxiliary Battery
Key off	Yes	No
Key on	Yes	Yes
*Key Crank	No	Yes
Run	Yes	Yes
Auto-stop	Yes	No
*Auto-start	No	Yes

\*During a Key Crank or Auto-start event, the primary battery supplies power to the Starter Motor.

Battery voltages should be monitored under actual driving conditions by using graphical analysis







**Auxiliary Battery is located in the trunk area on the drivers side of the vehicle.**

# Review Technical Service Bulletins

Diagnostic Tip for Malfunction Indicator Lamp (MIL) Illuminated with DTC P305F, P058B and/or P058D - ALLDATA Repair

https://my.alldata.com/repair/#/repair/vehicle/54597/component/1/itype/13/tsbs/20190502162413368/selfRefLink/false

Center of Learning... Thank12w - Free D... ProDemand Autom... Direct-Hit -- Create... Amazon.com Shop... AESWAVE ACE Misfire Detecti... Yahoo | Mail, Weath... Other favorites

**ALLDATA Repair** Diagnostic Hotline MARSHALL Help & Feedback

Change Vehicle Bookmarks Library Request Conversion Calculator Technician's Reference - Repair P305F

2015 Chevrolet Impala L4-2.5L Community 7

## Diagnostic Tip for Malfunction Indicator Lamp (MIL) Illuminated with DTC P305F, P058B and/or P058D

Vehicle > Diagnostic Tip for Malfunction Indicator Lamp (MIL) Illuminated with DTC P305F, P058B and/or P058D

**DIAGNOSTIC TIP FOR MALFUNCTION INDICATOR LAMP (MIL) ILLUMINATED WITH DTC P305F, P058B AND/OR P058D**

### #18-NA-367: Diagnostic Tip for Malfunction Indicator Lamp (MIL) Illuminated with DTC P305F, P058B and/or P058D - (May 1, 2019)

Subject: Diagnostic Tip for Malfunction Indicator Lamp (MIL) Illuminated with DTC P305F, P058B and/or P058D

This Bulletin replaces PIC6112 and PI1412A. Please discard PIC6112 and PI1412A.

Brand:	Model:	Model Year:	VIN:	Engine:	Transmission:

RELATED INFORMATION

- ALLDATA Reference
  - ADAS Quick Reference
- Application and ID
  - Components
- Description and Operation
  - Components
- Diagrams
  - Connector Views
  - Diagnostic Aids
  - Diagram Information and Instructions
- Locations
  - Components

Type here to search

1:07 PM 2/3/2023

Diagnostic Tip for Malfunction Indicator Lamp (MIL) Illuminated with DTC P305F, P058B and/or P058D - ALLDATA Repair

https://my.alldata.com/repair/#/repair/vehicle/54597/component/1/itype/13/tsbs/20190502162413368/selfRefLink/false

Center of Learning... Thank12w - Free D... ProDemand Autom... Direct-Hit -- Create... Amazon.com Shop... AESWAVE ACE Misfire Detecti... Yahoo | Mail, Weath... Other favorites

**ALLDATA Repair** Diagnostic Hotline MARSHALL Help & Feedback

Change Vehicle Bookmarks Library Request Conversion Calculator Technician's Reference - Repair P305F

2015 Chevrolet Impala L4-2.5L Community 7

This Bulletin replaces PIC6112 and PI1412A. Please discard PIC6112 and PI1412A.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Impala (VIN 1)	2014	2016				
	Malibu	2014	2015			2.5L (RPO LKW)	
	Malibu Limited (VIN 1)	2016	2016			2.5L (RPO LCV)	

Involved Region or Country	North America, Israel
Additional Options (RPOs)	Equipped with Engine Control, Stop-Start System (RPO KL9)
Condition	Some customers may comment that the Malfunction Indicator Lamp (MIL) is illuminated. Some technicians may find one or more of the following DTCs set, current or in history, in the Engine Control Module (ECM):

Diagrams
 

- Connector Views
- Diagnostic Aids
- Diagram Information and Instructions

Locations
 

- Components
- Fuse and Fusible Links
- Grounds
- Harness

Service and Repair
 

- Procedures
- Removal and Replacement

Service Precautions
 

- Technician Safety Information

Specifications
 

- Fluid Types and Capacities

Technical Service Bulletins
 

- All New Technical Service Bulletins
- All Technical Service Bulletins By Symptom
- Customer Interest Bulletins
- General Information Bulletins
- Recalls and Campaigns
- Denair Time

Type here to search

1:09 PM 2/3/2023



Diagnostic Tip for Malfunction Indicator Lamp (MIL) Illuminated with DTC P305F, P058B and/or P058D - ALLDATA Repair

https://my.alldata.com/repair/#/repair/vehicle/54597/component/1/itype/13/tsbs/20190502162413368/selfRefLink/false

Center of Learning... Thank12w - Free D... ProDemand Autom... Direct-Hit -- Create... Amazon.com Shop... AESWAVE ACE Misfire Detecti... Yahoo | Mail, Weath... Other favorites

### 2015 Chevrolet Impala L4-2.5L

Community 7

<b>Involved Region or Country</b>	North America, Israel
<b>Additional Options (RPOs)</b>	Equipped with Engine Control, Stop-Start System (RPO KL9)
<b>Condition</b>	Some customers may comment that the Malfunction Indicator Lamp (MIL) is illuminated. Some technicians may find one or more of the following DTCs set, current or in history, in the Engine Control Module (ECM): <ul style="list-style-type: none"> <li>P305F: Dual Battery Control Module Performance</li> <li>P058B: Battery Monitor Module Current Monitoring Performance</li> <li>P058D: Battery Monitor Module Voltage Monitoring Performance</li> </ul>
<b>Cause</b>	This condition may be caused by one or more of the following: <ul style="list-style-type: none"> <li>Loose ring terminal at negative battery terminal</li> <li>Fretting or corrosion on female terminal pins in 4 pin connector</li> <li>Loose splice in harness ground circuit</li> <li>Defective Battery Control Module</li> </ul>
<b>Correction</b>	If you encounter a vehicle with the above concern, prior to completing any repairs, perform the following Service Procedure steps:

**Service Procedure**  
Inspect the following if DTC P305F has been set:

**Specifications**  
Fluid Types and Capacities

**Technical Service Bulletins**  
All New Technical Service Bulletins  
All Technical Service Bulletins  
By Symptom  
Customer Interest Bulletins  
General Information Bulletins  
Recalls and Campaigns  
Repair Tips  
Software Update Bulletins  
Superseded Bulletins

**Testing and Inspection**  
Initial Inspection and Diagnostic Overview  
Programming and Relearning  
Symptom Related Diagnostic Procedures

**Tools and Equipment**  
Electrical / Mechanical Repair

Type here to search

1:10 PM 2/3/2023

Diagnostic Tip for Malfunction Indicator Lamp (MIL) Illuminated with DTC P305F, P058B and/or P058D - ALLDATA Repair


https://my.alldata.com/repair/#/repair/vehicle/54597/component/1/itype/13/tsbs/20190502162413368/selfRefLink/false

Center of Learning... Thank12w - Free D... ProDemand Autom... Direct-Hit -- Create... Amazon.com Shop... AESWAVE ACE Misfire Detecti... Yahoo | Mail, Weath... Other favorites

### 2015 Chevrolet Impala L4-2.5L

Community 7

Inspect the following if DTC P305F has been set:



Open In New Tab Zoom/Print

- Check state of health of auxiliary battery with the GR8 tester. Not just a state of charge check.
  - If low, replace the battery, clear codes and re-check.
  - If good, proceed to step 2.
- Check ground resistance from the Dual Battery Isolation Module (DBIM) to G103. Wiggle the harness (1) and negative battery terminal connections during test to look for varied resistance values.
  - If resistance is greater than 0.5 ohms, or changes more than 1 ohm, then inspect ground connections and/or splice in the harness about 1.5 ft. from the connector end.
    - Fix poor connections, clear codes and re-check.
  - If resistance is less than 0.5 ohms, proceed to step 3.
- Verify the engine harness is not pinched underneath the main battery tray (2).

Type here to search

1:12 PM 2/3/2023

Diagnostic Tip for Malfunction Indicator Lamp (MIL) Illuminated with DTC P305F, P0588 and/or P058D - ALLDATA Repair

https://my.alldata.com/repair/#/repair/vehicle/54597/component/1/itype/13/tsbs/20190502162413368/selfRefLink/false

Center of Learning... Thank12w - Free D... ProDemand Autom... Direct-Hit -- Create... Amazon.com Shop... AESWAVE ACE Misfire Detecti... Yahoo | Mail, Weath... Other favorites

### 2015 Chevrolet Impala L4-2.5L


Community 7

3. Verify the engine harness is not pinched underneath the main battery tray (2).

**Note:** The DBIM is located on the fuse block assembly. If found the cause of the concern, the Battery Distribution Fuse Block must be replaced.

4. Replace the battery distribution fuse block and wiring harness connector, clear codes and re-check.

Inspect the following if DTC P058B and/or P058D is set current or in history:



[Open in New Tab](#) [Zoom/Print](#)

1. Inspect the orientation of the grounding ring for circuit 150 (1) to the B110 Battery Sensor Module (2).

Type here to search

1:14 PM 2/3/2023

Diagnostic Tip for Malfunction Indicator Lamp (MIL) Illuminated with DTC P305F, P0588 and/or P058D - ALLDATA Repair

https://my.alldata.com/repair/#/repair/vehicle/54597/component/1/itype/13/tsbs/20190502162413368/selfRefLink/false


Center of Learning... Thank12w - Free D... ProDemand Autom... Direct-Hit -- Create... Amazon.com Shop... AESWAVE ACE Misfire Detecti... Yahoo | Mail, Weath... Other favorites

### 2015 Chevrolet Impala L4-2.5L

Community 7

[Open in New Tab](#) [Zoom/Print](#)

1. Inspect the orientation of the grounding ring for circuit 150 (1) to the B110 Battery Sensor Module (2).



[Open in New Tab](#) [Zoom/Print](#)

- If found contacting the sensor, reposition the terminal away from the sensor as shown above, and tighten the bolt to 5 Nm (44 lb in).

2. Check ground resistance of Dual Battery Isolation Module (DBIM) to G103. Wiggle the harness and negative battery terminal connections during the test to look for varied resistance values.
  - If resistance is greater than 0.5 ohms or changes more than 1 ohm:
    1. Inspect ground connections and/or splice in the harness about 1.5 ft. from the connector end.
    2. Fix poor connection and replace the module.
    3. Clear codes and re-check.
  - If resistance is less than 0.5 ohms, proceed to step 3.

Type here to search

1:15 PM 2/3/2023

Diagnostic Tip for Malfunction Indicator Lamp (MIL) Illuminated with DTC P305F, P0588 and/or P058D - ALLDATA Repair

https://my.alldata.com/repair/#/repair/vehicle/54597/component/1/itype/13/tsbs/20190502162413368/selfRefLink/false

Center of Learning... Thank12w - Free D... ProDemand Autom... Direct-Hit -- Create... Amazon.com Shop... AESWAVE ACE Misfire Detecti... Yahoo | Mail, Weath... Other favorites

### 2015 Chevrolet Impala L4-2.5L

Community 7

3. Clear codes and re-check.  
 o If resistance is less than 0.5 ohms, proceed to step 3.  
 3. Replace the battery distribution fuse block and wiring harness connector, clear codes and re-check.

**Parts Information**

Causal Part	Description	Part Number	Qty
N/A	BLOCK, BAT DISTRIBUTION ENG COMPT FUSE	23223079	1
N/A	CONNECTOR KIT, WRG HARN	13581092	1

**Warranty Information**  
**Note:** For vehicles repaired under warranty, use the appropriate labor operation for the repair performed.  
 For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
5430360	Front Compartment Fuse Block Replacement	Use Published Labor Operation Time
5430860	Connector Kit Replacement	
2680358*	Check the Orientation of The Grounding Ring	0.2 hr

\*This is a unique Labor Operation for Bulletin use only.

Type here to search

1:17 PM 2/3/2023

Diagnostic Tip for Malfunction Indicator Lamp (MIL) Illuminated with DTC P305F, P0588 and/or P058D - ALLDATA Repair

https://my.alldata.com/repair/#/repair/vehicle/54597/component/1/itype/13/tsbs/20190502162413368/selfRefLink/false

Center of Learning... Thank12w - Free D... ProDemand Autom... Direct-Hit -- Create... Amazon.com Shop... AESWAVE ACE Misfire Detecti... Yahoo | Mail, Weath... Other favorites

### 2015 Chevrolet Impala L4-2.5L

Community 7

**Note:** For vehicles repaired under warranty, use the appropriate labor operation for the repair performed.  
 For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
5430360	Front Compartment Fuse Block Replacement	Use Published Labor Operation Time
5430860	Connector Kit Replacement	
2680358*	Check the Orientation of The Grounding Ring	0.2 hr

\*This is a unique Labor Operation for Bulletin use only.

<b>Version</b>	2
<b>Modified</b>	Released December 06, 2018 May 01, 2019 - Added the 2014-2016 Chevrolet Impala (VIN 1).

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

© 2019 General Motors. All rights reserved.

WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION

Type here to search

1:18 PM 2/3/2023

Direct-Hit -- Search Fixes/Information Available - Asset Details

https://dh.identifix.com/AssetDetailsViewer/GetAssetDetailView?ROID=336537408&VID=2417574&WorkflowPath=1&AssetId=f7f54f4...

Center of Learning... Thank12w - Free D... ProDemand Autom... Direct-Hit -- Create... Amazon.com Shop... AESWAVE ACE Misfire Detecti... Yahoo | Mail, Weath... Other favorites

**SOLERA** Vehicle Repair **Direct-Hit** by Identifix

REPAIR HOTLINE AUTODATA TRAINING iATN by identifix

HOME | SEARCH FIXES | SERVICE MANUALS | MAINTENANCE | ESTIMATING | HOTLINE | MY SHOP

BOOKMARKS

Search | Information Available **Post Fix** | Can't Find Service Manual Info? | New Vehicle | Payment Settings | Referral | Logout

**2015 Chevrolet Impala LS 2.5L, L4, Gas, VIN L, Des LKW, 16V, USA/Canada** Ken Zanders - NAPA- Autotech Training

Hotline Archive With Service Manual diagrams, components, TSB: << Bookmark Print Preview Print >>

Number: 626217

Vehicle Application: 2015 Impala 2.5 2015 Malibu 2.5  
2014 Malibu 2.5 2016 Malibu Limited 2.5

Customer Concern: Code **P305F**

Average Reported Mileage: 87784

Tests/Procedures:

1. Connect a Digital Volt Ohm Meter (DVOM) to the auxiliary battery in the trunk.
2. Trigger a MIN/MAX recording.
3. Road test the vehicle to warm it up so that an Auto Stop occurs.
4. Release the brake and the engine should Auto Start on acceleration.
5. Stop the vehicle in a safe location.
6. Observe the Minimum voltage from the MIN/MAX recording.
7. If the voltage is under 10 volts, load test the both batteries with a tester approved for Absorbed Glass Mat (AGM) batteries. Replace battery if it fails the load test.
8. Check for poor cable connections at the auxiliary battery. Repair any problems found.

Author: [Bill Siegmann](#)

TSBs

- 18-Na-367
- TSBs
- #18-NA-367: DIAGNOSTIC TIP FOR MALFUNCTION INDICATOR LAMP (MIL) ILLUMINATED WITH DTC P305F, P058B AND/OR P058D (MAY 14, 2019)
- #PIEQ463A: ENGINEERING INFORMATION - SMOKE OR BURNING ODOR FROM UNDERHOOD WITH MALFUNCTION INDICATOR LAMP (MIL) ILLUMINATED WITH DTC P305F OR P058B (DEC 21, 2018)

Back To Top

< Previous 0 | Next 0 >



Training Toolbox

Type here to search


1:21 PM 2/3/2023

# Review Wiring Diagrams and Trouble Code Charts









Document ID: 3462696

https://gsitc.ext.gm.com/gsi/showDoc.do?pubName=Impala%20Service%20Manual%207525949&pubSectionName=&language=1&pu...

Service Information

2013 Chevrolet Impala (VIN 1) | Impala Service Manual 7525949 | Document ID: 3462696

### DTC P305F

**DTC Descriptors**

**DTC P305F Dual Battery Control Module Performance**

**Diagnostic Fault Information**

Circuit	Short to Ground	Open/High Resistance	Short to Voltage	Signal Performance
B+	—	P305F	—	P305F
Ignition	—	P305F	—	P305F
Control	—	P305F	—	P305F
Ground	—	P305F	—	P305F

**Circuit/System Verification**

- Ignition ON
- Using the Graphical Data Display in the scan tool, verify the ECM Ignition 1 Signal is 8.9 V or greater during ignition CRANK.

⇒ If Ignition 1 Signal is below 8.9 V

© 2023 General Motors. All rights reserved.

Document ID: 3462696

https://gsitc.ext.gm.com/gsi/showDoc.do?pubName=Impala%20Service%20Manual%207525949&pubSectionName=&language=1&pu...

Center of Learning... Thank12w - Free D... ProDemand Autom... Direct-Hit -- Create... Amazon.com Shop... AESWAVE ACE Misfire Detecti... Yahoo | Mail, Weath... Other favorites

**Service Information**

2015 Chevrolet Impala (VIN 1) | Impala Service Manual 7525949 | Document ID: 3462696

### DTC P305F

#### Circuit/System Verification

1. Ignition ON
2. Using the Graphical Data Display in the scan tool, verify the ECM Ignition 1 Signal is 8.9 V or greater during ignition CRANK.  
⇒ **If Ignition 1 Signal is below 8.9 V**
  - 2.1. Verify that there is no excessive parasitic current drain, refer to [Battery Electrical Drain/Parasitic Load Test](#).  
⇒ If there is excessive parasitic current drain, determine cause of the excessive parasitic current drain.  
⇒ If there is no excessive parasitic current drain, refer to Circuit/System Testing.
- ⇒ **If Ignition 1 Signal is 8.9 V or greater**
3. All OK.

#### Circuit/System Testing

**Note:** You must perform Circuit/System Verification before Circuit/System Testing.


1. Ignition OFF
2. Perform a [Battery Inspection/Test](#) on the C1 Battery and C1B Battery - Auxiliary.  
⇒ **If battery fails the battery test**  
Replace the defective battery
- ⇒ **If battery passes the battery test**
3. Ignition OFF, disconnect the X1 harness connector at the K20 Engine Control Module, Ignition ON.
4. Verify a test lamp illuminates between ignition circuit terminal 51 X1 and ground.  
⇒ **If the test lamp does not illuminate and the circuit fuse is good**
  - 4.1. Ignition OFF, remove the test lamp.

© 2023 General Motors. All rights reserved.

Type here to search

6:09 AM 1/7/2023

- 1) OCV voltage 12.13 volts
- 2) Cranking voltage 11.4 volts
- 3) Measured CCA of 498 with a capacity of 900 CCA
- 4) The AGM (primary) battery has failed the battery test and was replaced
- 5) The Auxiliary battery was also replaced based on the graphical analysis results





## Conclusion

- The subject vehicle is now working as designed in this particular area and the trouble code **P305F** is no longer stored in the controllers (PCM) memory
- Never assume that the Auxiliary Battery is OK. You should always Test.
- The customer is now asking that the **GM infotainment** system be evaluated and repaired

## Test Procedures

Case Study No 4

Can You Live Without Your Radio?

Code U0028  
MOST Bus

## Customer Concern

- ❖ The **Information Display Module** for the Infotainment System is Blank
- ❖ The **CD Player** does not appear to work as designed
- ❖ The owner would like to **sell the vehicle**, but the radio being inoperative is a barrier to obtaining a interested buyer

## Diagnostic Process

- ❖ Step 1: Obtain **Trouble Code** Information
- ❖ Step 2: Determine the **RPO code** for the infotainment system you are working on
- ❖ Step 3: Review **Description and Operation**
- ❖ Step 4: Review **any and all TSB's** that may apply
- ❖ Step 5: Review Trouble **Code Chart** and **Wiring Diagrams**

## Diagnostic Process

- ❖ Step 6: Review **MOST Diagnostic Starting Point**
  - ❖ Is there any information available that indicates a failure status exist?
- ❖ Step 7: Verify **MOST Control Circuit** (**MOST communication enable circuit**) is good

Obtain Trouble Code Information



**Review Wiring Diagrams and  
Trouble Code Charts**

**Review Technical Service Bulletins**

Direct-Hit -- Search

https://dh.identifix.com/SearchFixes/Index?ROID=336537408&VID=2417574&VSM=1&LocationId=2&WorkflowPath=1&KW=U0028#K...

Center of Learning... Thank12w - Free D... ProDemand Autom... Direct-Hit -- Create... Amazon.com Shop... AESWAVE ACE Misfire Detecti... Yahoo | Mail, Weath... Other favorites

Vehicle Repair by Identifix

HOME | **SEARCH FIXES** | SERVICE MANUALS | MAINTENANCE | ESTIMATING | HOTLINE | MY SHOP

Search Information Available **Post Fix** | Can't Find Service Manual Info? | New Vehicle | Payment Settings | Referral | Logout

2015 Chevrolet Impala LS 2.5L, L4, Gas, VIN L, Des LKW, 16V, USA/Canada Ken Zanders - NAPA- Autotech Training

**SEARCH**

U0028  ☐ Service Manuals Only

Models w/same Engine Package

**SEARCH RESULTS SUMMARY**

**Service Manuals**

2	<a href="#">TSBs/Recalls</a>
1	<a href="#">Description &amp; Operation</a>
8	<a href="#">Diagnostics</a>
1	<a href="#">Specifications</a>

No useful information noted here

**TSBS/RECALLS** **SERVICE MANUALS**

TSBs  
[#PI1149A: INTERMITTENT RADIO BLANK DISPLAY WITH OR WITHOUT AUDIO AND MOST BUS DIAGNOSTIC AID \(NOV 28, 2017\)](#)  
[#PIC6073E: DIAGNOSTIC TIP: EL-51578 MOST BUS DIAGNOSTIC TOOL KIT \(DEC 17, 2018\)](#)

[Back To Top](#) < Previous 0 | Next 0 > **Results: 1 - 2 of 2** [Show All](#)

**DESCRIPTION & OPERATION** **SERVICE MANUALS**

General Descriptions  
[DATA LINK COMMUNICATIONS DESCRIPTION AND OPERATION \(DATA COMMUNICATIONS\)](#)

[Training Toolbox](#)

Type here to search

Direct-Hit -- Search

https://dh.identifix.com/SearchFixes/Index?ROID=336537408&VID=2417574&VSM=1&LocationId=2&WorkflowPath=1&KW=U0028#K...

Center of Learning... Thank12w - Free D... ProDemand Autom... Direct-Hit -- Create... Amazon.com Shop... AESWAVE ACE Misfire Detecti... Yahoo | Mail, Weath... Other favorites

**SOLERA** Vehicle Repair **Direct-Hit** by Identifix

REPAIR HOTLINE AUTODATA TRAINING iATN by Identifix

HOME | **SEARCH FIXES** | SERVICE MANUALS | MAINTENANCE | ESTIMATING | HOTLINE | MY SHOP

Search Information Available **Post Fix** | Can't Find Service Manual Info? | New Vehicle | Payment Settings | Referral | Logout

2015 Chevrolet Impala LS 2.5L, L4, Gas, VIN L, Des LKW, 16V, USA/Canada Ken Zanders - NAPA- Autotech Training

**SEARCH**

U0028, U2098  ☐ Service Manuals Only

Models w/same Engine Package

**SEARCH RESULTS SUMMARY**

**Service Manuals**

2	<a href="#">TSBs/Recalls</a>
1	<a href="#">Description &amp; Operation</a>
8	<a href="#">Diagnostics</a>
1	<a href="#">Specifications</a>

No useful information noted here

Alternative Search Suggestions: "U2098"

**TSBS/RECALLS** **SERVICE MANUALS**

TSBs  
[#PI1149A: INTERMITTENT RADIO BLANK DISPLAY WITH OR WITHOUT AUDIO AND MOST BUS DIAGNOSTIC AID \(NOV 28, 2017\)](#)  
[#PIC6073E: DIAGNOSTIC TIP: EL-51578 MOST BUS DIAGNOSTIC TOOL KIT \(DEC 17, 2018\)](#)


[Back To Top](#) < Previous 0 | Next 0 > **Results: 1 - 2 of 2** [Show All](#)

**DESCRIPTION & OPERATION** **SERVICE MANUALS**

[Training Toolbox](#)

Type here to search

## Basic View of Components



**Determine the RPO Code(s)**  
GM Infotainment System





The screenshot shows a web browser window with the URL <https://decoderpo.com>. The page title is "RPO Codes Decoder - GM Chevrolet Buick Cadillac - Regular Production Option". The main heading is "RPO CODES DECODER" with the subtitle "DECODE RPO CODE FOR GM CHEVY BUICK CADILLAC". Below this, it says "type or paste RPO Codes here use comma or space delimiter". A text input field contains the code "IO3". A blue button labeled "Decode RPO" is next to the input field. Below the input field, the URL "https://decoderpo.com" is displayed. The page is divided into two main sections: "What do RPO Codes Means?" and "Decoding Results".

**What do RPO Codes Means?**

Find out what options your GM Chevy Buick Cadillac vehicle is equipped with.

A **Regular Production Option** is a General Motors standard coding for vehicle configuration options. Each **RPO** code is a combination of three alphanumeric characters (like **Z71**) that refers to a specific option or modification to the vehicle as built during production and can be used to identify specific vehicle options or modifications such as paint colors, engine types, interior options, wheel types, etc.

**Decoding Results**

IO3	RADIO INFOTAINMENT SYSTEM - BASE
-----	----------------------------------

**Other codes**

01F	TRIM COLOR SEAT SHALE
1SD	PACKAGE-OPTION 04

**MOST Diagnostic Starting Point**

Techline Connect S(pom.version) Production

GDS2

MOST Bus Diagnostic Starting Point

Complete

## MOST Bus Diagnostic Starting Point

Parameter Name	Control Module	Value	Unit
Battery Voltage	Radio	12.8	V
Number of MOST Communication Breaks	Radio	0	
Number of MOST Bus Nodes	Radio	3	
Surrogate MOST Master Node Upstream Position	Radio	0	
Node Locations of MOST Bus Communication Break	Radio	3 - 1	
Last Working MOST ID of Node 1	Radio	Radio	
Last Working MOST ID of Node 2	Radio	Amplifier	

Continue

Back Home Vehicle Menu Enter

GDS 2 v.22.3.02900 GM Global v2022.12.0 VIN: 2G11Z55L3F9168124 2015,Chevrolet,Impala,1,Module Diagnostics,Radio,Control Functions MDI: 22009314 13.8 V

Type here to search 28°F Cloudy 1:11 PM 1/6/2023

Techline Connect S(pom.version) Production

GDS2

MOST Bus Diagnostic Starting Point

Complete

## MOST Bus Diagnostic Starting Point



Parameter Name	Control Module	Value	Unit
Number of MOST Bus Nodes	Radio	3	
Surrogate MOST Master Node Upstream Position	Radio	0	
Node Locations of MOST Bus Communication Break	Radio	3 - 1	
Last Working MOST ID of Node 1	Radio	Radio	
Last Working MOST ID of Node 2	Radio	Amplifier	
Last Working MOST ID of Node 3	Radio	Instrument Cluster	
Last Working MOST ID of Node 4	Radio	UNRECOGNIZED ST...	



Continue

Back Home Vehicle Menu Enter



GDS 2 v.22.3.02900 GM Global v2022.12.0 VIN: 2G11Z55L3F9168124 2015,Chevrolet,Impala,1,Module Diagnostics,Radio,Control Functions MDI: 22009314 14.0 V



Type here to search 27°F Cloudy 11:23 AM 1/7/2023











# Description and Operation

Techline Connect \${pom.version} Production

gm Service Information

2015 Chevrolet Impala (VIN 1) (2G11Z5SL3F9168124) | Impala Service Manual 7525949 | Driver Information and Entertainment | Cellular, Entertainment, and Navigation | Description and Operation | Document ID: 2965495

## Radio/Audio System Description and Operation (IO3)

The entertainment system on this vehicle may have several different configurations available to it. To determine the specific configuration of the vehicle, please see the Service Parts ID Label, and refer to [RPO Code List](#).

Each item in the list below represents topics covered in detail below.

- Data Communications
- Remote Radio Receiver
- Media Disc Player
- Audio Amplifier (If equipped)
- Speaker Operation
- Infotainment Controls and Display
- Antenna System
- Radio Reception
- Theft Deterrent
- Auxiliary Audio Input Jack
- USB Port and SD Card Reader
- Valet Mode
- OnStar ®
- Steering Wheel Controls (If equipped)
- Auto Volume Control

### Data Communications

The infotainment system communicates with other devices on multiple serial data networks during operation.

### Media Oriented Systems Transport (MOST)

© 2023 General Motors. All rights reserved.

# Obtain Trouble Code Information

Techline Connect S(pom.version) Production

GDS2

DTC Display

Create Report Add Bookmark

Status	Control Module Name	Control Module Status	DTC Count	DLC Pin
⚠	Radio	DTCs Stored	4	1

Control Module	Type	DTC	Symptom...	Description	Symptom Description	Status
Radio		U0028	00	MOST Bus	---	Current
Radio		B1325	03	Control Module Power Circuit	Low Voltage	History
Radio		U0155	00	Lost Communication with Instrument Cluster	---	History
Radio		U15E1	00	Lost Communication with Device on LIN Bus	---	History

Let's start by taking a look at Radio Data

Category	Decoded Value
DTC Current Status	Current
DTC History Status	History



Clear DTCs Refresh


Back Home Vehicle Menu Enter

GDS 2 v.22.3.02900 GM Global v2022.12.0 VIN: 2G11Z55L3F9168124 2015,Chevrolet,Impala,1,Module Diagnostics,Radio,Diagnostic Trouble Codes (DTC) MDI: 22009314 13.8 V


Type here to search S&P 500 +1.85% 1:00 PM 1/6/2023








# Human Machine Interface Codes






There is  
not an HMI  
Control  
Module on  
this vehicle

**Radio 1**


**Amplifier 2**





**3 Instrument Cluster**





# Amplifier Codes






# Instrument Cluster Codes









Techline Connect [pom.version] Production

GDS2

DTC Display

Create Report Add Bookmark

Status	Control Module Name	DTCs Stored	Control Module Status
	Instrument Cluster	1	1

Control Module	Type	DTC	Sympto...	Description	Symptom Description	Status
Instrument Cluster		U2098	00	MOST Communication Enable Circuit	- - -	Passed and Failed

Category	Decoded Value
This Ignition Cycle	Passed
Since DTC Clear	Passed and Failed
DTC Current Status	Not Current
DTC History Status	History

Clear DTCs Refresh

Back Home Vehicle Menu Enter

GDS 2 v.22.3.02900 GM Global v2022.12.1 VIN: 2G11Z5SL3F9168124 2015,Chevrolet,Impala,1,Mo... MDI: 22009314 11.7 V

9:22 AM 1/10/2023

# Media Disc Player Codes

## Case Study

### Module Scan:

- The Media Disc Player (A33) shows no communication
- This is normal
- The Media Disc Player is only on the MOST Bus

Chevrolet  
V8.10

Chevrolet > Automatic selection > Control unit > Radio > Active test

VCMS 11.8V

ECU Information

Trouble codes

Live data

Active test

Special function

MOST bus diagnostic starting point(MOST bus communication)

Complete

Parameter name	Value	Unit
Battery voltage	10.8	
Number of MOST communication breaks	0	
Number of MOST bus nodes	3	
Surrogate MOST master node upstream position	0	
Node locations of MOST bus communication break	3 - 1	
Last working MOST ID of node 1	Radio	


VIN: 2G11Z5SL3F9168124  
Info: Chevrolet/Impala

Continue Back

Radio 1

Amplifier 2

3 Instrument Cluster



Chevrolet V9.00

Chevrolet > Automatic selection > Control unit > Radio > Live data

VCU 9.4V

Name	Value	Range	Unit
<input type="checkbox"/> Equalizer preset	Invalid		
<input type="checkbox"/> Surround sound	Off		
<input type="checkbox"/> Surrogate MOST master node upstream position	0		
<input type="checkbox"/> Number of MOST communication breaks	0	[0...65535]	
<input type="checkbox"/> Last working MOST ID of node 1	3		
<input type="checkbox"/> Last working MOST ID of node 2	Radio		
<input type="checkbox"/> Last working MOST ID of node 3	Amplifier		
<input type="checkbox"/> Last working MOST ID of node 4	Instrument cluster		
<input type="checkbox"/> Last working MOST ID of node 5	UNRECOGNIZED STATE		

**Data shown while using MOST bypass tool**

Navigation: Cancel All, Show Selected, Graph Merge, To Top, Setting, Clear Data, Freeze, Record, Review, Back





Chevrolet V9.00

Chevrolet > Automatic selection > Control unit > Radio > Active test

VC 10.9V

**ECU information**

**Active test**

**Special function**

**MOST bus diagnostic starting point(MOST bus communication)**

Number of MOST communication breaks	2
Number of MOST bus nodes	4
Surrogate MOST master node upstream position	0
Node locations of MOST bus communication break	4 - 1
Last working MOST ID of node 1	
Last working MOST ID of node 2	
Last working MOST ID of node 3	
Last working MOST ID of node 4	

**New CD player has been installed. MOST bypass tool is no longer being used**

**Radio 1**

**Amplifier 2**

**Media Disc Player 4**

**Instrument Cluster 3**

VIN: 2G11Z5SL3F9168124  
Info: Chevrolet/Impala

Continue Back



# Radio Controls Codes

Technline Connect \$(pom.version) Production

GDS2

DTC Display

Create Report Add Bookmark

Status	Control Module Name	Control Module Status	...	...
...	Radio Controls	Requesting DTCs	2	1

Control Module	Type	DTC	Sympto...	Description	Symptom Description	Status
Radio Controls		B1325	03	Control Module Power Circuit	Low Voltage	History
Radio Controls		U150E	00	LIN Bus	- - -	History

Category	Decoded Value
DTC Current Status	Not Current
DTC History Status	History

Clear DTCs Refresh

Back Home Vehicle Menu Enter

GDS 2 v.22.3.02900 GM Global v2022.12.1 VIN: 2G11Z5L3F9168124 2015,Chevrolet,Impala,1,Mo... MDI: 22009314 11.9 V

Document ID: 2692533

https://gsitc.ext.gm.com/gsi/cellHandler.do?cellId=183677&refDoc=2708974&pubName=Impala%20Service%20Manual%20... U150E 1/1

Center of Learning... Thank12w - Free D... ProDemand Autom... Direct-Hit - Create... Amazon.com Shop... U150E 1/1

Service Information

2016 Chevrolet Impala (VIN 11) | Impala Service Manual 8442464 | Document ID: 2692533



### Control Module U Code List


U Code	LIN BUS
U1501	LIN BUS
U1502	LIN BUS
U1505	LIN BUS
U1509	LIN BUS
	A26 HVAC Controls / P17 Info Display Module Lost Communication with K33 HVAC Control Module on LIN Bus
U150E	LIN BUS
	A22 Radio Controls / P17 Info Display Module Lost Communication with A11 Radio on LIN Bus
U150F	LIN BUS
	A22 Radio Controls / P17 Info Display Module Lost Communication with K74 Human Machine Interface Control Module on LIN Bus
	K161 Vehicle Performance Data Recorder Lost Communication with K74 Human Machine Interface Control Module on LIN Bus
	A11 Radio Lost Communication with A20 Radio/HVAC Control / P17 Info Display Module on LIN Bus
	A11 Radio (IOX/IOY) Lost Communication with S70R Steering Wheel Controls Switch - Right on LIN Bus
	K9 Body Control Module Lost Communication with B67 Ultrasonic Intrusion Sensor / B165 Content Theft Deterrent Sensor Module on LIN Bus
	K20 Engine Control Module Lost Communication with M06 Active Grille Air Shutter Actuator / M60A Active Grille Air Shutter 1 Motor Module

© 2023 General Motors. All rights reserved.









## Suggested Gameplan

- ❖ Step 1: Review Trouble Code Information
- ❖ Step 2: Determine the RPO code for the infotainment system and record it
- ❖ Step 3: Review **MOST Diagnostic Starting Point**
  - ❖ Is there any data available for review?
- ❖ Step 4: Review Operation and Description carefully
- ❖ Step 5: Verify **MOST Control Circuit** (**MOST communication enable circuit**) is good





