
GDi Fueling System

A Logical Approach To Driveability Concerns



**THE DATA
DOESN'T LIE**

Objectives

- **Discuss the functionality of the direct fuel injection system components**
- **Discuss how the components work as a system**
- **Describe the feedback loop we refer to as fuel trim**
- **Demonstrate how to leverage data PIDs from the scan tool**
- **Demonstrate the driveability road test**
- **Interactive case studies**

Let's Keep It "Simple"



- Comprehensible
- Meant to be applicable
- Aids in analysis
- Increases efficiency and Accuracy

The Load

Calculated Load

- *CALC_LOAD or Engine Load*
- *Compared to breathing capability at WOT*
- *Reads 100% @ WOT*
- *Disregards atmospheric pressure*

Absolute Load

- *ABS_LOAD*
- *Compared to swept-volume*
- *Can read well over 100%*
- *Better reflects volumetric efficiency*

Introduction to Gasoline Direct Injection (2004)



Precision Delivery

- Match actual to desired fuel rail pressure (FRP)
- Better MPG
- Lower poisonous tailpipe emissions
- Reduction of Green House Gases (CO₂)



More Stringent Tailpipe Emissions Standards

- Nox management: $\text{Lambda} < 1.00$
- CO management: $\text{Lambda} > 1.00$
- CO₂ management: Increased output/decreased combustion chamber



Fuel System Goals

Port Injection

- “Stoichiometry” (14.7:1)
- Narrow band of operation
- **CAT can function**
- Harmful tailpipe emissions minimized
- High CO₂ output



Direct Injection

- Focus on CAT functionality
- Wide band of operation
- WRAF and better strategies allow for it
- New inputs
- Rear fuel trim
- **Can CAT function?**




GDI Benefits

- Rail pressure reaching about **3000 psi (>200 bar)**
- Directly in-cylinder
 - *Vaporized/atomized format*
 - *Injector/spark timing optimized*
 - *Injection events per cycle*
 - *Catalyst supportive strategies*
 - *Higher compression? NO_x control*
 - *Lean strategies/better control (WRAF)*
 - *Increased cold-start volatility*
 - *Atkinson cycling*




GDI Disadvantages

- More complex fuel system
- Engine wear/HPFP drive
- New/unfamiliar strategies
- More data to analyze/digest
- Soot/carbon/Spray patterns
- NO_x/Sulphur issues
- Maintenance more critical
- **Engine pushed to limitations**





GDI Modes of Operation...

- Homogeneous
- Stratified
- Homogeneous-stratified
- Homogeneous-lean
- Homogenous knock-protection
- Stratified catalyst-heating





Homogenous Mode

- A uniform composition of particles
- Similar to port injection
- Direct-injected with air charge
 - *Start-up*
 - *High load*
 - *Time is limited*
- **Lambda approximately = 1.00**




Stratified Mode

- A/F charge, curtain of EGR
- Specially-designed pistons
- Direct-injected before spark occurs/centered
- Decreased thermal losses thru cylinder walls
 - *Light loads*
 - *Increased fuel economy*
- $\Lambda = >1.00$
 - *Open throttle/reduced suction losses*
 - *EGR effect = carbon/soot*
 - *High sulfur production/ 90-seconds storage*




Homogenous-Stratified Mode

- Transition between modes
- **Moderate to higher loads**
- Maintains good driveability (happy driver)
- Rich A/F surrounded by lean A/F
- Two injection pulses
 - *During intake (homogenous)*
 - *Prior to initiating compression*



Homogenous-Lean

- Smooths mode transitions
- Direct-injection during intake stroke
- Improved fuel economy (**leaner/longer**)
 - *Higher engine speeds*
 - *When stratified mode can't be used*
- High-throttle/reduced suction losses
- $\Lambda = >1.00$



Homogenous Knock-Protection

- Reduces “ping”
- Two injection pulses
 - *During intake stroke*
 - *During compression stroke (Quenching)*
- Second pulse reduces cylinder temperatures
- Lambda = variable with second pulse



Stratified Catalyst-Heating


- Heats/cleans NO_x converter
- Two fuel injection pulses
 - *First prior to ignition (Stratified)*
 - *Second after TDC-C*
- 650 degC for desulfurization
- Combustion continuing in exhaust system
 - *Delayed injection*
 - *Delayed ignition*




Low Pressure Fuel Supply...



Low Pressure Pump Operation...




Low Pressure Pump Operation...



Low Pressure Pump Operation



Example of Common Configuration



Can't Have "High" Without "Low"

- Takes low-pressure to make high-pressure
- Returnless system
- Brushed/brushless
- May offer pressure sensor input
- Supply is variable to match load
 - *Duty-cycled*
 - *Hi/Low speeds*
 - *Variable*




High Pressure Supply System...




High Pressure Fuel Pumps (HPFP)

- Fed fuel from low-pressure system
- Mechanically driven
- Traps/squeezes fuel (**Crankcase can fill with fuel**)
- Always moving with engine
- Single or multi-piston designs
- Generates pressure when commanded
- Proper engine oil (**CRITICAL**)
- Timed to engine (**CRITICAL**)
 - *Intake camshaft*
 - *Exhaust camshaft*
 - *Timing chain directly*




HPFP Operation...

- Driven mechanically (camshaft/chain/rotary)
- Pump strokes multiple times per engine cycle
- Pressurized fuel trapped between HPFP/injectors
- Coupled to Fuel Volume Regulator Valve (FVR)
 - *ECU actuates FVR*
 - *FVR traps fuel in pump*
 - *Pressure builds with shrinking chamber*
 - *Fuel displaced with FVR open*
 - *Normally-Open / Normally-Closed*




HPFP Exploded View


- Fuel volume regulator inlet valve
- Fuel volume regulator solenoid (FVR)
- Pump chamber
- Piston
- Outlet check valve
- Outlet fitting
- Pressure relief valve




End of Intake Stroke
Start of Compression Stroke



Compression Stroke



Compression Stroke Ends



Low Pressure Inlet


Electromagnet Control Valve

High Pressure Outlet


Piston/Plunger




Pumping Chamber/Cylinder


Intake Stroke




End of Intake Stroke
Start of Compression Stroke








Rotary High Pressure Fuel Pump




Rotary High Pressure Fuel Pump




Utilized Pump Strokes

- Multiple lobes stroke pump
- Same strokes every cycle
- Load/RPM based
- Matches FRP to desired pressure
- Not all strokes utilized (**Configuration**)
 - *Only when trap door shuts*
 - *Function of FVR*
 - *Normally-open/Normally closed?*




HPFP Regulator Waveform

- 2 wire solenoid
- Scope leads on high & low
- Control circuits
- Check voltage & current
- Driver's ability to control current
- Shorted Coil



Injector Rail and FRP Sensor

- Positive seal between HPFP outlet fitting/Injectors
- One-time use typically
 - *Metal-to-metal seal*
 - *Lubricate with engine oil only*
 - *Torque is critical*
- Sensor provides feedback to ECU
 - *3-wire device*
 - *Pressure transducer*






Fuel Injector Design

- Precision delivery required (Atomization)
- Similar control to diesel injectors
- Higher voltage and amperage (**CAUTION**)
- Limited time to deliver fuel
- Multiple injection events per cycle possible
- Cylinder compression opposes injection
 - *No longer injected in intake manifold*
 - *Directly into combustion chamber*
 - *Exposed to harsh environment*
 - *Special service procedures*



Piezo Fuel Injector

- Electricity excites piezo element stack
- Causes stack to expand
- Fuel lubricates/cool
- Hydraulic actuator
 - *Actuates injector*
 - *Very swift and precise control*
 - *Hydraulic = Fuel or Sealed Fluid*




Saturated Coil Injector

- Similar to conventional port injectors
- Operates at approximately 90 volts and 15 amps
- Long nozzle to reach combustion chamber
- Specially designed seals to trap combustion
 - *Single-use*
 - *Special replacement procedure*




Shared Power-Stage Supply...





Injector Primed for Opening

- ECU allows injector to saturate (piezo style)
- Low voltage builds magnetic field
 - *12v system*
 - *Injector remains closed*





Initial Opening (Peak)

- ECU driver discharges capacitor into injector
- Injector amperage increases significantly
 - *Ohm's law*
 - *High current/faster response*
 - *Injector open rapidly*





Injector Open (Hold)

- ECU driver switches
- Low-voltage applied to circuit
 - *Ohm's law*
 - *Current reduces with voltage reduction*
 - *Injector remains open*




Injector Circuit Momentary Turn-off

- Injector de-energized
- Injector ground control released
- Control-side referencing capacitor
 - *Injector magnetic field collapses*
 - *Induces inductive kick*
 - *Charges capacitor for subsequent initiation*




Current Limitation

- Injector grounded
- 12v supply is pulsed rapidly
 - *Occurs in microseconds (uS)*
 - *Meters fuel delivery*




Injector off


- Power supply released
- Ground supply released
 - *Current vanishes*
 - *Magnetic field collapses*
 - *Inductive kick occurs*



Shared Power-Stage Supply...



Paired-Injector Operation



Shared Power-Stage Supply

Energized Injector



De-energized Injector



Let's Analyze Data!



GDI, From the Driver's Seat

- Let the PIDs tell the story
- Divide and concur
- G-tests lead to P-tests
- Game plan
 - *Breathability*
 - *Fueling*
 - *Corrective factor*
 - *Failure strategy*



Breathability

- Is there enough air moving through the engine at the time?
- Fuel comes from air measured
- If “air” isn’t correct, performance suffers
 - *Unmetered air, fuel miscalculation*
 - *Poor pumping abilities*
 - *How will ECU respond?*




Fueling

- Is there enough fuel delivered for the air pumped?
- Low-pressure sensor/ FRP sensor inputs
- PCM to FPCM command/low-Pump performance
- FVR and HPFP performance
- Injector performance
- If “fuel” isn’t correct, performance suffers
 - *Poor fuel delivery skews intended A/F ratio*
 - *Compensation takes place*
 - *Default strategies may present*



Corrective Factor

- Are adaptive strategies at play?
- Adaptives can mask driveability issues and offer clues
- Have the thresholds been crossed?
 - *Pump fuel trim*
 - *Short term fuel trim*
 - *Long term fuel trim*
 - *Rear fuel trim*
 - *Total fuel trim*



Protection Strategies

- Protection against damage/pollution
- Can be cause of exhibited symptoms
- Can confuse technicians
 - *Low-power/closed throttle*
 - *Reduced throttle opening*
 - *Poor performance*



Systematic Analytical Approach

- Gather data to make diagnostic decisions
- Road test flushes faults to surface
- Divide data into groups
- Analyze data PID groups like puzzle pieces
- Assemble puzzle pieces
 - *G test vs. P tests*
 - *Data driven analysis*
 - *Limited hands-on testing*




Driveability Test Drive

WOT					
Mod. Accel					
Lite Accel					
Decel.					
Idle					

Time

Less Than a Minute

Driveability Test Drive



10 Sec Idle

15 Sec Light Acceleration

5 Sec WOT

5 Sec Decel

10 Sec Cruise

10 Sec Idle


Use Caution

- **Limit PIDs captured**
 - *Refresh rate*
 - *Maintain sanity*
- **Save “files”**
 - *Manipulate after capture*
 - *Share, save to cloud*
- **Use scan tool buffer**
 - *Action/reaction testing*
 - *History provided*
 - *DO NOT VIEW WHILST DRIVING*



Parameter Identifiers Groups (PIDs)

- Smaller groups per section
- Include PIDs reflecting operating conditions
- Answers questions we have about driveability
- Prevents confusion
- Organizes thought process
- Focus



Airflow PIDs

- RPM
- MAP
- MAF
- Calc_Load
- ABS_Load
- APP (actual/desired)
- TAC (actual/desired)
- IAT
- BARO
- Boost




Fuel PIDs

- HO₂s / WRAFs
- Low-pressure system fuel pressure
- Fuel rail pressure (FRP)
- Equivalence ratio (EQR) or Lambda
- Fuel system loop status
- Commanded EQR or Commanded Lambda
- Load PIDs
- Throttle PIDs



Adaptive PIDs

- STFT
- LTFT
- Rear Fuel Trim
- EQR
- Loop Status
- RPM
- Load PIDs
- Throttle PIDs



Protection PIDs

- Fuel system loop status
- MIL commanded “ON”
- “Reduced Power” message/symbol
- Throttle
 - *Desired position*
 - *Actual position*



Verify Sensor Accuracy

- Key-ON, Engine OFF
- After 8hr cold-soak
- Monitor PIDs statically
 - *Pressure*
 - *Temperature*
 - *Position*
 - *Voltages*



Be aware of how PIDs are referenced

Tech Support Case Studies...

- Fixed over the phone
- Acquired AFAD PIDs
- Performed Driveability Road Test
- Preliminary data led to the pinpointed testing






2014 BMW X6

P0303 sets above 4000 rpm

Subject Vehicle Background

- V8 engine
- Turbo charged
- Twin independent GDI (pumps/rails/FRPs)
- 2 MAFs
- **P0303, loaded above 4000 rpms**



How is the Vehicle Performing?

- Lean under heavy load
- Command near stoichiometry
- Lambda 1.36 (36% lean)
- Rear HO2 sensor @ .074 V (not visible)
- Load is dropping?



Why is the engine under fueled?

Possible Causes of Under Fueling

- Faulty GDI high pressure pump(s)?
- Faulty low pressure fuel supply pump system?
- Restricted injectors?
- Air mass calculation?
- Faulty WRAF sensor?
- Faulty Rear HO₂ sensor?



Is the Engine Breathing Correctly?

- Injection based upon airflow
- Engine is not pumping adequately
- Can an engine breath efficiently with throttle closed?



Take notice of the throttle position


Why Command the Throttle Closed?

- Newer strategy
- How to correct for a lean condition?
 - *Increase fuel delivery to maintain A/F ratio*
 - *Reduce airflow to maintain A/F ratio*

Not the “cause,” but the “effect”

Is the Engine Being Fueled Correctly?

- Road test under load
- 39% lean of stoichiometry (**Lambda 1.39**)
- **Increase in load, decrease in FRP**
- Occurred on both banks



Why would FRP be dropping?

Potential Causes of Low FRP

- Poor high pressure pump operation?
- Advanced cam timing issue?
- Control solenoid issue/control issue?
- Poor low pressure supply issue?



Chicken or the Egg?

- Which dropped out first?
- Compare PIDs
- Use cursor to measure
- **Breathability issue is the “effect” of fuel issue**



FRP dropped first, must chase that root-cause fault

Where Do We Go From Here?

- Replace both high-pressure fuel pumps?
- Replace the GDI injectors?
- Replace the low-pressure supply pump (in-tank)?
- Gather more info about low pressure supply system?



2019 Honda Fit

P0172- Bank #1, Rich Condition


Subject Vehicle Background

- P0172-Bank #1, Rich condition
- 4-cylinder twin cam, naturally aspirated
- MAF strategy
- Vehicle was taken on a driveability road test



How is the Vehicle Performing?

- Commanded stoichiometry
- Lambda indicates 8% rich
- HEGOs both indicate “Rich”
- PCM attempting to compensate (trim)



Why is the engine over fueled

Possible Causes of Over Fueling

- Rail pressure too high
- MAF over estimating
- Exhaust leak (air ingested)
- Faulty fuel injectors
- Contaminated oil
- Fuel contamination
- Skewed HEGOs?



How is the Engine Breathing?

- Idle speed of 741 rpm
- MAF value of 2.4 gps is accurate
- -32% fuel correction is present



Fault is not breathability related

Change the Running Conditions

- Eng speed elevated to 2600 rpm
 - *Load?*
 - *Fuel demand?*
- What does this test prove?
 - *No leaking purge valve*
 - *No dribbling injectors*



Only a few possibilities...still in the driver's seat!

Diagnosis and Repair

- Road test to confirm fault
- Alter conditions to reveal fault
- Eliminate the impossible
- Focus on the probable
- Easy tests first

Minimal time under the bonnet!



Preliminary Diagnostics Summary

- Proper interrogation
- Design you PID groups
 - *Breathability*
 - *Fueling*
 - *Corrective Factors*
 - *Protection strategies*
- Carry out your Diagnostic Test Drive
- Analyze ALL GROUPS before diagnosis




2013 Audi A4 2.0L



High Rail Pressure


Towed From Another Workshop

- Shop states “High fuel rail pressure”
- Previous repair attempts:
 - *HPFP replacement (x2)*
 - *Fuel rail pressure sensor replacement*
- **Scan DTCs...P008800 “Pressure too high”**



Fundamental Knowledge


- The HPFP produced more fuel pressure than desired
- PCM recognized the fault
- Logical process likely eliminates:
 - *Low-pressure fuel pump failure*
 - *Fuel pump control module failure*
 - *HPFP failure (would lack pressure)*
 - *FRP sensor (replaced already, low on suspect list)*



Causes of Higher-than-desired rail pressure?


How Rail Pressure is Made

- HPFP is driven by exhaust camshaft (**Configuration?**)
- Four lobes stroke pump piston
 - *Pumped stroked 4x per cam rotation*
 - *Fuel must be trapped to produce pressure*
 - *Fuel volume regulator valve must close*
- FRV solenoid attached to pump assembly (**Configuration?**)




FRV Functionality

- FRV acts like a trap door
- Piston action generates pressure against FRV
- Open valve allows fuel displacement
 - *Normally-Open*
 - *Normally-Closed*



Which design are we dealing with?

An Experiment



FRV Timing is Critical

- PCM energizes FRV to limit rail pressure
- Could the FRV be malfunctioning?
- Could PCM be sending incorrect command?
- Could the engine be out of time?
 - *No DTCs reflecting timing fault*
 - *Engine performs well*




Thinking This Through...


- DTCs result from thresholds crossed
- Pump generates pressure with FVR closed
- Camshaft driven
- If cam is late, pump piston is late
- FRV timing same (relative to crank angle)
 - *FVR driven closed with more piston stroke*
 - *More stroke, more pressure*




Determining Cycle time



Known-Good Capture




Suspect-Engine Capture



Results



- Camshaft 5 degrees retarded (**Stretched**)
- Late camshaft = higher-than-desired FRP
- Low volume HP fuel system
- Justified disassembly
- No Timing DTCs?
 - *11 deg. threshold for DTC was not crossed*
 - *Breathability not drastically effected*



BAD

GOOD


Delayed Camshaft Demonstration



Stepping-Stones from Preliminary Diagnostics

- **Causes of misfires:**

- Engine mechanical
 - *Compression*
 - *Breathability*
- Fuel Injectors
 - *Control*
 - *Spray pattern*
- Ignition system
 - *Primary*
 - *Secondary*
- Carbon issues
 - *VE*
 - *Density-misfires*



Ignition Waveform

- Combustion through the eyes of the scope
- Primary or secondary
- Efficiently obtained
- Applies to virtually all spark-ignition ICEs
 - *Become familiar with “good”*
 - *Bad becomes easily visible*




CAUTION: Use attenuation

Engine Mechanical Testing

- Pressure transducers can indicate flow characteristics
- Cranking-Intake waveforms
 - *WOT*
 - *Delta sensors*
 - *WPS-delta mode*




← SELECTABLE




Misfire Detection @ Tailpipe

- Combustion = Pressure @ EVO
- Misfire = Vacuum @ EVO
 - *Exhaust gas has inertia*
 - *Dollar-bill test*




Cranking Intake Waveform

- Comparison from one pull to the rest
- All pulls should be similar
- Look for the “odd-man-out”
 - *Zoom/filter appropriately*
 - *Partition the waveform*
 - *Compare pulls*
 - *Note pull for suspect cylinder*



In-cylinder Pressure Testing

- Carbon creates restriction
- Hinders cylinder fill
- Driving conditions dependent
 - *High flow reveals fault*
 - *Cylinder can't inhale*
 - *Induction creates negative pressure*



Approaching Low-Pressure Systems

- Fuel pressure bi-directional controls
- Pump trim reset
- Holding pressure
- Fuel pressure sensor accuracy
- Current ramping/Lab scope testing
- Action/Reaction testing



Scan Tool Testing Low-Pressure System...

- Scan DTCs
- Command vs actual
- Bi-directional controls
 - *Drive FPCM with scan tool*
 - *Monitor command duty-cycle*
 - *Monitor feedback duty-cycle*

GM V7.20

GM > Automatic selection > Control unit > Fuel pump control module > Active test

Fuel pump(Fuel pump control module)

Fuel pump command	70.0	%
Fuel pump command	69.8	%
Ignition 1 signal	14.3	V
5V reference 1	4.99	V
Desired fuel pressure	300	kPa
Fuel pressure sensor	579	kPa
Fuel pressure sensor	3.82	V
Fuel pump command	On	
Short term fuel pump trim	1.00	

VIN: 1G1PF5SCXC7270455
Info: GM/Chevrolet/Cruze



Fuel Pump Commands

- Varies per YEAR/MAKE/MODEL (**Service info**)
- Duty-cycle based
- Can compensate for issues (Fuel pump trim)
- Several example commands used
 - *Invalid/off*
 - *Normal operation*
 - *Full-ON*
 - *Valid/OFF*




Fuel Pump Monitor

- Varies per YEAR/MAKE/MODEL (**Service info**)
- Duty-cycle based
- Several commands used
 - *Invalid data received*
 - *Normal operation or SRS Event Invalid*
 - *Problem with secondary circuit (Fuel Pum*




Fuel Pump Trim Reset

- PCM can compensate for low-pressure system
- Communicate with FPCM
- Increased pump command
- **Must be reset after repairs**




Scope Testing Low-Pressure System...

- Action / Reaction testing
- FPDM easy access (Configuration)
- Bypass testing
- Multi-channel lab scope
 - *Current = Pump circuit*
 - *Voltage = Command FPCM-to-Pump*
 - *Voltage = Request PCM-to-FPCM*
 - *Voltage = Voltage FPCM-to-PCM feedback*




Current = Work Performed


- Monitor Pump operation
 - *Pump speed*
 - *Pump average current*
 - *Pump armature health*



Low-Pressure Pump Wiring Diagram



- A DC x1 + Stopped
- B DC 20 A DSP + ±20 A
- C DC x1 + Off
- D DC x1 + Off



Trick Question...*How Does This Look?*




Stopped

Timebase 20 ms/div Samples 800 kS Sample rate 4 MS/s Trigger None Waveform 1 of 1

Guided tests Auto setup Open Save Print Vehicle details Full


- A DC x1 Off
- B DC 20 A DSP ±20 A
- C DC x1 Off
- D DC x1 Off

- More...
- Rulers
- Measurements
- Views
- Notes
- Channel labels
- Waveform library
- Math channels





319.2 μs = .0003192 mS
60,000 (mS in a minute)/.000319
= 187,969,924 RPM?!

Variable Speed Fuel Pump



We need the pump to run at 100%





**W-WE DON'T HAVE ENOUGH
DILITHIUM CRYSTALS**


Fuel pump(Fuel pump control module)

Fuel pump command	70.0	%
Fuel pump command	69.8	%
Ignition 1 signal	14.3	V
5V reference 1	4.99	V
Desired fuel pressure	300	kPa
Fuel pressure sensor	579	kPa
Fuel pressure sensor	3.82	V
Fuel pump command	On	
Short term fuel pump trim	1.00	

Bi-Directional = 70% Max



VIN: 1G1PF5SCXC7270455
Info: GM/Chevrolet/Cruze

Increase Decrease ESC



I'm giving her all she's got, Captain!


Bypass Test: *Jump the Supply*



**Yes! Let's Jump the B+ & B-
from the FDCM directly to
the fuel pump**



Got It!



Approaching the High-Pressure System Fault

- Rail pressure
 - *Effected by RPM*
 - *Effected by Duty-cycle*
 - *Effected by INJPW*
- Process of elimination
- Proper signal to solenoid
- Accurate FRP signal
- No leaks
- Healthy mechanical drive
- **HPFP replacement... ONLY after all has been proven**




Hot-Soak FRP Monitoring

- Pressure should increase with heat
- Low-volume / High pressure
- If pressure decays over time
 - *Past injector*
 - *Past HPFP check valve (pump failure)*
 - *Past HPFP (into crankcase)*




HPFP Deadhead Test

- Configuration dependent
 - *Normally-open*
 - *Normally-closed*
- Highest stress on HPFP
 - *Low rpm (idle)*
 - *Full stroke utilized*
 - *Highest pressure/toughest conditions*




Results: Dead-Head Testing





A/F Ratio Imbalance DTCs (P219A or P219B)

- Rich or lean cylinder-to-cylinder imbalance
- HO2 sensor frequency and amplitude characteristics
 - *Closed loop*
 - *Warmed-up*
 - *No EVAP enrichment*
- Intake / Exhaust modifications, leaks
- Poor injector spray patterns
- HO2 or WRAF performance
- Fuel contamination
- Combustion quality (mechanical / ignition?)

Normal A/F




Failure A/F



GDI Injector Balance Testing...

- Relative flow characteristics
- Helps single out cause of misfire
- Right from the driver's seat!
- Scan tool Bi-directional control
 - *Differs from port injection*
 - *Analysis of test results tedious*



Unanticipated Test Sequence

- Obtain and record pressure drop for each injector
- Calculate total injector-drop (omit suspect injector)
- Find average pressure-drop
- Multiply by 0.20 (20% acceptable variance)
- **Can't exceed acceptable variance**



Delta-Lambda Demonstration

- Scan Tool Bi-Directional Test
- Disable Each Injector One at a Time
- Monitor EQ_Ratio / Lambda
- Compare Lambda Change of Each Cylinder
- Three Vehicle Demonstration
- Port Injection with Wide-Band Sensor
- GDI Injection with Narrow-Band Sensor
- GDI Injection with Wide-Band Sensor



2019 Ford Flex 3.5L
Port Fuel Injector Balance
Wide Band Sensor




Cylinder #1 Disable

- Port Injection with Wide-Band Sensor

• EQ_Ratio (Lambda) = 1.22


• Downstream Sensor = .01(V)

• Short Term Fuel Trim = 22%




Cylinder #2 Disable

- Port Injection with Wide-Band Sensor
- EQ_Ratio (Lambda) = **1.20**
- Downstream Sensor = **.01(V)**
- Short Term Fuel Trim = **24%**




Cylinder #3 Disable

- Port Injection with Wide-Band Sensor
- EQ_Ratio (Lambda) = **1.23**
- Downstream Sensor = **.01(V)**
- Short Term Fuel Trim = **24%**




Cylinder #4 Disable

- Port Injection with Wide-Band Sensor
- EQ_Ratio (Lambda) = **1.27**
- Downstream Sensor = **.01(V)**
- Short Term Fuel Trim = **29%**




Cylinder #5 Disable

- Port Injection with Wide-Band Sensor
- EQ_Ratio (Lambda) = **1.20**
- Downstream Sensor = **.01(V)**
- Short Term Fuel Trim = **21%**



Cylinder #6 Disable

- Port Injection with Wide-Band Sensor
- EQ_Ratio (Lambda) = **1.18**
- Downstream Sensor = **.01(V)**
- Short Term Fuel Trim = **23%**



2019 Chevy Malibu 1.5L


GDI Injector Balance with Narrow Band Sensor

- GDI with Narrow-Band Sensor
- No EQ_Ratio
- Commanded EQ_Ratio Stays @ 1.00 in Closed Loop
- Compare Upstream Sensor (V), STFT
& Rail Pressure (Preferably Voltage)



Cylinder #1 Disable

- GDI with Narrow-Band Sensor
- HO2S 1 (V) = **.01**
- HO2S 2 (V) = **.01**
- Short Trim Fuel Trim = **24%**
- Fuel Rail Pressure Sensor = **561 PSI**




Cylinder #2 Disable

- GDI with Narrow-Band Sensor
- HO2S 1 (V) = **.01**
- HO2S 2 (V) = **.01**
- Short Trim Fuel Trim = **23%**
- Fuel Rail Pressure Sensor = **565 PSI**



Cylinder #3 Disable

- GDI with Narrow-Band Sensor
- HO2S 1 (V) = **.01**
- HO2S 2 (V) = **.01**
- Short Trim Fuel Trim = **23%**
- Fuel Rail Pressure Sensor = **565 PSI**



Cylinder #4 Disable

- GDI with Narrow-Band Sensor
- HO2S 1 (V) = **.01**
- HO2S 2 (V) = **.01**
- Short Trim Fuel Trim = **23%**
- Fuel Rail Pressure Sensor = **565 PSI**






**2016 Kia Soul 1.6L
GDI Injector Balance
Wide Band Sensor**


Cylinder #1-Disable

- Required Lambda: **1.39?**
- Actual Lambda: **1.55**
- Cylinder #2 Injector On-Time: **1.6ms**




Cylinder #2-Disable

- Required Lambda: **1.39?**
- Actual Lambda: **1.39**
- Cylinder #1 Injector On-Time: **1.6ms**




Cylinder #3-Disable

- Required Lambda: **1.39?**
- Actual Lambda: **1.57**
- Cylinder #1 Injector On-Time: **1.6ms**



Cylinder #4-Disable

- Required Lambda: **1.39?**
- Actual Lambda: **1.43**
- Cylinder #1 Injector On-Time: **1.6ms**




Scope Testing High-Pressure Pump (FVR)...

- Action / Reaction testing
- Access varies between vehicles
- Multi-channel lab scope
 - *Current = Pump circuit*
 - *Voltage = Command PCM-to-FVR*
 - *Voltage = Ground PCM-to-FVR*



CAUTION: Use attenuation

HPFP Wiring Diagram






**2016 Kia Soul 1.6L
High Fuel Pressure
Regulator Control**


HPFP FVR Control...

- Trend view
- Multiple cycles on screen
- Cycle-to-cycle comparison
- Four waveforms tell the story
 - *FVR current*
 - *FVR Voltage feed control*
 - *FVR Ground feed control*
 - *Primary Ignition (for reference)*




ZOOM 1

- Zoom in to one complete cycle
- Better resolution
 - *Cylinder-to-cylinder comparison*
 - *FVR control*



ZOOM 2

- Zoom in to one single event
- Better resolution
 - *Frequency of pulses*
 - *Pulse-width*
 - *Pintle bump*
 - *Inductive kick*





Scope Testing Direct Injectors...

- Action / Reaction testing
- Access varies between vehicles
- Multi-channel lab scope
 - *Current = Injector circuit*
 - *Voltage = Command PCM-to-Injector*
 - *Voltage = Ground PCM-to-Injector*




CAUTION: Use attenuation

Direct Injectors Wiring Diagram




Scope Testing Direct Injectors...




GDI Injector

- 2 Wire Solenoid
- Scope Leads On High & Low
- Control Circuits
- Check Voltage & Current
- Drivers' Ability To Turn On
- Shorted Coil
- Pintle Hump?
- Comparative Analysis



Testing Induction System For Leaks

- Visual inspection
- Smoke testing
- Propane




CAUTION: High Pressure

Post-Fix Verification

- Repeat failed-tests
- Reduces/eliminates comebacks
 - *OBD status*
 - *Scan data PIDs*
 - *Bi-directional control*
 - *Driveability road test*
 - *Smoke testing*
 - *Propane testing*
 - *Gas analysis*

The Diagnostic Approach



Maintenance Is Critical

- Maintain ECU software levels
- Use quality materials and fluids
- Use the CORRECT filters and fluids
 - *Follow service specifications*
 - *Follow proper service intervals*
 - *Induction system maintenance?*



Carbon Issues

- Direct-Injection
- Blow-by / PCV system
- Poor maintenance
- Temperatures
- Countermeasures:
 - *Pour-in treatments (oil/fuel)*
 - *Fog-in treatments*
 - *Media blasting*



Chemical Treatments

- Best used as preventive maintenance (**Service info!**)
- Not great as a “Fix”
- Chemically dissolves carbon and limits production
- Not all are created equally
 - *Sticky rings*
 - *Collapsed lifters*
 - *Stuck phasers*
 - *Stuck OCVs*
 - *Noisy tensioners*
 - *Cleans port and Direct injectors*



Pressurized Treatments

- Best used a preventive maintenance (**Service info!**)
- Can be used as a “Fix”
- Uses staged chemicals for different carbon types
 - *Three chemicals*
 - *Strategized delivery*
 - *Pulsed pneumatically*



Media Blasting

- Not recommended for preventive maintenance
- Great for restoring proper engine operation
- Labor intensive
- Messy process
- Instant return-on-investment
 - *Walnut shells*
 - *Dry-ice / Nitrogen*




Low-Speed Pre-Ignition

- GDI vaporizes oil
- Higher compression
- Turbo charging
- High load conditions
- Auto-ignition of oil droplets




Depressurizing Fuel System

- High-Pressure fuel system can reach **200 Bar**
- Fuel can pierce skin and damage components
 - *Ouch!*
 - *Poisoned*
- Scan tool command
- Disable HPFP FVR and run engine



Follow Service Repair Information!

- Replace components as prescribed
- Pressurized / atomized fuel
- Won't see "drips"
- **Best to test with HC detection**



2006 MazdaSpeed6




Extended Crank & No Power

VIN #: JM1GG12LX61103470
Diagnosed: 8-14-17

Fault Code Retrieved

- P0012 (Bank 1)
- Actual Cam Timing is 10° Retarded from Target
- 5 Seconds or More
- Oil Control Valve in Feed-back Range
- ECT Above 20°C (68°F)




P0012 | Intake Cam Position Timing Over Retarded Bank 1



Camshaft Sensor Reluctor

Scan Data


- Rail pressure set value = **725 PSI**
- Actual value of rail pressure = **47 PSI**
- **Fuel pressure gauge verifies good low-pressure**
- No high pressure = **Low Power**



Determine cause of low rail pressure

Significance of Cam Timing

- Camshaft timing is critical
 - *ECM (DME) uses cam sensor signal for pressure control*
 - *Incorrect cam timing = Wrong pressure control timing*





Checking Camshaft Timing...

- Don't Disassemble
- Scope all the Things!
- Oscilloscope Waveform
 - *Crankshaft Vs Camshaft Signal*
 - *Reference Known Good & Compare*




Crankshaft vs. Camshaft Correlation





Crankshaft vs. Camshaft Correlation

- No “MazdaSpeed 6” reference available
- 2007 CX-7 is identical
 - *Never assume!*
 - *Good enough for us to proceed*




High Pressure Fuel Pump Control Circuits

- Current Flow Increases or Decreases Pressure
- Circuit Faults Could Cause Low Pressure
- Scope Needed for Dynamic Test
 - *Blue Trace = Ground Side Control*
 - *Red Trace = Voltage Control*
 - *Green Trace = Control Current*



High Pressure Fuel Pump Control Circuits



Justified Invasive Inspection...

- Physical Inspection Required
- Check Tappet Wear/Damage
- Camshaft Lobe or Drive Wear/Damage
- Pump Damage
- Final Elimination Step



Fuel Pump Tappet Missing



Broken Camshaft



This Part of
the Camshaft

Is Not Attached
To This Part



2006 Mazdaspeed6

Low Power And Backfiring During Cruise & Acceleration




VIN #:

JM1GG12LX61103470

Mileage: 122,066

Retrieved Fault Codes

- The P0012 DTC is not new
- The symptoms are new
 - *Is the P0012 Related?*




LET'S RIDE!



Road Test

MakeAGIF.com

Did We Duplicate The Symptom?



What Does It Mean?

- Commanded EQ-Ratio: **1.027**
- EQ-Ratio: **.781**
- O2S Bank 1-Sensor 1 Current: **-2.182 mA**
- O2S Bank 1-Sensor 2 (V) **.955 V**
- Short Term Fuel Trim: **-24.1%**



We Did Duplicate The Concern? *Yes!*


- Ran well for a minute then ran rough.
- The symptoms became more severe.
- The symptoms were present at idle, when we returned to the shop.

Let's Work Through This!

- **Commanded Equivalence Ratio = approx. 1.00** (Requesting stoichiometry)
- **Equivalence Ratio = < 1.00** (Rich condition)
- **The Upstream WRAF = -2.18 mA** (Rich condition)
- **The Downstream HO2S = >950 mv** (Rich condition)
- **STFT = -25%** (Compensating for a rich condition)


New Data Set *How About Now?*

- **FRP = ZERO**, during running condition
 - *1700 psi...*
 - *Then 0 psi...*
 - *Then back to 1700 psi in 5 frames?*




Rich condition... with no fuel rail pressure?

What's Next?




Pinpoint Test:

Measuring the Circuit vs. Processed Scan Data...



Pinpoint Test:

Measuring the Circuit vs. Processed Scan Data...



Why measure all three circuits?


Pinpoint Test:

Measuring the Circuit vs. Processed Scan Data...



Test Lead Connection

Does This Agree With Our Processed Data?



What possibilities are present?

Pin Drag Test

- Drag test “passes”
- Process of elimination
- Sensor requires replacement
 - *Needs fuel rail assembly*
 - *Includes FRP sensor*
 - *Follow service procedures*



Scan Data After Fuel Rail Replacement

- **The Vehicle Is Fixed!**
- **No Apples-To-Apples Comparison**
- **No Fuel Rail Pressure Dropout**





We still have a variable cam timing fault, but the client declined to investigate. We were disappointed to say the least!



2014 Chevrolet Silverado 1500 5.3L

Rough Running & Low Power After Transmission Replacement

VIN: 3GCUKRECEXEG469764

Mileage: 134,261

Diagnosed 6/27/22

Back Story

- **Runs rough two days after transmission repair**
- **Two different dealerships “couldn’t figure it out”**
- **Our client (shop owner) found oxygen sensor unplugged & melted**
- **Replaced sensor with aftermarket part but no change**


Topology

List

DTCs: 10

100%

Not scanned Pass Fault No response



FAULT SCAN

MOST Bus LS_CAN Object_CAN HS_CAN PE_CAN C_CAN

VIN: 3GCUKRECEXEG469764
Info: GM/Chevrolet/Silverado

Remote Expert Intelligent diagnostics Report Quick erase Fault scan Enter system ESC

Retrieved Fault Codes

- Engine misfire
- O2S Bank 2 – Sensor 1+2 DTCs
- Performance or circuit DTCs?
- Fuel trim DTC
 - *Misfire cause or effect?*

The screenshot displays a diagnostic report for a 2014 GM vehicle. The interface includes a top navigation bar with icons for home, settings, and other functions. The main content area is titled "2014 GM Vehicle Diagnostic Report" and shows "DTC details" for the "Engine control module(4 DTCs)". A table lists four DTCs with their descriptions and status information.

Codes	Description	Status
P0300:00	Engine misfire detected	DTC history status : Not history Since DTC clear : Passed and failed Last test : Failed current DTC This ignition cycle : Not run MIL status : Not requested
P0152:00	Heated oxygen sensor circuit high voltage bank 2 sensor 1	DTC history status : Not history Since DTC clear : Passed and failed Last test : Failed current DTC This ignition cycle : Not run MIL status : Not requested
P0157:00	Heated oxygen sensor circuit low voltage bank 2 sensor 2	DTC history status : History Since DTC clear : Passed and failed Last test : Failed current DTC This ignition cycle : Not run MIL status : Requested
P0175:00	Fuel trim system rich bank 2	DTC history status : Not history Since DTC clear : Passed and failed Last test : Failed current DTC This ignition cycle : Not run MIL status : Not requested

VIN: 3GCUKRECEG469764
Info: GM/Chevrolet/Silverado

ESC

Misfire Data

- Is there a trend **(YES!)**
- Let the data guide you
- Low-hanging fruit
- What is common to misfiring cylinders
 - *They're All On Bank 2!*

Name	Value	Range	Units
<input type="checkbox"/> Engine speed	550	[0...8000]	RPM
<input type="checkbox"/> Cyl. 1 current misfire counter	0	[0...255]	Counts
<input type="checkbox"/> Cyl. 2 current misfire counter	14	[0...255]	Counts
<input type="checkbox"/> Cyl. 3 current misfire counter	0	[0...255]	Counts
<input type="checkbox"/> Cyl. 4 current misfire counter	25	[0...255]	Counts
<input type="checkbox"/> Cyl. 5 current misfire counter	0	[0...255]	Counts
<input type="checkbox"/> Cyl. 6 current misfire counter	14	[0...255]	Counts
<input type="checkbox"/> Cyl. 7 current misfire counter	0	[0...255]	Counts
<input type="checkbox"/> Cyl. 8 current misfire counter	25	[0...255]	Counts
<input type="checkbox"/> Vehicle speed sensor	0	[0...255]	km/h
<input type="checkbox"/> MIL requested by DTC	Yes		

0 items selected

Cancel All Show Selected Graph Merge To Top Setting Clear Data Freeze Record Review Back

VCM!

52% 9:19

Engine Data Comparison

- Symptoms Present?
- Data Agree With Codes?
- Misfires: Cause Or Affect?

Name 9 items selected	Value	Range	Units
<input checked="" type="checkbox"/> Short term fuel trim bank 1	-4	[-100...100]	%
<input checked="" type="checkbox"/> Long term fuel trim bank 1	1	[-100...100]	%
<input checked="" type="checkbox"/> Short term fuel trim bank 2	-25	[-100...100]	%
<input checked="" type="checkbox"/> Long term fuel trim bank 2	-22	[-100...100]	%
<input checked="" type="checkbox"/> Fuel control loop status	Closed		
<input checked="" type="checkbox"/> HO2S bank 1 sensor 1	0.74	[0...1]	V
<input checked="" type="checkbox"/> HO2S bank 1 sensor 2	0.7	[0...1]	V
<input checked="" type="checkbox"/> HO2S bank 2 sensor 1	1.04	[0...1]	V
<input checked="" type="checkbox"/> HO2S bank 2 sensor 2	0	[0...1]	V

Cancel All Show all Graph Merge To Top Setting Clear Data Freeze Record Review Back

VCMI 49% 9:34

Be There With Me!

- Runs Rough In Closed Loop
- Clears Up In Open Loop



- **General experience**
 - *Bank 2 Sensor1 is highly suspect*
- **Models specific experience**
 - *Replacement HO2 sensor heater relearn?*



HO2 Sensor Heater Resistance Learn

- ECM pulse width modulates HO2S heater
- Resistance increases over time
- Performance degrades over time
 - *ECM compensates*
 - *Relearn needed with new sensor*

HEATED OXYGEN SENSOR RESISTANCE LEARN RESET CAUTION (DANGERS, WARNINGS, AND CAUTIONS)

Heated Oxygen Sensor Resistance Learn Reset Caution

Caution: When replacing the HO2S perform the following:


- A code clear with a scan tool, regardless of whether or not a DTC is set
- HO2S heater resistance learn reset with a scan tool, where available

Perform the above in order to reset the HO2S resistance learned value and avoid possible HO2S failure.

© 2014 General Motors. All rights reserved.

Special Function: HO2S Heater Learn Walk-Through

- Go To Special Functions
- Click HO2S Heater Resistance Learned Value Reset



Special Function: HO2S Heater Learn-Walk Through

GM V7.20

GM > Automatic selection > Auto scan > Engine control module > Special function

VCM 12.6V

HO2S heater resistance learned values reset(Heated oxygen sensor)

HO2S heater resistance learned values reset	Reset	-
HO2S heater bank 1 sensor 1	0.00	mA
Fuel control loop status	Open	
HO2S bank 1 sensor 1	1.89	V
HO2S bank 1 sensor 2	1.90	V
HO2S bank 2 sensor 1	1.89	V
HO2S bank 2 sensor 2	1.84	V
HO2S heater command bank 1 sensor 1	0	%
HO2S heater command bank 1 sensor 1	Off	

VIN: 3GCUKRECEG469764
Info: GM/Chevrolet/Silverado

Reset ESC

Click Reset

Special Function: HO2S Heater Learn Walk-Through

- Go To Special Functions
- Click HO2S Heater Learn

The screenshot displays the GM VCM software interface. At the top, it shows 'GM V7.20' and a navigation path: 'GM > Automatic selection > Auto scan > Engine control module > Special function'. The main area is titled 'Special function' and contains a grid of options. A red arrow points from the instructions on the left to the 'HO2S heater learn' option, which is highlighted with a red box. Other options in the grid include 'Brake pedal position sensor learn', 'Crankshaft position variation learn', 'Engine oil life reset', 'Fuel trim reset', 'HO2S heater resistance learned values reset', 'HO2S learned values reset', 'Idle learn', and 'Remote vehicle start disable history reset'. The bottom of the screen shows the VIN '3GCUKRECEG469764', the vehicle info 'Info: GM/Chevrolet/Silverado', and an 'ESC' button.

Special function		
Brake pedal position sensor learn	Crankshaft position variation learn	Engine oil life reset
Fuel trim reset	HO2S heater learn	HO2S heater resistance learned values reset
HO2S learned values reset	Idle learn	Remote vehicle start disable history reset

Special Function: HO2S Heater Learn-Walk Through

GM V7.20

GM > Automatic selection > Auto scan > Engine control module > Special function

H02S heater learn(Heated oxygen sensor)

H02S heater learn	Learn	-
Fuel control loop status	Open	
H02S bank 1 sensor 1	1.89	V
H02S bank 1 sensor 2	1.90	V
H02S bank 2 sensor 1	1.89	V
H02S bank 2 sensor 2	1.86	V
H02S heater command bank 1 sensor 1	0	%
H02S heater command bank 1 sensor 1	Off	
H02S heater command bank 1 sensor 2	0	%


VIN: 3GCUKRECEG469764
Info: GM/Chevrolet/Silverado

Learn ESC

Click Learn

Special Function: Fuel Trim Reset Walk-Through

- Go To Special Functions
- Click Fuel Trim Reset



Special Function: Fuel Trim Reset Walk-Through

GM V7.20

GM > Automatic selection > Auto scan > Engine control module > Special function

VCM 15.1V

Fuel trim reset(Fuel trim)

Fuel trim reset	Reset	-
Short term fuel trim bank 1	0	%
Long term fuel trim bank 1	0	%
Short term fuel trim bank 2	0	%
Long term fuel trim bank 2	0	%
Fuel trim learn	Disabled	
Fuel trim memory cell	14	
Fuel trim system test state	Running	
Short term fuel trim test average bank 1	0	%

VIN: 3GCUKRECEG469764
Info: GM/Chevrolet/Silverado

Reset ESC

Click Reset

Data After Relearn

- Not Graphed But...
- Both Upstream O2S Switching
- Both Downstream O2S Agree
- Bank 1 Total Fuel Trim: -1%
- Bank 2 Total Fuel Trim: -4%

Name 9 items selected	Value	Range	Units
<input checked="" type="checkbox"/> Short term fuel trim bank 1	4	[-100...100]	%
<input checked="" type="checkbox"/> Long term fuel trim bank 1	-5	[-100...100]	%
<input checked="" type="checkbox"/> Short term fuel trim bank 2	2	[-100...100]	%
<input checked="" type="checkbox"/> Long term fuel trim bank 2	-6	[-100...100]	%
<input checked="" type="checkbox"/> Fuel control loop status	Closed		
<input checked="" type="checkbox"/> HO2S bank 1 sensor 1	0.09	[0...1]	V
<input checked="" type="checkbox"/> HO2S bank 1 sensor 2	0.7	[0...1]	V
<input checked="" type="checkbox"/> HO2S bank 2 sensor 1	0.35	[0...1]	V
<input checked="" type="checkbox"/> HO2S bank 2 sensor 2	0.61	[0...1]	V

Cancel All Show all Graph Merge To Top Setting Clear Data Freeze Record Review Back

← Home App Store Camera VCM! Car Person 38% 10:15

Data After Relearn

No Cylinder
Misfires Present!

Name	Value	Range	Units
Engine speed	556	[0...8000]	RPM
Cyl. 1 current misfire counter	0	[0...255]	Counts
Cyl. 2 current misfire counter	0	[0...255]	Counts
Cyl. 3 current misfire counter	0	[0...255]	Counts
Cyl. 4 current misfire counter	0	[0...255]	Counts
Cyl. 5 current misfire counter	0	[0...255]	Counts
Cyl. 6 current misfire counter	0	[0...255]	Counts
Cyl. 7 current misfire counter	0	[0...255]	Counts
Cyl. 8 current misfire counter	0	[0...255]	Counts
Vehicle speed sensor	0	[0...255]	km/h
MIL requested by DTC	No		

0 items selected

Cancel All Show Selected Graph Merge To Top Setting Clear Data Freeze Record Review Back

VCM!

45% 9:50

Runs Great But...



Name	Value	Range	Units
<input checked="" type="checkbox"/> Short term fuel trim bank 1	2	[-100...100]	%
<input checked="" type="checkbox"/> Long term fuel trim bank 1	-5	[-100...100]	%
<input checked="" type="checkbox"/> Short term fuel trim bank 2	7	[-100...100]	%
<input checked="" type="checkbox"/> Long term fuel trim bank 2	-6	[-100...100]	%
<input checked="" type="checkbox"/> Fuel control loop status	Closed		
<input checked="" type="checkbox"/> HO2S bank 1 sensor 1	0.73	[0...1]	V
<input checked="" type="checkbox"/> HO2S bank 1 sensor 2	0.71	[0...1]	V
<input checked="" type="checkbox"/> HO2S bank 2 sensor 1	1.05	[0...1]	V
<input checked="" type="checkbox"/> HO2S bank 2 sensor 2	0.69	[0...1]	V

The Bank 2 upstream sensor still climbs over 1 volt

Update: GM HO2 Sensor Installed

- **Genuine HO2 Sensor Installed**

- *Cleared Up After Installing A Genuine Sensor*
- *Yes, They Relearned The New Sensor*
- *Runs Well & Never Returned*






2017 Kia Soul 1.6L

Rough Idle & Stall

VIN: **KNDJN2A2XH7880354**

Mileage: **98,438**

WHO'S
THE
BOSS?



Runs Rough, No Power & Stalling

- Shop replaced HO2S (No change)
- Shop requests ECM reprogramming
- TSB available to correct concern
- Will a software update fix it?
- The client is “The Boss”


Checking The VIN#

- The VIN in the module **Matches** the vehicle
- Not an unprogrammed used module




Getting the Calibration Number

- Is there an update available?
 - *Sometimes a comparison is needed*
 - *Current calibration vs latest calibration*
 - *Some programming applications auto-compare*
- **Vehicle manufacturer & programming application dependent**



Checking For Update Hyundai / Kia GDS

- There are no updates for our module?
- Old application could be a factor
 - *Former factory scan tool*
 - *KDS is current factory scan tool*
 - *KDS is tablet based*
 - *Hyundai vs Kia, separate interface*



Retrieved DTCs

P0030 | HO2S Heater Control Circuit Bank 1 Sensor 1

- Finding the root-cause problem
- P0030 “Heater control fault” DTC
- Wide-band application
 - *Heater’s more critical than with narrow-band*
 - *Could be massive clue*

DTC • G 2.0 NU GDI • Engine > Engine Control • P0030 HO2S Heater Control Circuit (Bank 1 / Sensor 1) • DTC Information

[Report a problem with this article](#)

DTC Description

The PCM monitors the Heated Oxygen Sensor (HO2S) heater circuit. If the PCM detects an open in the heater control circuit, the PCM sets DTC P0030.

DTC Detecting Condition

Item	Detecting Condition	Possible Cause
DTC Strategy	• Electrical check.	1. Poor connection 2. Open circuit 3. HO2S (S1)
Enable Conditions	• Ignition ON.	
Threshold Value	• Open circuit	
Diagnostic Time	• Continuous.	
Mil On Condition	• 2 driving cycles.	

Freeze Frame Data

- Data recorded when DTC sets
- Always document
- Understanding conditions is helpful
- Especially helpful for “intermittents”
 - *Data may offer clues*

Start Communication

✕ Exit

ID: \$	E8	P0030 HO2S Heater Control Circuit Bank 1 Sensor 1	
ENGINE SPEED(1/min)	73	ABSOLUTE THROTTLE POSITION(%)	17.3
ABSOLUTE THROTTLE POSITION B(%)	17.3	RELATIVE THROTTLE POSITION(%)	7.8
COMMANDED THROTTLE ACT.CONTROL(%)	10.2	ACCELERATOR PEDAL POSITION D(%)	14.5
ACCELERATOR PEDAL POSITION E(%)	7.5	TIME SINCE ENGINE START(s)	2
COMMANDED EQUIVALENCE RATIO	1.999	FUEL SYSTEM 1	OPEN LOOP
FUEL SYSTEM 2	NOT USED	AMBIENT AIR TEMPERATURE (°F)	68
INTAKE AIR TEMPERATURE (°F)	89	ENGINE COOLANT TEMPERATURE (°F)	134
INTAKE MAP (inHg)	26.5	BAROMETRIC PRESSURE (inHg)	29.5
IGNITION TIMING ADVANCE (°)	9.0	SHORT TERM FUEL TRIM BANK 1(%)	0.0
LONG TERM FUEL TRIM BANK 1(%)	0.0	FUEL LEVEL INPUT	73.3
COMMANDED EVAPORATIVE PURGE	0.0	FUEL RAIL PRESSURE (psi)	1064.3
VEHICLE SPEED (mph)	0	CALCULATED LOAD VALUE(%)	82.0
ABSOLUTE LOAD VALUE(%)	63.5	CONTROL MODULE VOLTAGE(V)	12.316

12.2 V

No Active Vehicle

How's It Running?



Misfire Data

The screenshot displays the 'Misfire Data' window in a diagnostic software interface. The window title is 'Diagnostic Suite'. The main area shows a list of parameters and their values:

Parameter	Value
Battery Voltage (V)	13.15
Misfire Current Cylinder #1 (Counts)	0
Misfire Current Cylinder #3 (Counts)	0
Total Counter of Emission Relevant Misfiring of Cy... (Counts)	0
Total Counter of Emission Relevant Misfiring of Cy... (Counts)	0
Total Counter of Catalyst Damaging Misfiring of Cy... (Counts)	0
Total Counter of Catalyst Damaging Misfiring of Cy... (Counts)	0
Total Counter of Emission Relevant Misfiring of All... (Counts)	0
Misfire Cycle Delay Reason	NO_DELAY
Misfire Current Cylinder #2 (Counts)	0
Misfire Current Cylinder #4 (Counts)	0
Total Counter of Emission Relevant Misfiring of Cy... (Counts)	0
Total Counter of Emission Relevant Misfiring of Cy... (Counts)	0
Total Counter of Catalyst Damaging Misfiring of Cy... (Counts)	0
Total Counter of Catalyst Damaging Misfiring of Cy... (Counts)	0
Total Counter of Catalyst Damaging Misfiring of All... (Counts)	0

The interface includes a menu bar with options like Exit, Custom, Alarms, Properties, Graph View, Save, Print, Scale, Sweep, and Next Data Group. At the bottom, there is a control bar with a play/pause button, a close button, a counter showing '55', and search icons. The system tray at the bottom right shows the time as 9:56 AM on 6/14/2024 and the vehicle information as '2017 Kia Soul' with a battery voltage of '13.5 V'.

ZERO Misfires?

Global Data

- Is the fault present? (Did we duplicate the concern?)

- *Yes! Difficult to keep running*

- How can we tell?

- *Engine RPM*
 - *Load*
 - *Manifold pressure*
 - *Throttle position*
 - *Fuel rail pressure*
 - *Loop status*
 - *EQ-ratio & HO2S current, etc.*

- Does this data offer us direction?

- *Yes! remember the fault code?*

The screenshot shows a diagnostic tool interface with a menu bar (Exit, Custom, Alarms, Properties, Graph View, Save, Print, Scale, Sweep) and a data table. The table is divided into two sections for engine IDs E8 and E9. The 'O2S CURRENT BANK 1-SENSOR 1(mA)' value for E8 is circled in red.

ID : \$			
		ENGINE SPEED(1/min)	314
ABSOLUTE THROTTLE POSITION(%)	54.1	ABSOLUTE THROTTLE POSITION B(%)	54.1
RELATIVE THROTTLE POSITION(%)	44.7	COMMANDED THROTTLE ACT.CONTROL(%)	59.6
ACCELERATOR PEDAL POSITION D(%)	14.5	ACCELERATOR PEDAL POSITION E(%)	7.5
TIME SINCE ENGINE START(s)	15	COMMANDED EQUIVALENCE RATIO	0.999
FUEL SYSTEM 1	OPEN LOOP FAULT	FUEL SYSTEM 2	NOT USED
AMBIENT AIR TEMPERATURE (°F)	68	INTAKE AIR TEMPERATURE (°F)	80
ENGINE COOLANT TEMPERATURE (°F)	84	INTAKE MAP (inHg)	29.5
BAROMETRIC PRESSURE (inHg)	29.5	IGNITION TIMING ADVANCE (°)	6.0
SHORT TERM FUEL TRIM BANK 1(%)	0.0	LONG TERM FUEL TRIM BANK 1(%)	0.0
O2S VOLTAGE BANK 1 - SENSOR 2(V)	0.450	SHORT TERM FUEL TRIM B1-S2(%)	NOT USED
EQUIVALENCE RATIO B1-S1 (-:1)	1.014	O2S CURRENT BANK 1-SENSOR 1(mA)	0.000
COMMANDED EVAPORATIVE PURGE	0.0	FUEL RAIL PRESSURE (psi)	1442.7
VEHICLE SPEED (mph)	0	CALCULATED LOAD VALUE(%)	80.8
ABSOLUTE LOAD VALUE(%)	71.8	NR OF WARM-UPS SINCE DTCs CLEARED	0
MIL STATUS	ON	DISTANCE WHILE MIL ACTIVE (mi)	0
DISTANCE SINCE DTCs CLEARED (mi)	0	CONTROL MODULE VOLTAGE(V)	12.128
EVAP SYSTEM VAPOR PRESSURE (Pa)	114.00	OBD REQUIREMENTS	OBD-II (CARB)
FUEL TYPE	GAS (PETROL)	SECONDARY LONG TERM FUEL TRIM B1(%)	0.0
ID : \$(2)		ENGINE SPEED(1/min) (E9)	638
ABSOLUTE THROTTLE POSITION(%) (E9)	-52.4	TIME SINCE ENGINE START(s) (E9)	44
ENGINE COOLANT TEMPERATURE (°F) (E9)	87	VEHICLE SPEED (mph) (E9)	0
CALCULATED LOAD VALUE(%) (E9)	83.6	NR OF WARM-UPS SINCE DTCs CLEARED (E9)	0
MIL STATUS (E9)	OFF	DISTANCE WHILE MIL ACTIVE (mi) (E9)	0
DISTANCE SINCE DTCs CLEARED (mi) (E9)		CONTROL MODULE VOLTAGE(V) (E9)	

Visual Inspection Is Key



The upstream sensor was unplugged!

Throttle Held OPEN to Prevent Stall...

- Intake MAP = Barometric Pressure
- Engine Stalling
- Very Open Throttle
- Commanded Open
- No Driver Request



▼	INTAKE MAP (inHg)	29.5
▼	BAROMETRIC PRESSURE (inHg)	29.5
▼	ENGINE SPEED(1/min)	314
▼	ABSOLUTE THROTTLE POSITION B(%)	54.1
▼	COMMANDED THROTTLE ACT.CONTROL(%)	59.6
▼	ACCELERATOR PEDAL POSITION E(%)	7.5

We disconnected throttle, engine now runs. We can gather & analyze data

Global Data After Connecting HO2S

- Is it fixed? Are we finished?

- *No!*

- Is it in fuel control?

- *No!*

- How can we tell?

- *Commanded EQ-ratio = 1.0 whilst EQ-ratio > 1.00*

- Is the ECM trying?

- *Yes, closed loop & positive fuel trims*

The screenshot shows a diagnostic tool interface with a menu bar at the top containing: Start Communication, Exit, Custom, Alarms, Properties, Graph View, Save, Print, Scale, and Sweep. The main area is a data table with two columns. The left column lists various engine parameters, and the right column lists their current values. Two red boxes highlight specific data points: 'COMMANDED EQUIVALENCE RATIO' with a value of 0.999 and 'EQUIVALENCE RATIO B1-S1 (-1)' with a value of 1.831. The bottom of the screen shows a navigation bar with a home icon, a list icon, a search icon, and a status bar indicating 'No Active Vehicle' and '13.7 V'.

Parameter	Value
ID: \$	E8
ABSOLUTE THROTTLE POSITION(%)	19.2
RELATIVE THROTTLE POSITION(%)	10.2
ACCELERATOR PEDAL POSITION D(%)	14.5
TIME SINCE ENGINE START(s)	32
FUEL SYSTEM 1	CLOSED LOOP
AMBIENT AIR TEMPERATURE (°F)	68
ENGINE COOLANT TEMPERATURE (°F)	96
BAROMETRIC PRESSURE (inHg)	29.9
SHORT TERM FUEL TRIM BANK 1(%)	23.4
O2S VOLTAGE BANK 1 - SENSOR 2(V)	0.450
EQUIVALENCE RATIO B1-S1 (-1)	1.831
CATALYST TEMPERATURE B1-S1 (°F)	232
ENGINE SPEED(1/min)	923
ABSOLUTE THROTTLE POSITION B(%)	19.6
COMMANDED THROTTLE ACT.CONTROL(%)	13.7
ACCELERATOR PEDAL POSITION E(%)	7.5
COMMANDED EQUIVALENCE RATIO	0.999
FUEL SYSTEM 2	NOT USED
INTAKE AIR TEMPERATURE (°F)	80
INTAKE MAP (inHg)	25.1
IGNITION TIMING ADVANCE (°)	14.0
LONG TERM FUEL TRIM BANK 1(%)	0.0
SHORT TERM FUEL TRIM B1-S2(%)	Not Used
O2S CURRENT BANK 1-SENSOR 1(mA)	1.582
FUEL LEVEL INPUT	75.0

Enhanced Data Comparison

- Commanded Lambda vs Actual Lambda = **Lean**
- Upstream sensor voltage instead of mA = **Lean**
- HO2S binary downstream = **Lean**
- Elevated fuel rail pressure = **Lean Compensation**
- Elevated GDI injector on-time = **Lean Compensation**


The screenshot displays the 'Diagnostic Suite' interface for a '2017 Kia Soul'. The 'Intake & Exhaust Data' section is active, showing a list of various engine parameters. Several parameters are highlighted with red boxes:

- Battery Voltage (V)**: 13.55
- O2 Sensor Linear Type Bank 1 Upstream (Option) (V)**: 2.89
- O2 Sensor Binary Type Bank 1 Downstream (Option) (V)**: 0.024
- Required Lambda**: 1.00
- Actual Lambda Value (%)**: 1.369
- Fuel Rail Pressure Set Point (psi)**: 1218.1

The interface includes a menu bar with options like Exit, Custom, Alarms, Properties, Graph View, Save, Print, Scale, Sweep, and Next Data Group. The bottom status bar shows the vehicle model '2017 Kia Soul', battery voltage '13.8 V', and the date '10:00 AM 6/14/2024'.

Understanding High-Pressure System & Verifying Inputs


- Some Default To high Pressure
- Most Default To Low Pressure
 - *Disconnect HPFP Regulator & Monitor Rail Pressure*
 - *Compare To Low Pressure (74 psi)*
 - *Low pressure PID alone not conclusive*



Fuel Delivery System		
Items	Specification	
Fuel Tank	Capacity	54 lit. (14.3 U.S.gal., 57.1 U.S.qt., 47.5 Imp.qt.)
Fuel Filter	Type	Paper type
Fuel Pressure	Low Pressure Fuel Line	480 ~ 520 kPa (4.89 ~ 5.30 kgf/cm ² , 69.6 ~ 75.4 psi)
	High Pressure Fuel Line	2.0 ~ 15.0 MPa (20.4 ~ 153.0 kgf/cm ² , 290.1 ~ 2175.6 psi)
Fuel Pump	Type	Electrical, in-tank type
	Driven by	Electric motor
High Pressure Fuel Pump	Type	Mechanical type
	Driven by	Camshaft


RC Test For Mechanical Integrity

- Quick mechanical integrity test
- Ignition sync for ID & timing
- **Include intake pressure = Powerful combination**
 - *Even starter amperage peaks*
 - *Sufficient peak-to-valley delta*
 - *Even intake pulls*
 - *Ignition timing = Good*




Ignition Analysis (Cylinder #1)

- Cylinder 1 primary ignition voltage
- Primary ignition current
 - *No ignition misfire present*
 - *Other potential clues present*




Ignition Analysis (Cylinder #2)

- Cylinder 2 primary ignition voltage
- Primary ignition current
 - *No ignition misfire present*
 - *Other potential clues present*




Ignition Analysis (Cylinder #3)

- Cylinder 3 primary ignition voltage
- Primary ignition current
 - *No ignition misfire present*
 - *Other potential clues present*



Ignition Analysis (Cylinder #4)

- Cylinder 4 primary ignition voltage
- Primary ignition current
 - *No ignition misfire present*
 - *Other potential clues present*




Other Characteristics

- Barely runs
- Will idle with throttle disconnected
- Not in fuel control but trying
- Lean condition
 - *Adequate rail pressure*
 - *Engine mechanically sound*
 - *Ignition okay*



Propane Enrichment...



Monitor feedback sensors for accuracy & determine if driveability improves

Smooth As Silk!



Watching The Improvements...

10 items selected	Name	Value	Range	Unit
<input checked="" type="checkbox"/>	\$7E8 Fuel system A status	CL		
<input checked="" type="checkbox"/>	\$7E8 Short term fuel trim (bank 1)	23.44	-100...99.22	%
<input checked="" type="checkbox"/>	\$7E8 Long term fuel trim (bank 1)	0	-100...99.22	%
<input checked="" type="checkbox"/>	\$7E8 Intake manifold absolute pressure	35	0...255	kPa
<input checked="" type="checkbox"/>	\$7E8 Engine rpm	1054	0...8000	rpm
<input checked="" type="checkbox"/>	\$7E8 Oxygen sensor output voltage (bank 1 sensor 2)	0.45	0...1.275	V
<input checked="" type="checkbox"/>	\$7E8 Fuel rail pressure	849.92	0.00...95050.46	psi
<input checked="" type="checkbox"/>	\$7E8 Equivalence ratio (lambda) (bank 1 sensor 1)	1.168	0...1.999	
<input checked="" type="checkbox"/>	\$7E8 Fuel/air commanded equivalence ratio	0.999	0...1.999	
<input checked="" type="checkbox"/>	\$7E8 Relative throttle position	91	0...100	%

Cancel All Show all Graph Merge To Top Setting Clear Data Freeze Record Review Back

10 items selected	Name	Value	Range	Unit
<input checked="" type="checkbox"/>	\$7E8 Fuel system A status	CL		
<input checked="" type="checkbox"/>	\$7E8 Short term fuel trim (bank 1)	3.12	-100...99.22	%
<input checked="" type="checkbox"/>	\$7E8 Long term fuel trim (bank 1)	0	-100...99.22	%
<input checked="" type="checkbox"/>	\$7E8 Intake manifold absolute pressure	5.8	0.00...36.98	psi
<input checked="" type="checkbox"/>	\$7E8 Engine rpm	1010	0...8000	rpm
<input checked="" type="checkbox"/>	\$7E8 Oxygen sensor output voltage (bank 1 sensor 2)	0.45	0...1.275	V
<input checked="" type="checkbox"/>	\$7E8 Fuel rail pressure	675.88	0.00...95050.46	psi
<input checked="" type="checkbox"/>	\$7E8 Equivalence ratio (lambda) (bank 1 sensor 1)	0.999	0...1.999	
<input checked="" type="checkbox"/>	\$7E8 Fuel/air commanded equivalence ratio	0.999	0...1.999	
<input checked="" type="checkbox"/>	\$7E8 Relative throttle position	91	0...100	%

Cancel All Show all Graph Merge To Top Setting Clear Data Freeze Record Review Back

Injector On-Time

Injection Time-Inj. 1 (ms)	2.46	Injection Time-Inj. 2 (ms)	2.46
Injection Time-Inj. 3 (ms)	2.46	Injection Time-Inj. 4 (ms)	2.46
Fuel Adaption (Idle)-Bank 1 (%)	0.000	Battery Voltage (V)	13.42
Fuel Adaption (Part Load)-Bank 1	1.000	Lowpass Filtered Fuel Tank Pressure (psi)	0.0
Fuel Tank Pressure Voltage (Option) (V)	2.534	The Number of MSV on the Engine	1
Filtered Rail Pressure Real Value (Absolute Pressure) (psi)	1216.6	Fuel Rail Pressure Sensor Voltage (V)	1.7
Angle to Close FPR (Fuel Pressure Regulator) (°)	30.6	Angle to Open FPR (Fuel Pressure Regulator) (°)	-4.0
Fuel Rail Pressure Set Point (psi)	1218.1	Status of Noise Reduction Stage	1
Reduced Current Parameter: Adaptation of T1 Ready (ms)	-0.299	Ignition Output Value-Cyl. 1 (°)	0.00
Ignition Output Value-Cyl. 2 (°)	0.00	Ignition Output Value-Cyl. 3 (°)	0.00
Ignition Output Value-Cyl. 4 (°)	0.00		

Before

0 items selected		Name	Value	Unit
<input type="checkbox"/>	Injection time - Injector 1		0.82	ms
<input type="checkbox"/>	Injection time - Injector 2		0.82	ms
<input type="checkbox"/>	Injection time - Injector 3		0.82	ms
<input type="checkbox"/>	Injection time - Injector 4		0.82	ms
<input type="checkbox"/>	Emission GasTemperature Sensor Value		-459.58	°F
<input type="checkbox"/>	Differential Pressure Valve Position Sensor Value		0	V
<input type="checkbox"/>	Differential Pressure Valve Position Value		0	%
<input type="checkbox"/>	Differential Pressure Sensor(DPS) Value(SENT)		0	
<input type="checkbox"/>	Differential Pressure		0	psi
<input type="checkbox"/>	Altitude adaptation value		0.984	
<input type="checkbox"/>	Barometric pressure		14.576	psi

After

CONDEMNED

This _____ is unsafe and its use
has been prohibited

PROPERTY ADDRESS

DATE


OWNER'S NAME

BUILDING OFFICIAL

Recommend What?

This Card Must Not Be Removed Under Penalty Of Law





2014 Ford Fusion 2.0L EcoBoost


Limited Throttle Response



VIN # **3FA6P0K97ER373325**

Mileage: **51,649**

Scan DTCs + Visual Inspection



No Codes Present




Actual vs. Commanded Throttle?

Accelerator-Pedal Increases In Both Boxes


PCM Not Commanding A Throttle Increase

Throttle-Position Is Not Increasing



Consider the Clues + Narrow Our Focus


- PCM sees throttle request (APP)
- PCM ignores request
 - *Rules out APP circuit faults*




Is this a default strategy?

PCM Default Strategy?

- Why no DTCs?
- Why's the PCM ignoring the APP?
 - *Desired vs actual low side fuel pressure?*
 - *Desired vs actual fuel rail (high side) pressure?*
 - *Desired vs actual cam timing?*
 - *Desired vs actual boost/map pressures?*
 - *Desired vs actual EQ ratio (Air/Fuel ratio's)*



Another Look at Scan Data



A Potential Clue

- Okay, we're not Sherlock Holmes
- Is this the brake pedal switch button?
 - *If so, that explains the brake switch PID*



Testing Our Theory



Removed Brake Switch




Button Missing



Temporarily Closed Switch

Success



A Missed Clue: *Check Codes In All Modules*

Code Scan + SureTrack®

Back Print Refresh

SureTrack® > Results for C0040-64

Verified parts replacement data not available.

Code Scan Results : Systems detected : 25

Side Obstacle Detection Control Module - Right - Codes : 0

Steering Column Control Module - Codes : 0

Seat Module - Driver - Codes : 0

Antilock Brakes:

C0040-64 | Brake Pedal Switch "A" - Signal Plausibility Failure - Current DTC - Warning Lamp On. **Fix It!**

Power Steering Control Module:

U0415-00 | Invalid Data Received From Anti-Lock Brake System (ABS) Control Module - Not Current DTC. **Fix It!**

2014 Ford Fusion Titanium (FWD)

A silver 2019 Honda CRV is shown from a front-three-quarter view, parked on a paved surface. The car is wet, with water droplets visible on its hood and roof. In the background, there is a calm pond reflecting the sky, surrounded by lush green trees under a bright, slightly overcast sky. A white text box is overlaid on the lower half of the image, containing the car's model and a description of a problem.

2019 Honda CRV

Cold Start Rough Running

VIN# 2HKRW5H34KH420089
Mileage: 60,804

Codes Retrieved

- P0300 Random cylinder misfire
- P0302 Cylinder 2 misfire
- P0303 Cylinder 3 misfire
- DTCs match symptoms
 - *Probably Related*

Honda > Automatic selection > Auto scan 12.8V

2019 Honda Vehicle Diagnostic Report

DTC details

1. PGM-FI(3 DTCs)

Codes	Description	Status
P0300	Random Misfire	Confirmed DTCs
P0302	No2 Cylinder Misfire	Confirmed DTCs
P0303	No3 Cylinder Misfire	Confirmed DTCs

2. ABS/VSA(1 DTC)

Codes	Description	Status
U0401-68	(ECM Failure)	Confirmed DTCs

3. Multiplex Integrated Control Unit(1 DTC)

Codes	Description	Status
U128D	Relay control module lost communication with gauge control module(VSP/NE frame)	Confirmed DTCs

4. EPS(1 DTC)

Codes	Description	Status
U0416-68	(VSA system malfunction)	Confirmed DTCs

Cold Start Misfire Data

- Runs rough at start-up
- Misfires correlate with DTCs
- Common causes of cold start misfire:
 - *Leaking Fuel Injector*
 - *Head Gasket Leaks*
 - *Carbon*

Name	Value	Unit
<input type="checkbox"/> Cyl3 Total Misfire	8	
<input type="checkbox"/> Cyl4 Total Misfire	0	
<input type="checkbox"/> Cyl1 Misfire	0	
<input type="checkbox"/> Cyl2 Misfire	4	
<input type="checkbox"/> Cyl3 Misfire	8	
<input type="checkbox"/> Cyl4 Misfire	0	
<input type="checkbox"/> Misfire Cycle	281	
<input type="checkbox"/> Cyl1 Misfire B	0	
<input type="checkbox"/> Cyl2 Misfire B	4	
<input type="checkbox"/> Cyl3 Misfire B	8	
<input type="checkbox"/> Cyl4 Misfire B	0	

3 items selected


Cancel All Show Selected Graph Merge To Top Setting Clear Data Freeze Record Review Back

VCMI 18% 10:48


Cylinders 2 & 3 are misfiring

Monitoring For Leaking Injectors...


- Very Little Fuel Rail Volume
- Normal Pressure Release = Injectors Only
 - *Engine Off = No Injection Event*
 - *Engine Off = No Pressure Drop*
- Piston Pump Should Hold Pressure For Extended Period
- Under Hood Heat Will Cause Short Term Increase




Monitoring For Leaking Injectors...




Monitoring For Leaking Injectors...



Monitoring For Leaking Injectors...



Monitoring For Leaking Injectors...



527 PSI-drop After 26 Minutes

What are some possibilities?

Another Justified *Arrow In the Target*



All For One & One For All!

ProDemand Automotive Repair | x Home | Assured Auto Works x Greg Alayon | RO #9164 | Assure: x +

www1.prodemand.com/Main/Index#2019|Honda|CR-V|2.4L%20Eng|LX|Gas|Eng%20CD%20K24W9|4D%20Utility|FWD|Not%20Applicable%20T%2FCas...

SEARCH FIXES AVI OnDemand - Tr... WORLDPAC - spee... Manufacturers | Oe... Ross-Tech Wiki Home | Assured Au... Trade Offers and Pr... Other bookmarks


ProDemand Change Vehicle 2019 Honda CR-V 2.4L Eng LX Recalls/Campaigns CONTACT SETTINGS LOGOUT

Remove & Replace Print X

Fuel Injector 1 of 2


NOTE:

- Where icon is shown continue to the information below.
- Refer to the [Emissions Systems Service Precautions](#) before disconnecting the fuel line.
- Fuel may cause flammable gas leaks and may result in fire. Keep sparks, flame and cigarettes away.
- When replacing the injector, you must replace all injectors on the fuel rail as a set and the fuel joint pipe. Failure to do so will cause poor engine performance and fuel leaks.




We recommended & Replaced All 4 Injectors


Post Repair Data & Codes



Rail Pressure After Shut Off



10 Minutes Later



Runs Well & No Codes

A meme featuring a man in a dark suit and white shirt, wearing a headset microphone, shouting with his mouth wide open. In the background, a woman with dark hair is visible, looking towards the camera. The scene is set outdoors with a blue sky and green foliage. The text "I EAT SUCCESS FOR BREAKFAST" is overlaid at the bottom in a bold, white, sans-serif font with a black outline.

**I EAT SUCCESS
FOR BREAKFAST**

A silver Honda CR-V is parked on a paved surface. The car is the central focus, with a pond and a line of trees in the background. The text 'They're Back!' and 'Same Symptoms!' is overlaid in a large, red, handwritten-style font across the middle of the car.

They're Back!
Same Symptoms!

VIN# 2HKRW5H34KH420089

Mileage: 60,804

Diagnosed: April 2023



Duplicate & Retrieve Codes

< Diagnostic Trouble Code ⋮

HONDA V47.71 > 16PIN DLC > Health Report

PGM-FI/ Diesel(Engine System)	DTC (2)	Enter
P0303 Misfire No.3 Cylinder	Current PGM-FI	
P0303 Misfire No.3 Cylinder	Temporary PGM- FI	
ABS(Anti-Lock Braking System)	DTC (1)	Enter
U0401-68 ECM Failure	Current ABS	
EPS(Electric Power Steering)	DTC (1)	Enter
U0416-68 VSA System Malfunction	Current EPS	
AT(Automatic Transmission)	Normal	Enter

Search Report Help

Continue Clear DTCs Rescanning

Cylinder 3 Again!

FRP Decay



Coolant Leaking in Cylinder #3

- Removed cylinder #3 spark plug
- Verified fluid in cylinder #3
- Initially assumed fluid was fuel
 - *Determined fluid was anti-freeze*
 - *Video scope confirmed leaking head gasket*



Where Did We Go Wrong?

- Initially, misfired at cold start-up
- Fuel decay was determined to be injector leak down
- Fuel decay gone with injector replacement

- **Vehicle returns with same symptom**
- **Fuel pressure decay returns...leak is confirmed to be head gasket (?)**



**2010 Buick Lacrosse 3.6L
Runs Rough & Fuel Odor**

VIN: 1G4GE5EVXAF325394

Mileage: 91,31

Diagnosed: Jan 2019

Stored DTCs

GDS 2

DTC Display

Create Report Add Bookmark

Status	Control Module Name	Control Module Status	DTC Count	DLC Pin
	Engine Control Module	DTCs Stored	5	6,14

Control Module	DTC	Symptom Byte	Description	Symptom Description	Status
Engine Control Module	P0300	00	Engine Misfire Detected	- - -	Current
Engine Control Module	P0305	00	Cylinder 5 Misfire Detected	- - -	Current
Engine Control Module	P0300	00	Engine Controls Ignition Relay Feedba...	- - -	Passed and Failed
Engine Control Module	P0300	00	Engine Misfire Detected	- - -	Passed and Failed
Engine Control Module	P0305	00	Cylinder 5 Misfire Detected	- - -	Passed and Failed

This Ignition Cycle
Last Test
Since DTC Clear
DTC History Status
MIL Status

- Rough running & cylinder misfire
- Probably Related

Clear DTCs Refresh


Back Contact Us Home Vehicle Menu Enter

GDS 2 v.20.3.05100 GM Global v2019.1.2 VIN: 1G4GE5EVXAF325394 2010,Buick,LaCrosse,Module Diagnostics,Engine Control Module,Diagnostic Trouble Codes (DTC) CarDAQ-M 13.6 V

5:35 PM 1/29/2019


Current Misfire Data...

- Idle speed
- Cylinders 1 or 2
 - *No misfires*




Current Misfire Data...

- Idle seed
- Cylinders 3 or 4
 - *No misfires*




Current Misfire Data

- Idle Speed
- Cylinders 5 or 6
 - *Lots of Cylinder 5 Misfires*
 - *Smoke at tailpipe*
 - *No Cylinder 6 Misfires*




History Cylinder Misfires...



22 = Historic cylinder 1 misfires

0 = Historic cylinder 2 misfires


History Cylinder Misfires...



0 = Historic cylinder 3 misfires

19 = Historic cylinder 4 misfires

History Cylinder Misfires




4700 = Historic cylinder 5 misfires

0 = Historic cylinder 6 misfires

This Seat Is Comfortable... I Think I'll Stay For a While


- Start pinpoint test or analyze?
- Strategy or a legitimate
- **Very helpful data parameter**



Engine Data...

- Idle speed

- *Fuel rail pressure 4.5 MPa = 652 PSI*
- *5.38 gram/second*
- *CEQ_ratio = 1.00*



The screenshot shows the 'Data Display' window in GDS 2, displaying 'Fuel System Data'. The data is presented in a table with columns for Parameter Name, Value, Unit, and Control Module. The 'Engine Speed' row is highlighted with a red box, showing a value of 702 RPM. Other parameters include Fuel Rail Pressure Sensor (4.5 MPa), MAF Sensor (5.38 g/s), and Air/Fuel Equivalence Ratio Command (1.00).

Parameter Name	Value	Unit	Control Module
Fuel Rail Pressure Regulator Command	129	*	Engine Control Module
Fuel Pump Enable Command	On		Engine Control Module
Fuel Rail Pressure Sensor	4.5	MPa	Engine Control Module
Fuel Rail Pressure Sensor	4.5	MPa	Engine Control Module
Engine Speed	702	RPM	Engine Control Module
ECT Sensor	51	°C	Engine Control Module
IAT Sensor	28	°C	Engine Control Module
MAF Sensor	5.38	g/s	Engine Control Module
Engine Load	36.1	%	Engine Control Module
Accelerator Pedal Position	0	%	Engine Control Module
Throttle Position	10	%	Engine Control Module
BARO	101.0	kPa	Engine Control Module
Air/Fuel Equivalence Ratio Command	1.00		Engine Control Module
Fuel Volatility	Low		Engine Control Module
Power Enrichment	Inactive		Engine Control Module
Deceleration Fuel Cut-Off	Inactive		Engine Control Module
Fuel Tank Pressure Sensor	0.12	in H2O	Engine Control Module

Engine Data...

- Bank 1 STFT: -25
- Bank 1 LTFT: -43%
- Total Bank 1 fuel trim: -68%
- Bank 2 STFT: -7
- Bank 2 LTFT: -15%
- Total Bank 2 fuel trim: -22%
- *Massive correction*
- *Generally, fuel-side failure*

The screenshot shows the GDS 2 software interface with the 'Data Display' window open. The 'Fuel Trim Data' section is selected, and a table of parameters is displayed. A red box highlights the following data:

Parameter Name	Value	Unit	Control Module
Short Term Fuel Trim Bank 1	-25	%	Engine Control Module
Short Term Fuel Trim Bank 2	-7	%	Engine Control Module
Long Term Fuel Trim Bank 1	-43	%	Engine Control Module
Long Term Fuel Trim Bank 2	-15	%	Engine Control Module
Long Term Fuel Trim Idle/Deceleration Bank 1	1505	%	Engine Control Module

The rest of the table shows various engine parameters such as 'Fuel Trim Learn' (Disabled), 'Fuel Pump Enable Command' (On), and 'Average Total Fuel Trim Bank 1' (-58%). The software interface includes a top menu bar with 'Create Report' and 'Add Bookmark' buttons, and a bottom status bar showing 'GDS 2 v.20.3.05.100', 'GM Global v2019.1.2', 'VIN: 1G4GE5EVXAF325394', '2010 Buick, LaCrosse, Module Diagnostics, Engine Control Module', 'CarDAQ-M', '14.5 V', and the date/time '5:40 PM 1/29/2019'.

What Does The Data Show Us?

- HO2S = “Rich”
- Bank 1 injectors on-time = 0.53 mS
- Bank 2 injectors on-time = 0.96 mS
 - *Result of negative fuel trim*
 - *Cylinder-to-Cylinder differences*
 - *Transient or A/F-imbalance compensation*


The screenshot shows the 'Data Display' window in GDS 2, specifically the 'Fuel Trim Data' section. The data is presented in a table with columns for Parameter Name, Value, Unit, and Control Module. A red box highlights the injector command values for cylinders 1 through 6.

Parameter Name	Value	Unit	Control Module
HO2S Bank 1 Sensor 1	0.68	V	Engine Control Module
HO2S Bank 1 Sensor 2	0.78	V	Engine Control Module
HO2S Bank 2 Sensor 1	0.73	V	Engine Control Module
HO2S Bank 2 Sensor 2	0.83	V	Engine Control Module
Cylinder 1 Injector Command	0.54	ms	Engine Control Module
Cylinder 2 Injector Command	0.99	ms	Engine Control Module
Cylinder 3 Injector Command	0.52	ms	Engine Control Module
Cylinder 4 Injector Command	0.93	ms	Engine Control Module
Cylinder 5 Injector Command	0.52	ms	Engine Control Module
Cylinder 6 Injector Command	0.96	ms	Engine Control Module
Power Enrichment	Inactive		Engine Control Module
Deceleration Fuel Cut-Off	Inactive		Engine Control Module
EVAP Purge Solenoid Valve Command	0	%	Engine Control Module
Engine Speed	896	RPM	Engine Control Module
ECT Sensor	72	°C	Engine Control Module
IAT Sensor	27	°C	Engine Control Module
MAF Sensor	6.13	g/s	Engine Control Module

Dribbling Injectors?

Justified Fuel Injector Balance Test

- Cranking test
- Test incomplete
- Insufficient rail pressure



The screenshot displays the GDS 2 interface for a Fuel Injector Balance test. The test parameters are listed in a table below, showing values of 0 for all fuel pressure drop measurements and 0.1 MPa for the fuel rail pressure sensor. The error message is highlighted in a red box.

Parameter Name	Value	Unit	Control Module
Fuel Pressure Drop - Cylinder 1 Injector	0	kPa	Engine Control Module
Fuel Pressure Drop - Cylinder 2 Injector	0	kPa	Engine Control Module
Fuel Pressure Drop - Cylinder 3 Injector	0	kPa	Engine Control Module
Fuel Pressure Drop - Cylinder 4 Injector	0	kPa	Engine Control Module
Fuel Pressure Drop - Cylinder 5 Injector	0	kPa	Engine Control Module
Fuel Pressure Drop - Cylinder 6 Injector	0	kPa	Engine Control Module
Fuel Pump Enable Command	Off		Engine Control Module
Fuel Rail Pressure Sensor	0.1	MPa	Engine Control Module
Fuel Rail Pressure Sensor	0.51	V	Engine Control Module
ECT Sensor			

Device Limits Exceeded
Maximum Crank Time Exceeded. Fuel System Operating Pressure Cannot be Achieved.

OK

Back Contact Us Home Vehicle Menu Enter

GDS 2 v.20.3.05100 GM Global v2019.1.2 VIN: 1G4GE5EVXAF325394 2010,Buick,La Crosse,Module Diagnostics,Engine Control Module,Control Functions,Fuel System CarDAQ-M 13.1 V 5:29 PM 1/29/2019

Ready to Make a Call

- Active cylinder 5 misfire
- No ECM-disabled injector
- Fuel odor present
- Substantial negative fuel trims
- Can't run injector balance
 - *Can't build rail pressure*
 - *Rail pressure dives with Engine "off"*



#1



#3



#5




Verification of Repair

- Injector Replacement
- Engine Runs Good
- Fuel Trims Good
- Engine Light Re-Illuminated



Post-Fix Scan

- P0420
- Suspect catalyst damage from leaking injector
 - *Client was warned before injector replacement*
 - *Declined additional testing*





2009 Mini Cooper 1.6L Turbo

Cranks / No Start

VIN: WMWMF73519TW87529

Mileage: 89,514

Diagnosed: March 2022

Back Story

- Injectors replaced recently
- Not recent enough to assume faulty
- Ran well for months
 - *Shop replaced dead battery*
 - *Shop replaced spark plugs (no change)*
 - *Shop determined no injector control*



DTCs Retrieved

- MAF DTCs
- Appears intermittent (not current)
 - *Could be self-induced*
 - *No obvious diagnostic direction*
 - *Remember, battery was replaced*

MINI V8.30

MINI > Automatic selection > Auto scan

2009_07 MINI Vehicle Diagnostic Report

System	Count	Status
IHKS (Integrated Heating Or A/C Control)	0	Pass
RAD2-BO (Radio2-User Interface)	0	Pass
RAD2-GW (Radio2-Gateway)	0	Pass
SZL (Airbag-Steering Column Switch Cluster)	0	Pass
JBE (Junction Box Electronics)	0	Pass

DTC details

1. DME (Engine-Motor Electronics)(2 DTCs)

Codes	Description	Status
002B51	Digital Motor Electronics (DME), Mass Air Flow (MAF) sensor signal	Absent
002B5F	Digital Motor Electronics (DME), Mass Air Flow (MAF) sensor, correction signal	Absent

VIN: WMW MF73519TW87529
Info: MINI/MINI/Cooper S_N14/R56/USA_LL

ESC

BT 64% 9:39

Start-Attempt Data...

- Engine Speed visible

- *Crank Signal Likely Recognized*

Name	Value	Units
<input type="checkbox"/> Engine idle	Active	
<input type="checkbox"/> Actual value of engine speed	195	r/min
<input type="checkbox"/> Idle speed specified value	1190	r/min

0 items selected

Cancel All Show Selected Graph Merge To Top Setting Clear Data Freeze Record Review Back

BT 64% 9:43

Start Attempt (*Cranking*) Data...

- MAF: 9.6kg/h = 2.5 grams/second
- Seems close enough to start
- Barometric = 1005 mbar (29.67 inHg)
- Intake pressure after throttle = 988 kPa = 29.17 inHg

Name	Value	Units
<input type="checkbox"/> Mass air flow	9.6	kg/h
<input type="checkbox"/> Ambient pressure	1005.7	mbar
<input type="checkbox"/> Intake pipe vacuum after throttle valve (only n54/n55)	988.52	hPa
<input type="checkbox"/> Stop, throttle adaptation	Not adapted	
<input type="checkbox"/> Throttle valve angle, actual value	8.62	%
<input type="checkbox"/> Throttle valve angle, setpoint value	8.68	%

Cancel All Show Selected Graph Merge To Top Setting Clear Data Freeze Record Review Back

9:43 64%

Start Attempt (*Cranking*) Data

- Requested rail pressure = 725 psi
- Actual rail pressure = 47 psi
- Injector on-time 22mS
- Service info discrepancies
 - *A little low*
 - *Can we trust rail pressure values that low?*
 - *Maybe it's 72 psi & reporting 47 psi*

Name	Value	Units
<input type="checkbox"/> Adaptation value of fuel delivery control	0.98	
<input type="checkbox"/> Cylinder 1 fuel injection timing	22.37	ms
<input type="checkbox"/> Cylinder 2 fuel injection timing	22.3	ms
<input type="checkbox"/> Cylinder 3 fuel injection timing	22.14	ms
<input type="checkbox"/> Cylinder 4 fuel injection timing	22.3	ms
<input type="checkbox"/> Actual value of rail pressure	47.86	psi
<input type="checkbox"/> Rail pressure setpoint value	725.19	psi
<input type="checkbox"/> Duty factor of fuel quantity control valve	62.89	%

13 31 Fuel Pump with Drive and Pipe N14

with ignition "ON" and fuel pump running bar 5.0


VS

Fuel Pressure

Pressure 1 (PSI)		Pressure 2 (PSI)
Range	Note	Note
50.0	Y331	Y332
Y331: System pressure with engine idling. Y332: Fuel pump pressure.		


Code Scan: *Hoping For Clues*

- Low rail pressure issues?
- Hoping for a circuit fault
 - *No DTCs detected*



Experiment: *HPFP Open Circuit/Pressure Change*

- Default to high- or low pressure?
- Quick test
- Results could flush out fault
- Results might be inconclusive
- **No change exhibited**



The image shows a close-up of a fuel rail assembly with a diagnostic tool connected to it. The tool's screen displays a list of parameters with their current values and units. Two items are selected, indicated by blue checkmarks in the 'Name' column.


Name	Value	Units
<input type="checkbox"/> Adaptation value of fuel delivery control	0.98	
<input type="checkbox"/> Cylinder 1 fuel injection timing	21.5	ms
<input type="checkbox"/> Cylinder 2 fuel injection timing	21.62	ms
<input type="checkbox"/> Cylinder 3 fuel injection timing	21.43	ms
<input type="checkbox"/> Cylinder 4 fuel injection timing	21.58	ms
<input checked="" type="checkbox"/> Actual value of rail pressure	50.76	psi
<input checked="" type="checkbox"/> Rail pressure setpoint value	0	psi
<input type="checkbox"/> Duty factor of fuel quantity control valve	0	%

The software interface includes a bottom toolbar with icons for 'Cancel All', 'Show Selected', 'Graph Merge', 'To Top', 'Setting', 'Clear Data', 'Freeze', 'Record', 'Review', and 'Back'. The device's home indicator bar at the very bottom shows icons for home, app, camera, and VCM, along with a battery level of 61%.


Does low-pressure system appear to be working?

Pinpoint Test: *Measuring HPFP Control Circuits*

- High pressure system diagnostics
- Process of elimination
- No HPFP regulator circuit codes
 - *Circuit & control verification still critical*



Test Lead Placement




The Waveform – *The Result*

- **Blue trace:** HPFP regulator voltage control
- **Red trace:** HPFP regulator ground control
- **Green trace:** #4 injector high-side control
- **Gold Trace:** #4 injector low-side control
 - *Initial control activity stops*
 - *To build peak pressure?*
 - *Control & circuits appear okay*




Significance of Cam Timing

- Camshaft timing is critical
 - *ECM (DME) uses cam sensor signal for pressure control*
 - *Incorrect cam timing = Wrong pressure control timing*




Checking Camshaft Timing

- No DTCs
- Oscilloscope waveform
- Crankshaft signal vs camshaft signal
- Compare to known-good reference
 - *Initially Not Available*
 - *Moving On For Now*




Relative Compression with Sync...

- Using starter current to compare
- General engine mechanical test
 - *Incorrect Cam Timing = Incorrect Ignition Timing?*




Relative Compression with Sync

- Inline engine, camshaft timing will affect all
- **Cylinder 3 starter current low**
- Indicates weak cylinder 3 mechanical contribution
- Followed by weak intake pull due to slowed crankshaft
- Ignition timing close to TDC, indicates sufficient timing




Relative Compression with Sync...

- Now cylinder #4!
 - *Weak intake pull*
 - *Due to slowed crankshaft speed*



Relative Compression with Sync...

- Cylinder pressure added
- Cylinder #3, again!
 - *Could be added volume from compression hose*
 - *Weak intake pull due to slowed crankshaft speed*




Relative Compression with Sync...

Now Cylinder #2!




Relative Compression with Sync...

- Very Erratic
 - *Cylinder #1 is good*
 - *Then not good*




Relative Compression with Sync...

- Erratic Cylinder Integrity?
 - *Cylinder #3 not good*
 - *Then good, within 720 degrees*



Justified Checking Camshaft Timing...


- No DTCs
- Oscilloscope waveform
- Crankshaft Vs Camshaft Signal
- Reference Known Good & Compare
 - *Now Available*



Subject-Vehicle



Known Good




...Match Or Not?

An Assumption Was Made Early On.


What Was It?

- Rail pressure low
- Supply pressure seemed close enough (scan data)
- Erratic cylinder contribution – Not the cause
- Camshaft timing appears good



Checking Supply Pressure

- A costly assumption
- We thought understood the limitations
 - *“50 psi is close enough”*
 - *“It’s not accurate”*
 - *“I bet it’s actually closer to 70 psi”*
- 50 psi scan data = 0 psi actual pressure






Supply Pump Circuit Test




- Alternate-load test
- High current test light did not illuminate light
 - *Missing voltage supply or ground*
 - *Testing each independently*
 - *Revealed no voltage present*



Supply Pump Schematic & Component Location



Circuit Has Been *Bypassed!*



Junction Box Relay & Fuse Bypassed

**External Inline Fuse & Relay Installed
Corroded & Crusty**

No Voltage Upstream of Inline Fuse


Supply Pump Circuit Tests



Jump Voltage To Under Dash Circuit



Voltage Now Present @ Pump



It's Alive, Building Pressure
& Moving Fuel

It's Alive!



What About The Erratic Relative Compression?

- Cranking cadence smoothed out
- May still have intermittent mechanical issue
- *Not fuel-washed*
- *Possible valvetrain hydraulics*
- Not the cause of our concern
- Our client was advised



It's *Science* ...Not Magic

- Appears to be *wizardry*
- Understand the science of Computerized Fuel Injection
- Strategy to achieve a goal
- **Tools/Limitations, Fundamental knowledge, Information**



Training Must Always Continue

- Standards will change
- Strategies will change
- Systems and components will change
- Need for intelligent analysis will never change
- Master that which applies to everything
- Most important tool is a Technician's mind

