



Technicians Service Training

INSIDE THIS ISSUE:

"Asian Diagnostics"

P. 1 - 21

Upcoming

TST Big Event March 29th 2025

Bill Weaver

Josh Weaver

Eric Zigler

Keynote Carm Capriotto

Check out our YouTube channel [tstseminars](#)

Like us Facebook

Editor

"G" Jerry Truglia

© 2025 ATTS INC.

"Asian Diagnostics"

This article contains a mixed bag of some common Asian diagnostic tips and techniques on a variety of vehicles. As you read through the different vehicle problems, you will learn what diagnostic route I rode to diagnose and fix the concerns. In some of the different examples I will explain what I used to test and confirm that a component was either good or bad. Never just change a part; but rather test it, then move on to the next logical step in your diagnostic routine. And use what God gave us—our brain, eyes, ears, nose and hands. Combine that with good service information and you will have a successful diagnosis.

Toyota Camry P0171

One of the most common vehicles that shows up in our bays is the Toyota Camry. A common problem that this vehicle will display is an illuminated Malfunction Indicator Lamp (MIL) caused many times by a P0171 (System Lean-Bank 1) Diagnostic Trouble Code (DTC). As part of my usual diagnostic routine, I first performed a visual inspection on this particular Camry. I noticed that the Mass Airflow sensor (MAF) and Air Fuel Ratio sensor (AFS) had been replaced. Seeing a bunch of new parts on a vehicle that other shops have installed without resolving the problem is nothing new to me. Before replacing any sensor or actuator, the first thing to do is "test and not guess," confirming whether the

(Con't on page 3)

What is TST?

TST is a group of dedicated technicians and instructors committed to the continuing education of our fellow technicians. We provide training seminars to technicians at a reasonable price. TST brings our members nationally known instructors and state of the art training.

Our Goal & Mission Statement

- ***Keep our fellow technicians up to date with the latest technology.***
- ***Provide training seminars for a reasonable price.***
- ***Deliver information that the technician can use now.***
- ***Keep technicians informed of information affecting our industry.***
- ***Increase consumer awareness of what a good technician is.***

Why join TST?

TST membership includes special pricing on weekday night seminars and the occasional full Saturday seminar. With a **\$99.00 yearly individual or shop \$299.00 membership, the simulcast are only \$20.00. TST seminars are NOT sales or product seminars.** The instructors that TST brings in are all “hands-on” industry experts with up to date, cutting edge knowledge that you can use in your shop the next day. That’s 99 dollars for a seminar in which you are able to learn something useful, for fixing those tough jobs that we all see on a regular basis. Our instructors are masters at making the complex understandable. Membership also includes a newsletter full of real world technical articles, diagnostic case studies, and solutions to the kinds of problems you see in your bays each week.

The following are some of TST’s regular instructors:

Bernie Thompson of ATS

John Thornton of Autotrain Inc.

Wayne Colonna of ATSG

Jorge Menchu the “Labscope Guru,” AES Wave

John Anello of Auto Tech On Wheels

Mark Warren of World Pac / Motor Magazine

Brandon Steckler of CTI & Motor Age Magazine

Peter Meier of Motor Age Magazine

Ken Zanders of Illinois Air Team

"G" Jerry Truglia of A.T.T.S. Inc.



Technicians Service Training

**11 Lupi Plaza
Mahopac, NY 10541**

Phone: (845) 628-6928

Fax: (845) 628-9109

Email:

Info@tstseminars.org

**TST on YouTube...type
in tstseminars**

No part of this newsletter may be reproduced, stored in a retrieval system, or transmitted, in any form by any means, electronic, mechanical, photocopying, recording, or otherwise, without prior written permission of the authors.

Information contained in this newsletter is intended for use by professional auto repair technicians familiar with approved vehicle repair procedures. The authors are not responsible for physical injury or property damage resulting from the incorrect application of information or procedures outlined in this volume.

Currently there are **TST chapters in Connecticut, Massachusetts, New Jersey, New York** and membership continues to grow. For more information you can call **TST** headquarters at:

(845) 628-6928

www.TSTseminars.org

DORMAN TECHNICIAN TRAINING



YOU KNOW US FOR THE PARTS. NOW WE DELIVER THE SMARTS.

We are continuing to invest in the transportation aftermarket by offering in-person training throughout North America, and online training wherever you are. As vehicles are always changing, we are always releasing new solutions, and now that means both products and knowledge.

For additional information contact

DTC@DormanProducts.com.



Get vehicle applications and technical details at dormanproducts.com
Dorman Products, Inc. | Corporate Office and Customer Service: 1-800-523-2492 | Tech Line: 1-855-933-2911
©2021 No reproduction in whole or in part without prior written approval.

Curriculum Includes:

- **Critical Thinking-
Diagnostic Strategies**
- **P0420 & P0430 “Keeping
the Light Off”**
- **Unlocking the Potential of
Your Scan Tool**
- **Understanding
and Diagnosing Air
Conditioning**
- **20+ additional topics
available**

"Asian Diagnostics" (con't from p. 1)

components are operating in the proper range or not.

The important thing to know about the Toyota AFS sensor is at idle on a good running engine, the voltage reading on your scan tool should be 3.3 volts. To check the sensor, induce a vacuum leak to see if the sensor reading changes from the idle voltage reading. If the voltage reading goes up with an induced vacuum leak, the sensor is able to correctly read a lean condition. To check to see if the sensor is capable of reading a rich condition, add some propane to a vacuum port while making sure the voltage goes below 3.3 volts. Since the sensor tested good on both lean and rich conditions, I moved on to testing the MAF sensor.

To perform an MAF sensor test I like to use the EScan scan tool that makes testing the sensor easy. The scan tool has a Sharp Shooter tab that incorporates an easy test feature to test Volumetric Efficiency (VE). In order to perform this test properly all you have to do is input the correct engine size, temperature and elevation. Once the correct information has been typed in, drive the vehicle while depressing the throttle pedal to Wide Open Throttle (WOT) a few times. (Note: Perform this test from a rolling start in first gear, followed by a WOT acceleration through the second gear upshift. Do this in a safe section of road near your shop and always obey local traffic laws in the process.) The tool will display the results based on what the VE table calculations test results currently are compared to the actual results. This is a very accurate and time-saving test that allows me to confirm if I have an induction problem. Problems could be related to a clogged air filter, intake manifold, valve problem including carbon build up and even a clogged exhaust. The tool will graph two lines; the red line is based off the engine size, temperature and evaluation while the yellow line displays the test results. The example **(Figure 1)** displays a lower than acceptable reading along with turbulence on the yellow graph, indicating a clogged exhaust. If the test results were normal the yellow line would be over the red *(Con't on page 5)*

"Asian Diagnostics" (con't from p. 4)

line, indicating that the intake system was good.

Now if you don't have this tool, don't worry. You can perform a similar test, though not as accurate, by using any Generic/Global OBD II that graphs. Select the Calculated Load Parameter Identifier (PID) from the list and graph it. Once the selection is set up, start the engine and take the vehicle out for a test drive. You will need some clear space so you can depress the throttle pedal to it's WOT limits a few times. For safety reasons, make sure you are in a safe area and that someone else is driving while you are operating and viewing the scan tool test results. After achieving WOT a few times, it's time to view the graphed results of Calculated Load (**Figure 2**), making sure the graph obtained at least 90 percent at WOT.




Figure 1




Figure 2



a little deeper and do more research. I had completed my visual inspection, scan tool query and checked for Technical Service Bulletins (TSBs), but found nothing that provided information for my P0171. My next step was to check Identifix and iATN to see if there is any information that could assist me in solving this problem. Bingo! Identifix had some good information on the most common problems reported on the 2007 Toyota Camry. It reported the abnormal brake pedal feeling that I had experienced on one of my test drives. The Identifix information stated that sometimes there is a symptom of a hard or harder than normal brake pedal that is caused by a

(Con't on page 6)

"Asian Diagnostics" (con't from p. 5)

few ruptured diaphragm in the brake power booster. The scan tool data on Long Term Fuel Trim in Freeze Frame was at +7, indicating that there was a problem that can be from many different sources. I have come across some Toyotas that had a P0171 due to intake gasket problems, but the DTC usually sets when the engine temperature is cold. The Freeze Frame data indicated that the DTC on this vehicle occurred when the engine was at operating temperature so that ruled that problem out.

Since I already had the EScan connected to this vehicle, I thought that I would check the fuel trim at idle while I depressed the brake pedal as suggested in Identifix. On the EScan, there is a separate test for fuel trim that is located in the Sharp Shooter tab section (Figure 3 & 4) that would allow me to view live results in either Short Term Fuel Trim (STFT) or Long Term Fuel Trim (LTFT) as I depressed the brake pedal. As you can see from the test results on the tool, STFT at idle was high while I was depressing the brake pedal and good when my foot was off the pedal. This vehicle was diagnosed and repaired quickly with a little help from my friends at Identifix and with the replacement of the brake power booster.



Nissan Running Lean

Recently, a 2012 Nissan Altima P0171 came in from another shop that had already diagnosed the vehicle with a P0101 MAF sensor problem. Since this vehicle did not exhibit any driveability problems

(Con't on page 13)



GDI

Got Deposit Issues?

You need the Run-Rite® #1077 GDI Fuel System Cleaning Kit!

Offer a solution to your customer's deposit problems!

The Run-Rite® #1077 GDI Fuel System Cleaning Kit

removes deposits from valves, injectors and combustion chambers.

Use on Gasoline Direct Injection (GDI) and Port Injection Systems (PFI).

Safe for turbos and inter-coolers.

Fuel

Oil

Run-Rite® GDI Fuel System Cleaner
Run-Rite® GDI Oil System Treatment

Run-Rite® D.I.D.C.
 (Direct Injection Deposit Cleaner)

Removes Valve Deposits
 Reduces Combustion Chamber Deposits

Designed for GDI & PFI Fuel Systems

Safe for Turbos & Inter-coolers

Improves Fuel Economy

Keep Precision Oil Passages Clean

Kleen-Rite® Engine Cleaning

Reduces Deposits and Soot Buildup
 Promotes a more complete drain of oil

Helps Neutralize Combustion Acids

Improve Oil Changes



Run-Rite #1077 G.D.I. 3 Step Fuel System Cleaning Kit:
 8 kits per case (3 parts in each)

Kleen-Rite #3110 Ultimate ECD (Engine Cleaning Detergent)
 4 bottles per case (1 gallon each)

1.800.872.8921



www.Run-Rite.com

“THE SOURCE” FOR DIAGNOSTIC TEST PREP

Motor Age Training offers
the most complete and
extensive ASE Training
Series available anywhere

- Study guides
- Practice tests
- Detailed illustrations
- Available in your favorite format



YOU PASS OR YOU DON'T PAY!



**MOTOR AGE
TRAINING**



WE SUPPORT
PROFESSIONAL CERTIFICATION
THROUGH THE
National Institute for
**AUTOMOTIVE
SERVICE
EXCELLENCE**

www.passthease.com



X-431 Throttle III

X-431 Throttle III is Wi-Fi enabled and super advanced scan tool with upgraded all-in-one Smartlink VCI. One is Enough for most repair shops who has business in relation with ADAS calibration, Truck diagnosis, Remote diagnostic, OE-level vehicle diagnosis, IMMO functions and more.

WWW.LAUNCHTECHUSA.COM


1820 S. MILLIKEN AVE • ONTARIO, CA 91761 • PH : 1-877-528-6249

INTRODUCING THE *SWA-5D* A BREAKTHROUGH IN WHEEL ALIGNMENT TECHNOLOGY

The **SWA-5D** features a 5D imaging system that self-calibrates and mounts to any 2 post lift, with the option to hang from the ceiling for further space savings! It is easy to install and ultra-accurate. Included is an Android tablet display that also has the option to have our diagnostic software, for more added value and efficiency!

FEATURES & BENEFITS:

- Suspended 5D Design on 2 Post Lifts
- Hardware Designed in the US for all 2 post lifts
- Zero Shop Floor Footprint
- Self-calibrating with Center Camera
- Android Tablet with optional Scan Tool Diagnostics available
- Easy Installation in under 30 minutes
- Intuitive, Easy to Use Interface
- Complete Database of Specifications
- Ultra Rugged, Maintenance-free Design
- High Value, All-Inclusive Package
- Light, Compact & Easy to Ship



www.candointl.com | 1-909-CanDo-11(226-3611)

CanDo
INTERNATIONAL, INC.

Folks love us for our Heavy Duty Truck & Off-highway Coverage. WE'RE ABOUT TO CHANGE THAT.

The CanDo **C-Pro** is a fully loaded, full functionality scan tool complete with bi-directional controls, special test functions and a full suite of activations and service resets.

Packaged in an 8" Android tablet that is Bluetooth wireless to the car, Wi-Fi to the internet, intuitive to use and easy to update - the **C-Pro** also includes our ASE Remote Technician function at no extra charge!



EUROPEAN, ASIAN & DOMESTIC PASSENGER CARS & LIGHT TRUCKS FULLY COVERED.

CanDo

www.candointl.com • 909-Cando-11(226-3611) INTERNATIONAL, INC.

FLO-DYNAMICS®



**THE LEADER IN FLUID
MAINTENANCE EQUIPMENT**

TRANSMISSION POWER STEERING COOLANT BRAKE AND MORE


www.flodynamics.com

AutoLeap¹

#1 Ranked Auto Repair Software



Software Advice.



Move Save Time | Make More Money




Scan this QR code to get in touch with your AutoLeap rep and learn more!

Get in touch with us to see how AutoLeap can transform your auto repair shop:

Sales@autoleap.com

"Asian Diagnostics" (con't from p. 6)

associated with an MAF sensor, the shop made the right decision not replacing the MAF. The tech was sharp enough to avoid a case of tunnel vision and replacing an MAF that had nothing wrong with it. I have seen this shop improve over the years as they have learned not to throw parts at a vehicle and spend more time on research and diagnostics instead. During their preliminary inspection and diagnosis, they found that the MAF should not be replaced before updating the Engine Control Module (ECM) first.



They used their service information to search for test procedures and TSBs, and found NTB12-051 for the P0101. This vehicle indeed needed a reflash of the PCM and not the MAF sensor to be replaced. Since this shop does not want to invest the time, money or education in performing reflash/reprogramming, they brought the vehicle to me.

The procedure for reflashing a Nissan vehicle requires a bit more time compared to other vehicles. Since I don't own the Nissan factory tool, I was going to reflash this vehicle using my Drew Tech J2534 box. The procedure for Nissan is a bit different than others since you have to purchase their Nissan ECU Reprogramming Software (NERS) for \$270 before purchasing the file needed to reprogram the vehicle. Before reprogramming any vehicle, make sure that the ECM DTCs are cleared, all accessories are off, key fobs other than the one needed to start the vehicle are not in range and most importantly a proper battery maintainer (not a battery jumper pack) is connected to the battery. Do not interrupt the procedure in any way including opening doors, windows, hoods or trunk. Be careful setting up the wiring from the OBD II diagnostic connector to the tool and laptop. On some vehicles during the reprogramming procedure, the windows may go up pinching or pulling the wire from the connections. This can lead to bricking a computer and costing you a lot of money.

(Con't on page 14)

"Asian Diagnostics" (con't from p. 13)

The safe thing to do is close the door latch, making it seem to the vehicle that the door is closed followed by connecting the wire to the tool/laptop. The 45-minute reprogramming procedure yielded the proper results, clearing the P0101 DTC (**Figure 5**) and extinguishing the MIL.

Another Misbehaving Nissan

A 2007 Nissan Maxima came in with an illuminated MIL and an idle problem after the vehicle had a throttle body cleaning service. The first step after interviewing the vehicle owner was a visual inspection that yielded no results to the stalling problem. The next logical step is to connect a scan tool to see what DTC(s) is causing the MIL to illuminate. The scan results came up with a P0507 (incorrect idle speed) DTC. I am sure over the years that you have come across an idle problem on Nissan vehicles many times. In some cases there is no illuminated MIL and just a problem with a high idle, making the diagnosis a bit more difficult. Some techs find it very difficult to resolve this problem and get the idle back to normal. Most likely they are only following the procedure that their scan tool displays. If they are not performing a very important step they won't be successful in relearning the idle.




Figure 6

When I am teaching anything about an idle driveability problem on a Nissan, I use an example from Identifix. The suggested procedure is to disconnect one or more fuel injectors. It's always a good idea to turn the key or power button to the off position before unplugging any solenoids/injectors. Depending on whether the engine is a four or six cylinder will make a difference with how many injectors need to be disconnected. I usually disconnect two injectors on a four cylinder and three on a six cylinder.




Figure 7

(Con't on page 15)

"Asian Diagnostics" (con't from p. 15)

Since this tank is composite, we ruled out a rust hole in the top of the tank. With the foam on the connectors and around the O-ring and on top of the sending unit we were able to identify the **(Figure 6)** locking ring and gasket was leaking. We installed the new O-ring and locking ring with the special Hyundai fuel tank sending unit tool and retested **(Figure 7)** the system using the Hyundai EVAP test on our scan tool. The customer was happy and drove the vehicle around for a few months and down to Florida.

Months had passed by and guess what, the vehicle owner called us up and said his MIL light was back on. We scanned the vehicle and found a P0442 and used the Hyundai EVAP **(Figure 6)** test to confirm the concern was still present. We used the BullsEye tester again and found that this time the fuel pump module had become porous. The leak was coming from the plastic on the **(Figure 7)** fuel pump module. We installed a new fuel pump module and O-ring followed by retesting the system that now passed with flying colors.




Figure 8

I was wondering why there was no smoke coming from the leak area and decided to see if I could determine the reason. As a good practice we baseline our smoke machine before using it so we know the machine is introducing smoke and working properly. We performed this smoke experiment with the fuel sending unit out of the tank while we were flowing smoke into the system. When we looked deep into the tank it seemed that smoke was coming in and being pulled down into the fuel and disappearing. We still love and use our smoke machine, but when we can't find the smoke after resetting the timer button on the machine more than twice we know there is either a leak in the fuel tank or in the canister.

(Con't on page 21)

"Asian Diagnostics" (con't from p. 14)

removed That usually lowers the idle down enough for the idle relearn procedure to start running. After I have been successful in getting the idle lower I follow the procedure on the scan tool and complete the idle relearn. Now the vehicle is back idling normal by just following proper service information.

A Korean Intervention

Our next problem vehicle is a 2007 Hyundai Sonata that came in with a P0442 (EVAP Small Leak Detected) problem. When we encounter a small Evaporative Emissions system (EVAP) leak we know that it's sometimes going to be very difficult to find where the leak is coming from. In the case of this EVAP leak on this Sonata, it may be more difficult than normal to locate the leak. See, we had this Hyundai in before with two EVAP leaks that happened a few months apart from each other. On one occasion, the EVAP leak was very difficult to locate because the leak was barely over 0.020." We were using our normal method to locate the leak by using our smoke machine. The smoke machine was able to show us that the leak was about 0.022" but we could not locate any signs of smoke.

At first we thought that the leak may have been from the charcoal canister, but it was not. We confirmed this by using CO2 along with our smoke machine and gas analyzer. We use this method to look for a rise in CO2, indicating the area of the leak.

As we were moving the gas analyzer probe from the front of the vehicle to the rear we found an area near the upper side of the gas tank where the reading went up. We found dirt and rust on the locking ring of the fuel tank ending unit only after we switched to a new EVAP tool called BullsEye. There was no sign of smoke leaking from this area, but when we used the BullsEye leak detector it went off right at the ring. The next step was to spray on the BullsEye foam that will change color from pink to yellow if a leak is present.

(Con't on page 16)

Want the best? Be the best with DrivePro™.

 **DrivePro™ Remote**
UNLIMITED

Expert assistance from
the most trusted people
in the industry. Opus IVS.

With cutting-edge diagnostics
and UNLIMITED technical support,
DrivePro gives you the confidence to
resolve the most complex repair
challenges fast. DrivePro helps your
shop minimize complexity
and maximize profitability.



Repair Reinvented. OpusIVS.com



SMART TOOLS OF THE TRADE

SMART SPLICE™ LINE SPLICE METAL LINE CONNECTORS



PRO GRADE OIL/DYE INJECTOR

EASILY READ, MEASURE, AND INJECT
PROPER OIL/DYE QUANTITY



SIGHT GLASS

REAL TIME VISUAL
A/C SYSTEM DIAGNOSTICS



DUAL RECYCLE GUARD™

PROTECT YOUR A/C SERVICE EQUIPMENT
FROM CONTAMINANTS





MEMBER ONLY PRICING AND PACKS AVAILABLE NOW! CALL TST FOR MORE!



N2 NEURON
RP-2P4DOUG23



LOW AMP CLAMP
RP-2COR23



PREMIUM STACKABLE SILICONE TEST LEADS
RP-2LUCMGOFU




MAGNETIC BOOT
RP-2P4DQV23 124 125




ROUND TERMINAL PIN TEST KIT
RP-2ETKVVUM23




AMP FINDER & FUSE DRAW TEST




FREE 1 ON 1 TRAININGS BUILT IN



FULL WAVEFORM CAPTURE




PINCH/ZOOM FULL GRAPHING



GRAPHING

FULL TRAINING VIDEO LIBRARY BUILT IN



FULL 2 CH. MULTIMETER



2 ZONE TEMP TESTING



30 DAY FREE PREMIUM TRAINING



WWW.CURIENLLC.COM





The Battery Chargers Professional Technicians TRUST



IBC6008MSK

- Safely charges ALL 12V EFB (Start-Stop), AGM, Lithium, Gel and SLA battery types
- Customize battery charging profiles with adjustable voltage and adjustable amperage by type
- Built-in refresh power supply and memory saver port with 12 ft. OBDII cord
- Patented Intellamatic® smart charger analyzer technology with battery rejuvenation
- Partial Charge mode for busy shops
- Energy efficient and OE manufacturer approved
- Legendary power and generational quality
- "Safe in any weather" operation



6006AGM/6009AGM/6012AGM

- Upgraded "tried and true" heavy duty chargers with setting for AGM batteries
- Improved energy efficiency
- Legendary power and quality

AMERICAN MADE, FAMILY OWNED

5043 Farlin Ave. | St. Louis, MO 63115 | 800-949-1472 | www.associatedequip.com

#IWANTTHEBLUEONE

"Asian Diagnostics" (con't from p. 16)

Toyota SRS

My friend Armine called me about his 2004 Toyota Camry that had an illuminated air bag light on the dash. When he drove the vehicle to the shop, I decided to connect the Toyota Techstream to the vehicle. The following DTCs were stored in the vehicle (**Figure 8**): B1785 Occupant Detection LH Collision Detection and B1650 SRS Airbag. An attempt by a shop closer to where he lives tried clearing the DTCs, but they came right back. The shop most likely used an aftermarket scan tool that did not have the ability to perform a Zero Point calibration for the B1785. The problem with this DTC was not caused by an accident, but most likely from something heavy that contacted the seat frame. Since there was no damage to the seat frame, I continued diagnosing the B1650 DTC. One way a B1650 can set is if the airbag sensor assembly center receives signals from the Occupant Classification ECU, it determines whether or not the front passenger airbag assembly and the front seat airbag assembly RH should be operated. So after reading the DTC definition in our service information, it seemed like the Zero Calibration would fix both DTCs if the procedure was successful. I performed the procedure successfully, and the vehicle was now fixed. So what caused the problem? Take a look at the rear bumper, (**Figure 9**). See the two holes? It looks like the bumper was hit by something or hit something hard. Maybe an NYC parallel parking job (I say with a smile)?





Figure 9

By
"G" Jerry Truglia
TST Founder and President
ASE World Class Triple Master
Auto, Truck, School Bus L1, L3, F1, X1, C1, Technician

ATS | AUTOMOTIVE Test Solutions



▶ eSCOPE ELITE 8



▶ iGA5 ELITE



▶ eSCAN ELITE

www.automotivetestsolutions.com

800-572-6112