



Sat, Apr 06 | Westchester Marriott

TST 2024 LIVE IN PERSON 21th ANNUAL BIG EVENT & TRADE SHOW

All PAID attendees receive a Android Tablet. MUST HAVE TICKET TO ENTER THE EVENT. (MUST ATTEND TO RECEIVE A TABLET) ABSOLUTELY NO REFUNDS -



Transmission Change Awareness





- Welcome to "Transmission Change Awareness" sponsored by ATSG/ETE Reman.
- Please allow me to begin with a short "Shameless Self Promotion" ©
- ETE Reman is in Milwaukee, Wisconsin, where it remanufactures approximately 330 transmissions a day offering a 3-year no hassle warranty to its customers.

Transmission Change Awareness





- ATSG is a technical organization supporting the automotive industry in diagnosing automatic transmission malfunctions. ATSG then provides technical seminars sharing the discovery of the many causes to these transmission malfunctions. ATSG also provides a variety of manuals from rebuilding to diagnosing and quick references guides.
- Both ETE Reman and ATSG started in 1985. In August of 2018, ETE Reman acquired ATSG bringing great support to both organizations for the benefit of the automotive industry.



TECH LIBRARY 24/7 access to Confirmed Fixes, Bulletins & videos

800-245-7722

SUPPORT HOTLINE

- Unlimited calls into ATSG's Technical Hotline
- Expert techs on stand-by
- 300+ years of combined experience
- Spanish speaking tech available

TRAINING DISCOUNTS

Common problems & how

Easily find information on part changes & updates

Information on computer troubleshooting & quick checks

to correct them

- Print manuals, downloads, CDs, tools, and more
- Members get 30% OFF

BOOKSTORE DISCOUNTS

- New & improved online shopping experience
- Free domestic shipping

- Insider discounts on webinars (LVS)
- Insider discounts on in-person seminars
- Keep your tech's knowledge up-to-date
- Cutting edge information year after year

1ST MONTH FREE!

atsg.link/atsgmember

ETE Reman/ATSG Corporate Headquarters







ETE REMAN Shipping & Receiving Center Trans-R-Us







ETE REMAN Torque Converter Rebuilding Plant











































ETE'S MOBILE APP TAKES FLIGHT

T282020 - 6L80

Sorry Feathers,

some things are better done on the phone.

Convenience and Speed - ETE's app lets you search products by application, interchange or VIN. You can also...





Effortlessly Scan to Read and Input VIN

Schedule Core Returns

Get Estimated Delivery Times for Orders

Download the App Here!



iOS/iPhone





Google Play/Android


GET TORQUED! IN AN ALL NEW WAY!

BUYETE.COM



ASSOCIATED PRESS apnews.com

Repelled by high car prices, Americans are holding on to their vehicles longer than ever






Transmission Change Awareness









- Our presentation today will primarily cover from old to new (from 4 to 10 speeds), some changes that have occurred within a family of transmissions which if a tech is unaware of, will make it difficult to diagnose. We call this, "Transmission Change Awareness."
- Some unrelated helpful tips will also be given peppered throughout this presentation.















Sheet metal windows mounted on the spider clutch shell are used to excite the pulse generator.








Pulse Generator Reads Planet Speed so there is no Turbine Speed signal In 1st Gear











Hall Effects Sensor Reads Actual Input Speed From Forward Clutch (A)















"A" CLUTCH DRUM FOR PULSE GENERATOR



"A" CLUTCH DRUM FOR HALL EFFECT SENSOR



MAGNETIC BAND





SPIDER CLUTCH BELL FOR PULSE GENERATOR



SPIDER CLUTCH BELL FOR HALL EFFECT SENSOR







SUN SHELL FOR PULSE GENERATOR IS FERROUS



SUN SHELL FOR HALL EFFECT SENSOR IS NON-FERROUS





ZF5HP19FL/FLA PULSE GENERATOR MODELS

MAKE	MODEL	ENG.	YEAR	ZF PART#	CODE	TYPE
AUDI	A4 QUATTRO/AVANT	1.8	1996	1060-040-018	DTV	PULSE GENERATOR
AUDI	A4 QUATTRO/AVANT	2.8	1996	1060-040-002	CJP	PULSE GENERATOR
AUDI	A4 QUATTRO/AVANT	2.8	1996	1060-040-012	DRN	PULSE GENERATOR
AUDI	A4 QUATTRO/AVANT	1.8	1997	1060-040-018	DTV	PULSE GENERATOR
AUDI	A4 OUATTRO/AVANT	2.8	1997	1060-040-002	CJP	PULSE GENERATOR
AUDI	A4 QUATTRO/AVANT	2.8	1997	1060-040-012	DRN	PULSE GENERATOR
AUDI	A4 OUATTRO/AVANT	1.8	1998	1060-040-018	DTV	PULSE GENERATOR
AUDI	A4 OUATTRO/AVANT	2.8	1998	1060-040-012	DRN	PULSE GENERATOR
AUDI	A6 OUATTRO	2.8	1998	1060-040-013	DPT	PULSE GENERATOR
AUDI	A6 QUATTRO	2.8	1998	1060-040-036	EKX	PULSE GENERATOR
AUDI	A4 QUATTRO/AVANT	1.8	1999	1060-040-018	DTV	PULSE GENERATOR
AUDI	A4 QUATTRO/AVANT	2.8	1999	1060-040-012	DRN	PULSE GENERATOR
AUDI	A6 QUATTRO	2.8	1999	1060-040-013	DPT	PULSE GENERATOR
AUDI	A6 QUATTRO	2.8	1999	1060-040-036	EKX	PULSE GENERATOR
AUDI	A4 QUATTRO AVANT	1.8	2000	1060-040-018	DTV	PULSE GENERATOR
AUDI	A4 QUATTRO/AVANT	2.8	2000	1060-040-012	DRN	PULSE GENERATOR
AUDI	A6 QUATTRO	2.8	2000	1060-040-013	DPT	PULSE GENERATOR
AUDI	A6 QUATTRO	2.8	2000	1060-040-036	EKX	PULSE GENERATOR
AUDI	A4 QUATTRO/AVANT	1.8	2001	1060-040-018	DTV	PULSE GENERATOR
AUDI	A4 QUATTRO AVANT	2.8	2001	1060-040-012	DRN	PULSE GENERATOR
AUDI	A6 OUATTRO	2.8	2001	1060-040-013	DPT	PULSE GENERATOR
AUDI	A6 OUATTRO	2.8	2001	1060-040-036	EKX	PULSE GENERATOR
AUDI	A4 QUATTRO AVANT	1.8	2002	1060-040-018	DTV	PULSE GENERATOR
AUDI	A4 QUATTRO AVANT	2.8	2002	1060-040-012	DRN	PULSE GENERATOR
VW	PASSAT	2.8	1999	1060-040-012	DRN	PULSE GENERATOR
VW	PASSAT	2.8	2000	1060-040-012	DRN	PULSE GENERATOR
VW	PASSAT	2.8	2001	1060-040-012	DRN	PULSE GENERATOR



TAG IS AN EXAMPLE OF AN AUDI A6 QUATTRO 2.8 1998 MODEL YEAR TRANS ID CODE: DPT PULSE GENERATOR MODEL

ZF5HP19FL/FLA HALL EFFECT SENSOR MODELS


MAKE	MODEL	ENG.	YEAR	ZF PART#	CODE	TYPE
AUDI	A6 QUATTRO	2.7	1998	1060-040-044	EMP	HALL EFFECT
AUDI	A6 OUATTRO	2.7	1998	1060-040-063	FAO	HALL EFFECT
AUDI	A6 OUATTRO	2.8	1998	1060-040-035	EKD	HALL EFFECT
AUDI	A4 QUATTRO AVANT	1.8	1999	1060-040-030	EFO	HALL EFFECT
AUDI	A4 QUATTRO AVANT	1.8	1999	1060-040-054	FAL	HALL EFFECT
AUDI	A4 QUATTRO AVANT	2.8	1999	1060-040-035	EKD	HALL EFFECT
AUDI	A6 QUATTRO	2.7	1999	1060-040-044	EMP	HALL EFFECT
AUDI	A6 OUATTRO	2.8	1999	1060-040-035	EKD	HALL EFFECT
AUDI	S4 OUATTRO AVANT	2.7	1999	1060-040-044	EMP	HALL EFFECT
AUDI	A4 QUATTRO AVANT	1.8	2000	1060-040-030	EFO	HALL EFFECT
AUDI	A4 OUATTRO AVANT	1.8	2000	1060-040-054	FAL	HALL EFFECT
AUDI	A4 QUATTRO AVANT	2.8	2000	1060-040-035	EKD	HALL EFFECT
AUDI	A6 QUATTRO	2.7	2000	1060-040-044	EMP	HALL EFFECT
AUDI	A6 QUATTRO	2.8	2000	1060-040-035	EKD	HALL EFFECT
AUDI	S4 QUATTRO AVANT	2.7	2000	1060-040-044	EMP	HALL EFFECT
AUDI	A4 QUATTRO AVANT	1.8	2001	1060-040-030	EFO	HALL EFFECT
AUDI	A4 QUATTRO AVANT	1.8	2001	1060-040-054	FAL	HALL EFFECT
AUDI	A4 QUATTRO AVANT	2.8	2001	1060-040-035	EKD	HALL EFFECT
AUDI	A6 QUATTRO	2.7	2001	1060-040-044	EMP	HALL EFFECT
AUDI	A6 QUATTRO	2.8	2001	1060-040-035	EKD	HALL EFFECT
AUDI	A6 ALLROAD QUATTRO	NA	2001	1060-040-093	FXL	HALL EFFECT
AUDI	A6 ALLROAD QUATTRO	2.7	2001	1060-040-053	EYK	HALL EFFECT
AUDI	S4 QUATTRO/AVANT	2.7	2001	1060-040-044	EMP	HALL EFFECT
AUDI	A4 QUATTRO AVANT	1.8	2002	1060-040-030	EFQ	HALL EFFECT
AUDI	A4 QUATTRO AVANT	1.8	2002	1060-040-054	FAL.	HALL EFFECT
AUDI	A4 QUATTRO AVANT	1.8	2002	1060-040-073	FEP	HALL EFFECT
AUDI	A4 QUATTRO AVANT	1.8	2002	1060-040-101	GBF	HALL EFFECT
AUDI	A4 QUATTRO AVANT	2.8	2002	1060-040-035	EKD	HALL EFFECT
AUDI	A4 QUATTRO AVANT	3.0	2002	1060-040-087	FEO	HALL EFFECT
AUDI	A4 QUATTRO AVANT	3.0	2002	1060-040-103	GBJ	HALL EFFECT
AUDI	A6 QUATTRO	3.0	2002	1060-040-075	FEJ	HALL EFFECT
AUDI	S4 QUATTRO AVANT	2.7	2002	1060-040-044	EMP	HALL EFFECT
VW	PASSAT	2.8	1999	1060-040-035	EKD	HALL EFFECT
VW	PASSAT	2.8	2000	1060-040-035	EKD	HALL EFFECT
VW	PASSAT	2.8	2001	1060-040-035	EKD	HALL EFFECT
VW	PASSAT	4.0	2001	1060-040-100	GAK	HALL EFFECT








41TE 42RLE 45RFE 545RFE **62TE** 65RFE 66RFE 68RFE







Solenoid Body Pass Through Connector View







42RLE
Solenoid
Body Pass
Through
Connector
View








41TE
(A604)
Solenoid
Body
Assembly








41TE (A604)
Pressure
Switches






(A604)
NA and
NV
Solenoids




























































68RFE
Solenoid
Body Pass
Through
Connector
View

2010 Changes were made to the valve body assembly and the solenoid assembly.








































The beaded gasket between the solenoid block and VB remained the same




























68RFE
Solenoid
Body Pass
Through
Connector
View


















White with OD Solenoid

GRAY with OD Solenoid Eliminated






White with OD Solenoid



D21 LINE PRESSURE FEED TO 2^{ND} , 4^{th} & OD SOLENOID




Beaded Gasket Design

Gray with OD Solenoid Eliminated

OAth NV

D21 LINE PRESSURE FEED TO 2ND & 4th SOLENOID



BIG CHANGE IN 2019








BIG CHANGE IN 2019








BIG CHANGE IN 2019







- Aside from adding a converter clutch variable force solenoid, they also added:
- A solenoid to control the reverse clutch engagement after 30 years of not having this solenoid.















REVERSE CLUTCH SOLENOID - NA

2019 & LATER

LINE PRESSURE SUPPLY FROM MANUAL VALVE IN THE REVERSE POSITION ONLY







D21 LINE PRESSURE SUPPLY FROM MANUAL VALVE FOR 2ND & 4TH SOLENOID

REVERSE CLUTCH SOLENOID - NA


2018 WITH EARLY GASKET


D21 LINE PRESSURE FEED TO 2ND & 4TH SOLENOID





White with OD Solenoid with Blue Connector Beaded Gasket





GM 6T30/40/45/50 SERIES TRANSMISSIONS











General Motors 6T Series Transmissions 6T30/40/45/50


- These series of transmissions began service with the 2007 model year.
- GM 6T40 Series Generation 2 arrived in 2012 and was selectively used and cannot back service previous design levels – Pressure switches were eliminated, and solenoid changes were made as well – variable bleed to variable feed solenoids as well as computer strategy.
- By 2015 all platforms using the 6T series transmissions should be Generation 2 equipped.





• For increased torque capacity, the wave plate was removed from the 4-5-6 clutch pack assembly and was replaced with an additional friction plate.









• For increased torque capacity, the wave plate was removed from the 4-5-6 clutch pack assembly and was replaced with an additional friction plate.












An Orifice Is Placed In The Line Pressure Feed Circuit To The R1/4-5-6 Clutch Regulator Valve








The Line Pressure Feed Orifice Was Moved To The 4-5-6 Clutch Feed Circuit


Example Of A Software Change





System Pressure Learn










GENERATION 1 TEHCM

Transmission Electro-Hydraulic Module







GENERATION 1 TEHCM








GENERATION 1 TEHCM







SHIFT ADAPTS



Coming Off



Kiss Point 30 psi



Coming On




ISS/OSS

RANGE	GEAR	RATIO	SHIFT SOL (On/Off)	1-2-3-4CL PC SOL 5 N.L.	2-6 CL PC SOL 4 N.L.	3-5 REV CL PC SOL 2 N.H.	LO/REV 4-5-6 CL PC SOL 3 N.H.	4-5-6 CLUTCH	3-5 REV CLUTCH	2-6 CLUTCH	LOW ONE-WAY CLUTCH		1-2-3-4 CLUTCH
PARK	P		ON	OFF	OFF	ON	OFF					APPLIED*	
REV	R	2.940	ON	OFF	OFF	OFF	OFF		APPLIED			APPLIED	
NEUT	N		ON	OFF	OFF	ON	OFF					APPLIED*	
Neutral Stop Capable ←	IST -BRAKING	4.584	OFF	ON	OFF	ON	OFF	1				APPLIED	APPLIED
	1ST	4.584	OFF	ON	OFF	ON	ON				HOLD		APPLIED
D R	2ND	2.964	OFF	ON	ON	ON	ON			APPLIED			APPLIED
V	3RD	1.912	OFF	ON	OFF	0FF	ON		APPLIED				APPLIED
E	4TH	1.446	OFF	ON	OFF	ON	OFF	APPLIED					APPLIED
	5TH	1.000	OFF	OFF	OFF	0FF	OFF	APPLIED	APPLIED	-			
	6ТН	0.746	OFF	OFF	ON	ØN	OFF	APPLIED		APPLIED			

GENERATION 2 TEHCM







GENERATION 2 TEHCM











- Patent App Pub. US 20120067690 A1 entitled:
- Hydraulic clutch and method for determining an adaptive clutch fill volume of the hydraulic clutch
- A method for learning a characteristic filling volume of a hydraulic clutch:
- The method comprising of:





- Applying a pressure pulse to the hydraulic clutch when the hydraulic clutch is in a disengaged state.
- Determining an inflection event at a torque path that comprises the hydraulic clutch.
- Deriving the characteristic filling volume of the hydraulic clutch from the inflection event.





Clutch Pulse Learn Event					
Disengaged Clutch	Gear Clutch is Pulsed				
4-5-6 Clutch	3rd Gear				
1-2-3-4 Clutch 2-6 Clutch	5th Gear				
3-5-R Clutch	6th Gear				
Clutch Pulse	e Learn occurs				

Clutch Pulse Learn occurs every 1,000 miles or more

GM calls the Clutch Pulse Learn strategy as a Non-Shifting Clutch Function Verification





Start

Determining a fluid pressure command value

Determining a reactive pressure of a return spring

Calculating a flow rate

Measuring a fill time

Calculating a clutch fill volume

Operating a clutch

When to Perform Adaptation Procedures





- Transmission internal service/overhaul
- Valve body repair or replacement
- Control solenoid valve assembly replacement
- TCM software/calibration update
- Any service in response to a shift quality concern

Adaptation Abort





- TFT too cold or too hot
- Brake Pedal Position Sensor Malfunction
- DTC's stored in system
- TPS signal too high
- TRS malfunction
- Line pressure out of specification
- Vehicle is moving or vibrating excessively
- Improper clutch assembly

Neutral Idle Control





- Neutral Idle is commanded ON when:
- The transmission is in Drive 1st Gear
- Brakes Applied
- Temperature is at 99 degrees F or greater

Neutral Idle Control





- What is being commanded to provide Neutral Idle:
- The Low/Reverse Clutch remains applied.
- The TCM will command PCS 5 to reduce 1-2-3-4 Clutch apply pressure allowing the clutch to slip/release.
- NOTE: There are no indicator lights to inform the driver this fuel saving strategy has been initiated.

Brake Pedal Position Sensor







BPPS DTC Descriptors





- DTC P057B
- Brake Pedal Position Sensor Performance
- DTC P057C
- Brake Pedal Position Sensor Circuit Low Voltage
- DTC P057D
- Brake Pedal Position Sensor Circuit High Voltage

Circuit	Short to Ground	Open/High Resistance	Short to Voltage	Signal Performance
Signal	P057C	P057C	P057D	P057B
5 V Reference	P057C P0651	P057C	P0651	2
Low Reference		P057D	P057D	[- 1.5 - 1]

Pressure Control Solenoids ON/OFF SS TCC PCS 2 PCS 3 LPCS PCS 4 PCS 5

Pressure Control Solenoids






Gear	Shift SOL 1	1-2-3-4 CL PC SOL 5 N.L.	2-6 CL PC SOL 4 N.L.	3-5 REV CL PC SOL 2 N.H.	LOW REV 4-5-6 CL PC SOL 3 N.H.
Park	ON	OFF	OFF	OFF	ON
Reverse	ON	OFF	OFF	ON	ON
Neutral	ON	OFF	OFF	OFF	ON
1st Braking	ON	ON	OFF	OFF	ON
1st	OFF	ON	OFF	OFF	OFF
2nd	OFF	ON	ON	OFF	OFF
3rd	OFF	ON	OFF	ON	OFF
4th	OFF	ON	OFF	OFF	ON
5th	OFF	OFF	OFF	ON	ON
6th	OFF	OFF	ON	OFF	ON

Pressure Control Solenoids





Parameter	System State	Expected Value	Description
Pressure Control Solenoid Valve 5 Control Circuit Low Voltage Test Status	ок	OK, Malfunction, Not Run	This parameter displays whether a short to ground exists in the pressure control solenoid valve 5 control circuit. The scan tool displays OK, Malfunction, or Not Run.
Pressure Control Solenoid Valve 5 Control Circuit High Voltage Test Status	ок	OK, Malfunction, Not Run	This parameter displays whether a short to voltage exists in the pressure control solenoid valve 5 control circuit. The scan tool displays OK, Malfunction, or Not Run.
Pressure Control Solenoid Valve 5 Performance Test Status	ок		This parameter displays whether a performance issue exists in the pressure control solenoid valve 5 control circuit by comparing the commanded current with the expected current. The scan tool displays OK, Malfunction, or Not Run.
Pressure Control Solenoid Valve 5 Pressure Command	Varies	kPa (psi)	This parameter displays kPa (psi).







	Legend	Parameter Name	Control Module	Value 1	Value 2	Delta	Unit:
Г		Transmission ISS	Transmission Control Module	623			RPM
Γ		Transmission OSS	Transmission Control Module	0			RPM

AUTOMOTIVE CALIBRATION AND DIAGNOSTIC TOOL











AUTOMOTIVE CALIBRATION AND DIAGNOSTIC TOOL








Engine Tuning is not something new in the driveability world










Greg Banish publications have helped many in their tuning quest.

- Understand & Tune Complicated Systems
- Precisely Control Inputs & Outputs
 Advanced Calibration Tips & Secrets
- Practical Tuning Examples

Greg Banish







- been getting into this now for a number of years changing transmission shift and TCC strategies.
- This has opened new issues if you are not aware of pervious work done.



6L80 Woven Fiber Clutch







6L80 Woven Fiber Clutch







6L80 Woven Fiber Clutch







6L80 Woven Fiber Clutch















































































HP Tuning Scenarios





- Scenario 1
- A 2012 GMC Yukon 5.3L comes into your shop using the 6L80 transmission not knowing it was once serviced by a transmission shop where it was HP Tuned.
- The vehicle needs a new PCM.
- Or you reprogram it.
- Customer now knows something is different and complains about it.
- Scenario 2
- It comes from a shop that used HP Tuning incorrectly causing odd shifting patterns and/or TCC issues.
- You spend hours of diagnostics trying to determine what the HELL is going on!!!





USING HP TUNERS AS A DIAGNOSTIC TOOL









USING HP TUNERS AS A DIAGNOSTIC TOOL









Gear Position	Actual Li	ne Pressure - I	PSI (KpA)	Line Pressure Control (L/EPC) - PSI (KpA)			
	Idle Gas & Diesel	WOT Gas Only	WOT Diesel Only	Idle Gas & Diesel	WOT Gas Only	WOT Diesel Only	
P/N	90 (619)			14 (94)			
R	90 (619)	240 (1675)	260 (1790)	14 (94)	60 (410)	70 (480)	
D	90 (619)	230 (1600)	225 (1550)	14 (94)	55 (375)	55 (375)	
3	90 (619)	180 (1230)	160 (1100)	14 (94)	40 (275)	35 (240)	
2	90 (619)	240 (1675)	235 (1650)	14 (94)	60 (410)	60 (410)	
1	90 (619)	230 (1600)	225 (1550)	14 (94)	55 (375)	55 (375)	









COMPONENT APPLICATION CHART

RANGE	1-2-3-4 Clutch (Fwd)	3-5-Rev Clutch (Direct)	2-6 Clutch (Int)	Low/ Reverse Clutch	4-5-6 Clutch (OD)	Low One-Way Clutch	Torque Converter Clutch	Gear Ratio
Park				On				
Reverse		On		On				3.13
Neutral				On				
"D"-1st	On			^On		Hold	Applied*	3.97
"D"-2nd	On		On				Applied*	2.32
"D"-3rd	On	On					Applied*	1.52
"D"-4th	On				On		Applied*	1.15
"D"-5th		On			On		Applied*	0.86
"D"-6th			On		On		Applied*	0.67




SOLENOID APPLICATION CHART



SSB is on in Park. It ramps off in reverse for a controlled apply


Selector Lever Position	Commanded Gear	1-2-3-4 (SSA) NL	3-5-Rev (SSB) NH	2-6 (SSC) NL	L-Rev (SSD) NL	4-5-6 (SSE) NH	Torque Converter Clutch NL
P	P	off	On	Off	On	On	Off
R	R	Off	off	Off	On	On	off
N	N	off	On	Off	On	On	Off
	1	On	On	off	off^	On	On/Off*
	2	On	On	On	off	On	On/Off*
D	3	On	off	Off	off	On	On/Off*
D D	4	On	On	Off	off	Off	On/Off
	5	off	off	Off	off	Off	On/Off
	6	Off	On	On	Off	Off	On/Off
L	L	On	On	Off	On	On	off
















































































TUN







- We sent out a unit with the exact broadcast code with its own TUN.
- When the shop entered the new TUN, it was rejected.
- He tried entering the PUN and it was rejected.
- After entering the original TUN, he could enter the new PUN.
- Shifts were brutal preventing a complete road test.












• It is necessary to perform a Fast Learn Adapt Process





RESSETTING SHIFT ADAPTS – 12-15 MINUTES



Set parking brake and block the drive wheels. If vehicle has 4WD make sure to put it into 2WD. Start engine and allow transmission temperature to reach 167-187°F (75-86 °C) before running this test.

- Here is the caveat.
- It's too difficult to drive to bring vehicle up to operating temperature.
- Idle vehicle to about 130° F. Place in reverse and brake torque to operating temperature





RESSETTING SHIFT ADAPTS — 12-15 MINUTES

Clutch purge in progress.

Continue to hold the brake pedal.



RESSETTING SHIFT ADAPTS – 12-15 MINUTES



It is necessary to perform a Fast Learn Adapt Process


The Fast Learn procedure is complete.

To exit this test, perform the steps in the order below.

Failure to properly exit the test may cause a no drive condition, set DTCs or both.

- Apply the brakes and put transmission in Park.
 - 2. Exit this test.
 - 3. Turn the ignition off and remove the key.
- Open and close the driver door and wait for 30 seconds.

BINARY POSITIVE DISPLACEMENT VANE TYPE PUMP














- TWO PUMPS
- 5 DIFFERENT GASKETS























































ZF8HP VS 845RE










ZF8HP Mechatronic


















Transitional change began in 2019









845RE Mechatronic












THE ZF9HP48-948TE



	A Clutch (Dog)***	B Clutch	C Brake	D Brake	E Clutch	F Clutch (Dog)***	Ratio	
P/N	Open			ON		Closed		
Reverse	Open	ON		ON		Closed	3.830	
1st Gear	Closed			ON		Closed	4.713	
2nd Gear	Closed		ON			Closed	2.842	
3rd Gear*	Closed	ON	1.		-	Closed	1.909	
4th Gear**	Closed				ON	Closed	1.382	
5th Gear	Closed	ON			ON	Open	1.000	
6th Gear	Closed		ON		ON	Open	0.808	
7th Gear	Closed			ON	ON	Open	0.699	
8th Gear	Open		ON	ON	ON	Open	0.580	
9th Gear	Open	ON		ON	ON	Open	0.479	

- * Failsafe Gear according to Land Rover
- ** Default Gear according to Dodge
- *** Dog Clutch shift transitions dependent upon proper engine and shaft speed

DOG CLUTCHES A & F



Hydraulically engaged and disengaged synchro devices providing a non-slipping connection of two components.

- To engage or disengage a dog clutch, the TCM sends a request for the PCM to increase or decrease engine RPM and torque to allow speed matching.
- Example: As the engine rpm increases, the transmission slips one or more of the multi-disc clutches until the components of the dog clutch are at the same speed.







- 2015 Jeep Cherokee3.2L 4WD
 Trailhawk 948TE Transmission
- P0887 TCM Power Control Circuit High
- U1412 Implausible VSS Signal Received
- U0001 CAN C Bus
- P061B Internal Control Module Torque Calculation Performance







- 5-4 Coast downshift issues
- Low speed acceleration issues
- Bad shift qualities
- Hill climb and descent shift issues
- Stop/Start Engagement issues
- Slow to upshift after lift throttle







CHRYSLER RECALLS 410,000 VEHICLES OVER WIRING PROBLEMS

Fiat Chrysler says wiring harness problems can cause loss of propulsion in nearly 410,000 vehicles.

July 25, 2016 — Fiat Chrysler (FCA US) is recalling nearly 410,000 vehicles to replace wire harnesses and update software, fixing problems that could cause the vehicles to stop moving forward.

Included in the recall are the 2015 Chrysler 200, 2015 RAM ProMaster City, 2015 Jeep Renegade and 2015 Cherokee. Certain 2014 Jeep Cherokees are also affected. The automaker says the vehicles are equipped with 9HP48 or 948TE transmissions.








Hard, Strange Shifts and Sudden Shutdowns with the ZF 9-Speed Transmission


(9 December 12, 2018 © Scott McCracken

(#transmission)

#lawsuit




- 2014-2015 were the worst
- After programming 9th gear is seemingly lost.
- The dealer says that it will engage under certain driving conditions.
- When asked what are those conditions:









































































	A Clutch (Dog)***	B Clutch	C Brake	D Brake	E Clutch	F Clutch (Dog)***	Ratio
P/N	Open			ON		Closed	
Reverse	Open	ON		ON		Closed	3.830
1st Gear	Closed			ON		Closed	4.713
2nd Gear	Closed		ON			Closed	2.842
3rd Gear*	Closed	ON	1.		-	Closed	1.909
4th Gear**	Closed				ON	Closed	1.382
5th Gear	Closed	ON			ON	Open	1.000
6th Gear	Closed		ON		ON	Open	0.808
7th Gear	Closed			ON	ON	Open	0.699
8th Gear	Open		ON	ON	ON	Open	0.580
9th Gear	Open	ON		ON	ON	Open	0.479








Intermittent No Forward

DTC P0730 – Incorrect Gear Ratio DTC P07A6 – Clutch C Performance


^{** -} Default Gear according to Dodge *** - Dog Clutch shift transitions dependent upon proper engine and shaft speed

























For the curious mind







https://www.transmissiondigest.com/chrysler-948te-doggy-dog-transmission




Chrysler 948TE: It's a doggy dog transmission



By Wayne Colonna

Published: August 4, 2022







Ford 10R80/140W Transmission
















































- 2023 F350 4WD Super Duty 6.7L Turbo Diesel
- After a transmission exchange the Solenoid Body Strategy and ID numbers were programmed into the TCM.
- The shops normal operating procedures is to run updates after repairs.
- During a programming event it wrote to the PCM, then the TCM and then to the Glow Plug Module (Glow Dosing Module).









- Halfway into it the program freezes.
- Various codes were set: IAT, DEF, etc.
- Vehicle was sent to the dealer for the module to be replaced.
- The dealer says this occurs frequently.









- 2019 F250 Super Duty 2WD 6.7L Deisel
- 10R140 Transmission needed replacement
- The Solenoid Body Strategy and ID numbers were programmed into the TCM.
- The shops normal operating procedures is to run updates after repairs.









- During a programming the DEF warning lamp started flashing. The Red Stop Lamp illuminated. An audible warning beep occurred, and the MIL illuminated as well.
- Vehicle initiated Low Power Mode.
- The shop was unaware of:






















- EGR/DPF/DEF Delete Kits
- The shop was faced with talking to the customer to restore the delete or
- To bring it to the one who tuned the delete.

Thank You For Your Time





