
November 2024



Technicians Service Training

INSIDE THIS ISSUE:

"First-Time Mistakes"

P. 1 - 15

Upcoming

December 18th

Advanced Diagnostics: Exploring Tools and Techniques for Modern Vehicle Analysis - HP Tuners, Picoscope + CAN, Tesla Cybertruck

Scott Brown

TST Big Event March 29th 2025

Bill Weaver - Josh Weaver - Eric Zigler -Keynote Carm Capriotto

Check out our YouTube channel tstseminars

Like us Facebook

Editor

"G" Jerry Truglia

© 2024 ATTS INC.

"First-Time Mistakes"

To err is human; to forgive, divine is a phrase that you may have heard at one time or another. In the automotive business, however, an error could be very costly and just may not be forgiven by the vehicle or owner. In this article, I will provide you with real-world shop mistakes that I and others have made. Some are costly in time or parts that both affect the shop's bottom line; and, in other cases, costly in terms of one's reputation.

Our First Tale

One of the problems that we encountered in our shop recently was on a 2008 Honda Accord with 125,000 miles that had come back after a timing belt and tune up were performed. The owner returned to our shop because of an illuminated check engine light that resulted from an engine misfire. After the tech connected the Honda factory scan tool, he retrieved the misfire DTCs (Figure 1) along with a P0339 Crank Sensor DTC. It's never good when a customer returns with any problem after a repair has been recently performed on their vehicle. The return of the MIL light is the telltale sign that the vehicle's computer system sees something wrong and is going to alert the driver. There is no way, at least with drivability issues, that you can hide from doing it right. So, we had to handle the vehicle owner very carefully and be honest with her on what the problem was. (Con't on page 3) Page 2 Volume 21, Issue 9

What is TST?

TST is a group of dedicated technicians and instructors committed to the continuing education of our fellow technicians. We provide training seminars to technicians at a reasonable price. TST brings our members nationally known instructors and state of the art training.

- Our Goal & Mission Statement
- Keep our fellow technicians up to date with the latest technology.
- Provide training seminars for a reasonable price.
- Deliver information that the technician can use now.
- Keep technicians informed of information affecting our industry.
- Increase consumer awareness of what a good technician is.

Why join TST?

TST membership includes special pricing on weekday night seminars and the occasional full Saturday seminar. With a \$99.00 yearly individual or shop \$299.00 membership, the simulcast are only \$20.00. TST seminars are NOT sales or product seminars. The instructors that TST brings in are all "hands-on" industry experts with up to date, cutting edge knowledge that you can use in your shop the next day. That's 99 dollars for a seminar in which you are able to learn something useful, for fixing those tough jobs that we all see on a regular basis. Our instructors are masters at making the complex understandable. Membership also includes a newsletter full of real world technical articles, diagnostic case studies, and solutions to the kinds of problems you see in your bays each week.

The following are some of TST's regular instructors:

Bernie Thompson of ATS

John Thornton of Autotrain Inc.

Wayne Colonna of ATSG

Jorge Menchu the "Labscope Guru," AES Wave

John Anello of Auto Tech On Wheels

Mark Warren of World Pac / Motor Magazine

Brandon Steckler of CTI & Motor Age Magazine

Peter Meier of Motor Age Magazine

Ken Zanders of Illinois Air Team "G" Jerry Truglia of A.T.T.S. Inc.



7echnicians Service 7raining
11 Lupi Plaza
Mahopac, NY 10541
Phone: (845) 628-6928
Fax: (845) 628-9109
Email:

Info@tstseminars.org

TST on YoutTube...type in tstseminars


No part of this newsletter may be reproduced, stored in a retrieval system, or transmitted, in any form by any means, electronic, mechanical, photocopying, recording, or otherwise, without prior written permission of the authors.

Information contained in this newsletter is intended for use by professional auto repair technicians familiar with approved vehicle repair procedures. The authors are not responsible for physical injury or property damage resulting from the incorrect application of information or procedures outlined in this volume.

Currently there are TST chapters in Connecticut, Massachusetts, New Jersey, New York and membership continues to grow. For more information you can call TST headquarters at:

(845) 628-6928 www.TSTseminars.org

DORMAN TECHNICIAN TRAINING



YOU KNOW US FOR THE PARTS. **NOW WE DELIVER THE SMARTS.**

We are continuing to invest in the transportation aftermarket by offering in-person training throughout North America, and online training wherever you are. As vehicles are always changing, we are always releasing new solutions, and now that means both products and knowledge.

For additional information contact

DTC@DormanProducts.com.

Г

Curriculum Includes:

- Critical Thinking-Diagnostic Strategies
- P0420 & P0430 "Keeping the Light Off"
- Unlocking the Potential of Your Scan Tool
- Understanding and Diagnosing Air Conditioning
- 20+ additional topics available






Page 4 Volume 21, Issue 9

"First-Time Mistakes" (con't from p. 1)

We explained what went wrong and caused the MIL light to illuminate and what we were going to do to make it right.

Before we dive too deep into this misfire and crank sensor problem, a good suggestion would be to read up and understand the DTC description before moving forward. Since this looked like a simple problem that may be the result of a possible defective ignition part, the tech performed the usual diagnostic routine. Well, in this case it was a lesson that was going to be learned the hard way. Since many technicians would start testing the ig-




nition and fuel system as the first part of the diagnosis, they would not find the root cause of the problem on this Accord. The next logical step that the technician would most likely perform is checking the crank sensor and possibly replacing it without repairing the problem. Some of the first steps to perform are having a vehicle owner Q&A, visual inspection, system scan and a TSB check. In this case, there was a TSB for this Honda that describes the DTCs and lists the potential problems, such as a weak battery that can cause the P0339 DTC. Reminder: It's also a good idea to check service information and TSBs on every vehicle you work on. After all, you don't know what you don't know. My technician checked the crank sensor and (Con't on page 5)

"First-Time Mistakes" (con't from p. 4)

the circuit without finding any problems. After checking the vehicle for over an hour, my tech was still baffled on what the root cause of the misfire could be. He decided to ask me if I had any idea what was causing the problem since he could not pinpoint it.

I proceed to check all the basics from the battery, engine mechanical condition, ignition and fuel systems, as well as the CKP circuit, only to find the same results as my tech. My suggestion was to perform a Crank Relearn procedure (Figure 2) on this vehicle, since it's the procedure that Acura/ Honda recommends. I connected the MVCI along with the Honda factory software, showing and explaining the procedure to the technician so he could get a better understanding of the problem. Once the procedure was

complete, the vehicle was road tested, then returned to the owner without any DTC or MIL illuminated. We assured the vehicle owner that her engine was in very good condition and all the issues were addressed. We explained that there was re-



ally nothing wrong with the work we performed on the engine, but by accident we forgot to perform the relearn procedure. The vehicle owner left our shop with a smile and even called us about 10 days later to tell us that the Accord was running great.

Lesson No. 2

Our next mistake was on a 2003 Saab 9-3 that had a DTC P1681 Control Module Internal fault that one of my techs brought in the shop for his cousin. After my tech checked all the basics, he confirmed that the (Con't on page 6)

Page 6 Volume 21, Issue 9

"First-Time Mistakes" (con't from p. 5)

After my tech checked all the basics, he confirmed that the problem was in the ECU. This problem on the 9-3 had only one fix for the P1681 DTC and that was to replace the ECU and program it. Since we all know that Saabs are no longer made, my tech went the cheapest way and found a used ECU to install. With the new ECU installed, his next step was to program it with the correct information by updating the programming file. Without asking anyone else in the shop, he proceeded to program the car with a J2534 tool (Figure 3), rather than using our factory Saab tool.

It's wasn't his first time programming a vehicle, but there are some things that he just did not know about programming a Saab. After trying the program procedure two different times without success, you would think he would have asked one of us for some assistance. Not sure why he didn't ask, but he decided to wait for the weekend and contact one of my students. Jamie is a good technician that already took his lumps with a Saab and is knowledgeable and helpful, so he showed my tech the correct procedure. Jamie explained that the only way the vehicle could be programmed was with the factory Tech 2 Saab scan tool. When it comes to programming a Saab, you must go through the Tech 2 scan tool and not a J2534 device. Sometimes you just have to ask others for help and not be embarrassed to say you don't know everything. Once the procedure was properly performed on the 9-3, the vehicle ran great without any DTCs.

On to No. 3

A 2016 Acura RDX came in from one of the body shops we do work for because it was involved in an accident and had two codes stored: BD0090-87 DTC (No Signal from the Left Front Impact Sensor) (Figures 4, 5) and B18C7 (Blind Spot System) error. Since this is a new vehicle, the only way we were going to diagnosis it was by connecting our Honda factory scan tool. With the scan tool connected, DTCs were visible, along with helpful information on what to check and test right in the scan tool. (Con't on page 13)



Run-Rite® GDI Fuel System Cleaner Run-Rite® GDI Oil System Treatment

Run-Rite® D.I.D.C. (Direct Injection Deposit Cleaner)

Removes Valve Deposits

Reduces Combustion Chamber Deposits

Designed for GDI & PFI Fuel Systems

Safe for Turbos & Inter-coolers

Improves Fuel Economy

Keep Precision Oil Passages Clean



Reduces Deposits and Soot Buildup Promotes a more complete drain of oil

Helps Neutralize Combustion Acids

> Improve Oil Changes



Run-Rite #1077 G.D.I. 3 Step Fuel System Cleaning Kit: 8 kits per case (3 parts in each)

1.800.872.8921



Kleen-Rite #3110 Ultimate ECD (Engine Cleaning Detergent) 4 bottles per case (1 gallon each)

www.Run-Rite.com

Page 8 Volume 21, Issue 9

"THE SOURCE" FOR DIAGNOSTIC TEST PREP

Motor Age Training offers the most complete and extensive ASE Training Series available anywhere


- Study guides
- Practice tests
- Detailed illustrations
- Available in your favorite format



YOU PASS OR YOU DON'T PAY!







www.passthease.com



X-431 Throttle III

X-431 Throttle III is Wi-Fi enabled and super advanced scan tool with upgraded all-in-one Smartlink VCI. One is Enough for most repair shops who has business in relation with ADAS calibration, Truck diagnosis, Remote diagnostic, OE-level vehicle diagnosis, IMMO fuctions and more.

Page 10 Volume 21, Issue 9



Folks love us for our Heavy Duty Truck & Off-highway Coverage. WE'RE ABOUT TO CHANGE THAT.

www.candointl.com | 1-909-CanDo-11 (226-3611)

The CanDo **C-Pro** is a fully loaded, full functionality scan tool complete with bi-directional controls, special test functions and a full suite of activations and service resets.

Packaged in an 8" Android tablet that is Bluetooth wireless to the car, Wi-Fi to the internet, intuitive to use and easy to update – the **C-Pro** also includes our ASE Remote Technician function at no extra charge!

EUROPEAN, ASIAN & DOMESTIC PASSENGER CARS & LIGHT TRUCKS FULLY COVERED.



INTERNATIONAL, INC.







THE LEADER IN FLUID MAINTENANCE EQUIPMENT

TRANSMISSION POWER STEERING COOLANT BRAKE AND MORE

www.flodynamics.com

Auto Leap'

#1 Ranked Auto Repair Software





Capterra Software Advice. SetApp 💪 Google









Move Save Time | Make More Money



Scan this QR code to get in touch with your AutoLeap rep and learn more!

Get in touch with us to see how AutoLeap can transform your auto repair shop:

Sales@autoleap.com

"First-Time Mistakes" (con't from p. 12)

As you can see (Figure 5), the BSI (Blind Spot System) indicator problem could be everything from an open in a wire or connector to a bad connection. We decided to tackle this problem first since it looked the easiest out of the two DTCs. We performed all the suggested checks and did not find a problem, so we performed a drag test on the BSI indicator connection along with applying Stabilant 22, then retested the circuit. The good news was that this problem was now repaired, but now we had to move on to the tougher of the two problems.

With our attention now directed to the BD0090-87 DTC, we first tried to clear the DTC again only to find it would not erase. This result meant that we had a hard code that was caused by either an open circuit, a defective impact sensor or defective SRS computer as per Acura/Honda factory information. The body shop stated that they had replaced the impact sensor and the SRS computer with new Acura parts. After performing all the system checks, wiring and connector checks, we did not find any issues that would cause this hard DTC. I called the body shop and inquired about the impact sensor, asking if they knew where the old part was. The body shop informed me that the impact sensor was replaced with an updated part number and that they were sure it was installed correctly. I stopped him to ask if he was sure that there was an updated sensor for this vehicle. He replied that his information system that he uses for collision work provided him with that information. I suggested he locate the original part and please drop it off so I could check it out. The body shop located the old left front impact sensor and dropped it off.

While examining the impact sensor we noticed that the part looked the same but the numbers did not match (Figure 6). For the hell of it, and since we could not find anything else wrong in the circuit, we thought we would plug in the old sensor to see if we could clear the DTC and prevent it from returning. Bingo - the old sensor cleared up the DTC, along with removing the message from the dash display.


Page 14 Volume 21, Issue 9

"First-Time Mistakes" (con't from p. 5)

Our conclusion was that the old sensor was good and the new one was either bad or it was the wrong part.

The Acura was not finished just yet. Due to body repair regulations, once a vehicle is involved in an accident, the sensors and computers for the SRS system are required to be replaced. It would now be up to the body shop to contact the dealer and get the correct Left Front





Impact Sensor for the vehicle before returning it to the owner. The lesson learned here is to never fully trust a part information system or parts person 100 percent, since the part was obviously wrong. With the new Left Front Impact Sensor installed, the vehicle was back to proper operation with no codes or warning messages displayed.

And The Lessons Continue

A 2008 Mercedes-Benz ML350 with 254,697 on the clock came in with a bunch of different problems from the common intake manifold to the tail lights staying on all the time. Our customer's issue with the rear tail lights staying illuminated even when the vehicle was turned off, along with the icon for the rear hatch being illuminated, killed the ML350 battery. The vehicle owner stated he noticed that the lights were not turning off, (Con't on page 13)

"First-Time Mistakes" (con't from p. 12)



Article By
"G" Jerry Truglia
TST Founder and President
ASE World Class Triple Master
Auto, Truck, School Bus L1, L3, F1, X1, C1, Technician

A Very Healthy Happy
Thanksgiving to you and your
family

Page 16 Volume 21, Issue 9



Working with ETE is a breeze. We make it easy to stay in touch and get the help you need when you call, text, or buy online with BuyETE.com. Your dedicated team of Customer Support Representatives and Technical Specialists are the most knowledgeable and helpful team in the industry

- and they're just a call or click away!

We also need your core, and you need it out of your way.

We take care of that too.

OF A REMA

All transmissions include a remanufactured and improved torque converter.

Torque converters are tested to eliminate the possibility of leaks, vibration, and wear.

Every independently-tested fully remaned valve body includes a complete system correction and recalibration kit.

All transmissions are hot, cold, load, and simulated road tested using our proprietary CARS dynamometer program.

All wear-prone valves are vacuum tested to confirm proper function.

3 YEARS/

UNLIMITED MILEAGE

Your customers are covered for 3 years/unlimited miles on standard and commercial applications.



PAID PARTS & LABOR

When installed at a certified shop, we pay parts and labor. Oh and if you included fluid on your original order, we'll cover that too.



NATIONWIDE COVERAGE

Your customers are covered anywhere (and everywhere) in the continental U.S.



TRANSFERABLE WARRANTY

Our Warranty is attached to the VIN and fully transferable with the vehicle ownership - no fees or registration paperwork required.



SCAN QR CODE FOR FULL WARRANTY

(800) 934-9479

Product quality backed by










SMART TOOLS OF THE TRADE









EASILY READ, MEASURE, AND INJECT PROPER OIL/DYE QUANTITY



REAL TIME VISUAL A /C SYSTEM DIAGNOSTICS




DUAL RECYCLE GUARD"

PROTECT YOUR A/C SERVICE EQUIPMENT FROM CONTAMINANTS







Page 20 Volume 21, Issue 9

ASSOCIATED

The Battery Chargers Professional Technicians TRUST









IBC6008MSK

- Safely charges ALL 12V EFB (Start-Stop), AGM, Lithium, Gel and SLA battery types
- Customize battery charging profiles with adjustable voltage and adjustable amperage by type
- Built-in reflash power supply and memory saver port with 12 ft. OBDII cord
- Patented Intellamatic® smart charger analyzer technology with battery rejuvenation
- · Partial Charge mode for busy shops
- · Energy efficient and OE manufacturer approved
- Legendary power and generational quality
- "Safe in any weather" operation





6006AGM/6009AGM/6012AGM

- Upgraded "tried and true" heavy duty chargers with setting for AGM batteries
- Improved energy efficiency
- · Legendary power and quality

AMERICAN MADE, FAMILY OWNED

5043 Farlin Ave. | St. Louis, MO 63115 | 800-949-1472 | www.associatedequip.com

#IWANTTHEBLUEONE

Search for Technical Training Nationwide!

INDUSTRY ATTENDS

A single place to find all of the events happening in our industry...

in one easy to use automotive training & events calendar

...and best of all - it's FREE!



INDUSTRYATTENDS.COM



Discover and Attend Automotive Industry Events

Grow your connections, business and expertise with Industry Attends.

Free Calendar

This 8	March March	2023 ~				
UN	MON	TUE	WED	THU	FRI	SAT
26	27	28	1	2	3	4
000 am - 500 am	000 pp - 000 pp (7)	6:00 pm - 7:30 pm	Vision 18-Tech Training	A Tomo		
DANY DLIS System Diagnostics With Justin Morgan	BANK Engines Part 1 & 2 (4 Ear) Every — Workspac	VCDS (nownellises) - SSF 6:00 pm - 5:00 pm (3) SMMI Engines Part 1 8:2 rd Day Duest) - Voyatjust	700 pm - 0.30 pm (5) Shop2Shop Morenly Networking	6.00 pm - 7:30 pm VCOS ((micro+data) - 508		
5	6	7	8	9	10	11
12	13	14 A SEN SITTS Charging - W	15 Super Conference 2023	18	17	18
			Devabiles Lest Practices			
			6:30 pm - 8:30 pm Nissans R134 & R1234/FAC System Diagnostics Viebinar - 966			800 pm - 800 pm TST Sig Event 20th Accordancy
15	20	21	22	23	74	25
			rity Elth Assessed (Detroit)			600 an - 500 pm S-1234y/AC LOOP TROUBLESHOOTIN & DHOMOSTIC TEO-INIQUES - Worldhar
		The state of the s	Control	0.00 pm-7:30 pm Chanair Diagnosis & Repair – 20F		
28	27	28	29	30	31	1.
800 Am - 500 pm R-120HyFAIC LOOP TROUBLESHOOTING & DINGMOSTIC TSCHNIGUES - Wellspac		6:00 pm - 7:20 pm VW Duel Chech Transmission - 2SF	Domestic Diesel Aftermeatment Systems		ATE (Automobile Training Days)	
				6:00 pm - 7:30 pm VW Dust Outch Transitionies - SQF		

Page 22 Volume 21, Issue 9

